

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : GY8633G

Accident Date : 10/8/2021

Location : CTE (CITY) BEFORE BRADDELL ROAD EXIT

Model: TOYOTA DYNA
(6/9/2005)

3P: YP2919G(CHINA TAIPING)

JT7UF34Y103011029

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear tail-gate Distorted	1248	1584.57	
2	1 pc	Rear tail-gate '70 km/h' sticker		20.00	10
3	1 pc	Rear tail-gate '13 pax' sticker		20.00	10
4	2 pcs	Rear tail-gate o/s & n/s lock Bent	80.00		
5	1 pc	Rear tail-gate o/s & n/s lock handle Bent	97.80		
6	4 pcs	Rear tail-gate hinges Bent	60.00		
7	4 pcs	Rear tail-gate hinges pins Bent	20.00		
8	1 pc	Rear tail-gate lower panel Dented	455.20		
9	2 pcs	Rear tail-gate o/s & n/s rubber stopper L/H int	40.00	20	
10	2 pcs	Rear tail-gate o/s & n/s rubber stopper bracket L/H Bent	150.00	75	
11	2 pcs	Rear o/s & n/s tail-lamp panel L/H Bent	320.00	160	
12	2 pcs	Rear o/s & n/s tail-lamp Cracked	540.00		
13	1 pc	Rear cabin panel Repair	Repair	X	
14	1 pc	Rear floor aluminium Dented		800.00	300(SN)
15	30 pcs	Rivets		30.00	
16	1 pc	Rear reg. no. plate bracket Bent	120.00		
17	1 pc	Rear regn no. plate Bent		35.00	25
18	1 pc	Rear spare wheel bracket Missing	398.80		
19	1 pc	Rear spare tyre rim (big)	600.00	180	
20	1 pc	Rear spare tyre rim (small)	500.00	120	
21	1 pc	Rear spare tyre tyre (big)		150.00	120
22	1 pc	Rear spare tyre tyre (small)		160.00	120
23	1 pc	Front bumper Distorted	720.00	564	
24	1 pc	Front bumper bracket Bent	320.60		
25	1 pc	Front panel (Upper) Dented	565.2		
26	1 pc	Front panel (Lower) Distorted	1,350.00	1069	
27	1 pc	Front panel "DYNA" emblem	125.60		
28	1 pc	Front panel black ganrish (middle) Cut	220.00		
29	1 pc	Front panel black ganrish o/s & n/s RH int	176.40	88.20	
30	1 pc	Front grille Cracked	540.00		
31	12 pcs	Front grille clips		48.00	30
32	1 pc	Front grille moulding	150.00	X	
33	1 pc	Front grille "TOYOTA" emblem	126.50	53	
34	2 pcs	Front o/s & n/s head-lamp Cracked	1,440.40		
35	2 pcs	Front o/s & n/s head-lamp clips		12.00	
36	1 pc	Front regn no. plate Dented		35.00	25
37	1 pc	Front Air con pipe	130.00	X	

38	1 pc	Blower <i>could</i>	1,718.20	<i>2</i>	1037
39	1 pc	Cooling coil <i>could</i>	2,110.20	<i>2</i>	985
40	1 pc	Wiper tank <i>Not in</i>	461.50	<i>x</i>	
41	2 pcs	Gear selector cable <i>cut</i>	1250.80	<i>485</i>	
42	1 pc	Front o/s windscreen nozzle <i>could</i>	210.00	<i>68</i>	
43	1 pc	Front o/s door company sticker <i>in</i>		8.00	<i>✓</i>
44	1 pc	Front n/s cabin mounting <i>see in</i>	320.00	<i>x</i>	
			Sub-Total:	16,911.77	1,318.00 0.00
				25%	0% 0%
			After Less %:	12,683.83	1,318.00 0.00
Labour					
1		To dismantle, straighten, cutting & welding front and rear portion and re align front n/s door pillar	1,800.00	<i>1600</i>	
2		To spray painting.	1,600.00	<i>1300</i>	
3		To remove rear cannopy	100.00	<i>80</i>	
4		To remove and replace rear floor aluminium	140.00	<i>60</i>	
5		To remove and refit rear carriage to facilitate repair of rear cabin	800.00	<i>x</i>	
6		To remove and replace air-cond system vacuum and refill gas.	150.00	<i>✓</i>	
7		To remove and refit front dash board to facilitate removal of air con blower & cooling coil	300.00	<i>220</i>	
8		To remove and replace gear selector cable	200.00	<i>80</i>	
9		To remove and refit n/s front cabin mountng	200.00	<i>x</i>	
10		To check wiring.	80.00	<i>60</i>	
11		To re-seal anti-rust.	80.00	<i>✓</i>	
			Sub-Total:	5,450.00	
			Total:	19,451.83	
			After Less 20%:	15,561.46	

1135.80
8351.85
SIN: 660

3630

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

Adrian Lj
H/S 11/08/21
12 Days.



AL 8778 1999
24 hr accident call

Mobil 1



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Supplementary: 257.50.

total: 12899.35

H/S: 10.3K ✓

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : GY8633G Model: TOYOTA DYNA
 Accident Date : 10/8/2021 (6/9/2005)
 Location : CTE (CITY)BEFORE BRADDELL ROAD EXIT 3P: YP2919G(CHINA TAIPING)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	2pcs	Front o/s & n/s door sticker <i>New</i>		300.00	
2	1 pc	Front n/s corner panel <i>re-hd</i>	210.00		
		Sub-Total:	210.00	300.00	0.00
			25%	0%	0%
		After Less %:	157.50	300.00	0.00
		Total:		457.50	
		After Less 20%:		366.00	

Chan

Chan San Choon

Director

DipEng, AAE MIMI,MSAE(Aust)

210
157.50

S.N:100 Adnan Li
12/08/21

HL



8778 1999
24 hr accident call



Supplementary: 257.50