LAWRENCE LEE & CO

Advocates & Solicitors

李伟平律师楼 UEN: 53159236K

Your ref:

(please advise)

Our ref:

LWP/QAS/4631/21/wt

5 July 2021

This is a letter of claim issued pursuant to the Non-Injury Motor Accident Practice

133 New Bridge Road #13-10

tel: 6533 3680 fax: 6533 3689

email: info@lawrencelee.com.sg

Chinatown Point Singapore 059413

CERTIFICATE OF POSTING

\$ 7,372,30 (\$6,890 plus GST)

Direction of the State Courts

Comfort Transportation Pte Ltd 383 Sin Ming Drive GAS Building Singapore 575717

Dear Sirs

ACCIDENT ALONG JLN TUA KONG ON 10.02.21 INVOLVING GBK3538P & SHC3265Y

We act for UKA Leasing Pte Ltd, owner of the above vehicle GBK3538P.

We are instructed to claim against you in connection with the above accident involving our client's vehicle and vehicle SHC3265Y owned by you and driven by your servant/agent one Sim Ling Zhou at the material time.

We are instructed that the accident was caused by your servant/agent's negligent driving, management and/or control of your vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

Particulars

Cost of repairs

1.	Cost of repairs	L.	1,0112.00	(40,000 pius GDI)
2.	Loss of use (6 days x \$120 pd)	S	720.00	
Di	sbursements			
3.	Survey fee	\$	570.00	
4.	LTA fee	S	7.49	
5.	Legal costs	\$	700.00	
6	Miscellaneous	S	100.00	

A copy of each of the following documents is enclosed:

- 1. LTA search with receipt;
- 2. Our client's LTA online enquiry;
- 3. Our client's GIA report;
- 4. Pro-Forma Invoice No. E210203 from QAS Auto Pte Ltd;

- 5. Invoice No. INV0089 from Dreamzgarage Pte Ltd; and
- 6. Original Survey Report Ref 87/TP/2021 with 30 color photographs and Invoice No. 010621-87 from Sincere Appraisal Services Pte Ltd.

Please note that:

- a. If you are insured and you wish to claim under your insurance policy, you should immediately pass this letter to your insurer.
- b. You or your insurer should send us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.
- c. If you have any witnesses or photographs of the accident scene, please send to us the witnesses' names/addresses/contact nos. or the photographs within 14 days of your receipt of this letter.
- d. If you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

In the event that your vehicle had been driven by someone not in the capacity as your servant/agent, please inform us in writing within 14 days otherwise we will name you as a defendant in the Writ that may be issued and you may be liable for legal costs.

Yours faithfully

LEE WEE PENG LAWRENCE Paralegal: Ms Tay Wan Ting

Email: wanting@lawrencelee.com.sg

Encs by email only

Cc AXA Insurance Pte Ltd (Insurer of SHC3265Y) 8 Shenton Way #24-01 AXA Tower Singapore 068811

POST/EMAIL

Cc Client

Enquire Vehicle Owner Details

Enquire Vehicle Owner Details (As At 10 Feb 2021 / 16:00:00)

/e	hicle Owner Details	
	Owner ID Type:	
	Company	
	Owner ID:	
	199303821R	
	Owner Name:	
	COMFORT TRANSPORTATION PTE LTD	
	Registered Address Type:	
	Private Residential (Condo Apt or House) / Shopping / Office Complexes	
	Registered Block/House No.:	
	383	
	Registered Street Name:	
	SIN MING DRIVE	
	Registered Unit No.:	
	-	
	Registered Building Name:	
	GAS BUILDING	
	Registered Postal Code:	
	575717	

Vehicle No.:

Vehicle Insurance Details

SHC3265Y

Make Description/Model:

TOYOTA / PRIUS 5DR HATCHBACK (AUTO)

Insurance Company Name:

AXA INSURANCE PTE LTD

Save as PDF

ОК 🖈

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	T.,
Owner ID Type:	Company
Owner ID: Vehicle Details	072Z
Vehicle No.:	GBK3538P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Feb 2021
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1KDB030387
Chassis No.:	JTFHT02PX00250387
Maximum Power Output:	-
Open Market Value:	\$28,138.00
Original Registration Date:	01 Jun 2020
First Registration Date:	01 Jun 2020
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	NI_
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$ 0.00
COE Expiry Date:	31 May 2030
COT Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$20,478.00
COE Rebate Amount:	\$16,382.00
Total Rebate Amount:	\$16,382.00

The information contained herein is correct as at 18 Feb 2021

SM0G212H0004 / MODERN AUTOMOTIVE PTE LTD ENTRY DATE & TIME: 17/02/2021 16:21 (SGT) SUBMITTED BY: CHIN SOI SHONG GRACE VERSION: 1 (17/02/2021 16:21 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 17/02/2021 16:21 (SGT) Date of Accident 10/02/2021 16:00 (SGT) Exact Location of Accident Jln Tua Kong, Singapore Additional Location Information OUTSIDE CRESCENDO PARK Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

(Phone) +65-67429983

Vehicle Registration Number **GBK3538P** INSURED/POLICYHOLDER Is company? Yes Name Of Registered Owner UKA LEASING PTE LTD Company Reg No 2XXXXXX072Z Email Address QASAUTO2011@GMAIL.COM Mobile Phone No

Alternative Phone No +65-81334261

VEHICLE PARTICULARS

Manufacturer Toyota Model Hiace Variant

Exact purpose for which vehicle was being used at time of accident Employment

Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company NTUC Type of Coverage Comprehensive Fleet Policy Yes Policy Number 5111756127 Cover Note Number

DRIVER

Name of Driver ZAINAL BIN JAMIL NRIC No SXXXX5831 Date Of Birth 13/10/1995 Occupation Outdoor

Date Of Driving Pass Driving experience

Gender

Mobile Number Alt. Phone Number

Email Address

Address

Address complement

Postcode Is the driver the policyholder?

If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) 1

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

DETAILS OF POLICE ACTION

Was the accident reported to the police? Νo Was notice of intended Prosecution given? Nο If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

I STOPPED AT A DISTANCE BEFORE THE ENTRANCE OF THE CONDO AND SIGNAL LEFT TO TURN INTO THE CONDO. TAXI (SHC3265Y) REVERSED WITHOUT CHECKING HIS BLIND SPOT AND REVERSED INTO MY VEHICLE FRONT RIGHT PORTION.

30/06/2014

Male

549298

No

No

Hirer

Clear

Dry

No

6 YEARS AND 8 MONTHS

BOYZAC.ZAINAL@GMAIL.COM

BLK 298C COMPASSVALE STREET #01-88

(Phone) +65-81334261

Collision - Major/Minor Rd

ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer Vehicle Model Vehicle Variant

Vehicle Category Name of Driver

Vehicle Colour


Contact Number Address

Address complement Postcode

Taxi

SHC3265Y

SIM LING ZHOU (Phone) +65-97478776



Insurance Company Name	-
Nature Of Damage	
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

SKETCH PLAN

IMPORTANT NOTICE

- 1. Physic report concertly the delibered the continuent to the effect of the position of the continuent of the continuen
- 2. The form most be completed by the Falacyholder and/or the Authorised Draws
- 3 Information provided must be extendible and accurate as possible due within more pour relation or within integral motors.
 Facts may allow measures companies to requidible policy liability.
- 4. The usua and acceptance of this term by measures companies is not an oriential of public hubility on the good of the interance companies.
- 5 Any take reporting may be referred to the Folice for investigation.
- The report will be forwarded by the insurers of the GIA becords Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgment of this report to the insurers, you licreby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 3. Consent under the Personal Data Protection Act (PDPA)

Funderstand, acknowledge, agree and consent that:

- (a) My insuter, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers lawyers/haw firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the meiting of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time Oriver's Signature (If driver is not the policyholder)

Date & Time.

17/2/2021

Reporting Centre Personnel's Signature

NRIC/FIN No.:

SKITCHPHAN Jalan Tua K		cresceudo Park)
**************************************	99/9/2014-00	A: G8K 3538 P
<u> </u>		B= SHC 3265Y
DESCRIBE CIRCUMSTANCES OF I stopped 9+ a Condo and Taxi (5Hc 32 blindspot and Portion.	THE ACCIDENT I distance before to signal left to true 65 Y) reversed withon Yeversed into my	ne entrance of the mistory with the condo. If Checking his vehicle front rynot
DECLARATION If We declare the foregoing carticulars Policyholder's Signature Date & Time:	Driver's Signature (if driver is not the policy/folder)	Reporting Centre Personnel's Signature Name.
	Oale & Time 17/2/2021	MAIC/FIN NO :



















QAS Auto Pte Ltd 3018A Ubi Road 1 #01-23 Singapore 408711 +65 67429983 qasauto2011@gmail.com

GST Registration No.: 201027141K

ADDRESS
UKA Leasing Pte Ltd
3018A Ubi Road 1 #01-23
Singapore 408711

PROFORMA E210203 INVOICE NO. DATE 01/06/2021

VEHIO GBK3	CLE NO. 538P	MAKE & MODEL Toyota Hiace			
NO	DESCRIPTION		OTY	GST	TNUOMA
1	Lump sum repair		1	7% SR	5,000.00
2	Replacement of Coplus Black base Headlamp		1	7% SR	1,890.00
	(Accident on 10/02/2021 / SHC3265Y Along Jln Tua Kong)			on	
		CUDTOTAL			
		SUBTOTAL GST TOTAL			6,890.00 482.30
		TOTAL		S\$7,	372.30



DREAMZGARAGE PTE LTD

50 SERANGOON NTH AVE 4,#04-17 SINGAPORE 555856 +6590236999 dickson_loh@yahoo.com.sg INVOICE INVOO89

DATE 06/06/2021

DUE On Receipt

BALANCE DUE

SGD S\$822.30

BILL TO

OTHER

PAYNOW: 202006710C

GBK 3538P

DESCRIPTION		RATE	QTY	AMOUNT
Coplus black base headlamp		S\$1,890.00	1	S\$1,890.00
	SUBTOTAL			S\$1,890.00
	GST (7%)			S\$132.30
Payment Instructions	TOTAL	— <u></u>		S\$2,022.30
PAYPAL dickson_loh@yahoo.com.sg	PAID			-\$\$1,200.00 06-06/2021
BY CHECK DREAMZGARAGE PTE LTD	BALANCE DUE		SGD	\$\$822.30



SINCERE APPRAISAL SERVICES PTE LTD Co.Reg no: 201800639R

420 North Bridge Road, #02-05 North Bridge Centre, Singapore 188727

Tel: 6636 4628 E-mail: office@sincereappraisal.com.sg

INVOICE

Uka Leasing Pte Ltd C/O QAS Auto Pte Ltd Blk 3018A Ubi Road 1 #01-23 Singapore 408711

Invoice No:

010621-87

Our ref:

87/TP/2021

Date:

1/6/2021

Claim Type: Third Party

Vehicle Reg No: GBK3538P

Vehicle Make/Model: Toyota Hiace

Date of Loss: 10/2/2021

Claimant:

Uka Leasing Pte Ltd

Description

Amount (S\$)

1. Professional Fee

(including Transport, 30 Photographs and

Miscellaneous charges)

570

Total

570

Singapore Dollar: Five hundred and seventy dollars only.

Cheques should be crossed A/C PAYEE and made payable to Sincere Appraisal Services Pte Ltd





VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 87/TP/2021 Date: 1/6/2021

REFERENCE

Date of loss: 10/2/2021

Claimant: Uka Leasing Pte Ltd

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBK3538P Make & Toyota Reg date: 1/6/2020 Model Hiace

Colour: White Engine No: 1KDB030387

Type: Van Chassis No: JTFHT02PX00250387

Type of Claims: Third Party Odometer No: 35959km

Engine Cap: 2982cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

(STATIC ONLY)

General Condition: Good Steering: Good Engine Modification: Nil

Paint work: Good Handbrake: Good Pre-accident

Footbrake: Good Damage: Nil

CONDITION OF TYRES

Front Left Size: Radial 225/40ZR18 70% Front Right Size: Radial 225/40ZR18 70% Rear Left Size: Radial 225/40ZR18 70% Rear Right Size: Radial 225/40ZR18 70%

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS Repairer S\$ Adjuster S\$

Parts \$ 5,182.25 \$ 4,912.25 Labour \$ 1,590.00 \$ 1,350.00

Calculated Cost (S\$): \$ 6,772.25 \$ 6,262.25

Recommended Lump Sum Repair Cost (S\$): \$ 5,000.00

Date of Assignment: 10/3/2021 Inspected At: QAS Auto Pte Ltd

Date Inspected: 10/3/2021 Blk 3018A


Est. repair Period: 06 days Ubi Road 1 #01-23

Singapore 408711

SINCERE APPRAISAL SERVICES PTE LTD Co.Reg no: 201800639R

POINT OF IMPACT

Damaged at the right hand front portion.



BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle along Jalan Tua Kong.

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the right hand front portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$6,772.25. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$5,000.00.

We have not authorised the repair. Under normal circumstances, estimated **06** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

ANNEX A

REPAIR DETAILS

Recommended Parts

				R	epairer's	A	djuster's
No	Qty	Description	Condition		Amount		Amount
1	1	Front bumper assy	cracked/dented	\$	1,418.00	\$	1,418.00 1200
2	1	Front bumper right retainer	bent/necessary	\$	122.00	S	122.00 60
3	1	Front bumper right bracket	bent/necessary	\$	122.00	\$	122.00 60
4	1	Front right LED headlamp	cracked/cut	\$	2,800.00	\$	2,800.00 2200
5	1	Front grille assy	bent/warped	\$	381.00	\$	381.00
			3900	\$	4,843.00	\$	4,843.00
		Less 25%	2925	\$	1,210.75	\$	1,210.75
				\$	3,632.25	\$	3,632.25
		Special Nett Items					
1	10	Front bumper clips	necessary	\$	60.00	\$	50.00 30
2	1	Front no plate	necessary	\$	100.00	\$	80.00 Xnn
3	4	Front grille clips	necessary	\$	30.00	\$	20.00
4	1	Front bumper lower spoiler	cracked/grazed	\$	1,200.00	\$	1,000.00 600
5	1	Front bumper lower spoiler sealant	necessary	\$	120.00	\$	100.00 40
6	6	Front bumper lower spoiler clips	necessary	\$	40.00	\$	30.00
				\$	1,550.00	\$	1,280.00 720
		Total parts		\$	5,182.25	\$	4,912.25

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	epairer's Amount	djuster's Amount
1	Labour for panel beating, cut, weld, straighten front and front	\$ 700.00	\$ 600.00 400
	right affected area and replace front and front right damaged		
	parts.		
2	To putty and spray painting front and front right portion.	\$ 700.00	\$ 600.00 400
3	To check wiring and focus front headlamp.	\$ 50.00	\$ 30.00
4	To apply anti rust proofing to front and front right affected area.	\$ 140.00	\$ 120.00 Xnn
	Total labour :	\$ 1,590.00	\$ 1,350.00
	•		830

ANNEX C

REPAIR DETAILS

RDITTER PET TIES.	42/23			
Adjusted Repair Cost				
	,			J
		epairer's		
		Amount	1	Amount
Total parts :	2	5 182 25	T.	4 912 25
Total parts.	ъ.	29102.23	Ψ	79712.23
Total labour:	\$	1,590.00	\$	1,350.00
Total repair cost :	\$	6,772.25	\$	6,262.25
		•		-

Adjusted Repair Cost (Lump Sum Repair)	Adjusted Repair Cost (Lump Sum Repair)	\$ 5,000.00
--	--	-------------

4475 I/s\$3600 5 days













