



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

IMMEDIATE ADVICE

To : AXA Insurance Pte Ltd

DATE: 25/3/21

Survey details

Date of loss	10/2/2021
Date of appointment	18/2/2021
Date of survey	10/3/2021
Location of survey	QAS AUTO PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	GBK 3538P
Make and Model	TOYOTA HIACE VAN TURBO 5DR MT
Date of registration	1/6/2020
Excess	
Market Value	\$75,000.00
Part Rebate	\$18,804.00
Nett Loss	\$56,196.00

Repair details

Initial Estimate	
------------------	--

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	
Number of days of repair	3 days (est)

Remarks:

The estimated repair cost of the damaged vehicle is in the region of \$1,500.00-\$2,500.00