

LESS 20% 25%				\$10,337.33
DISCOUNTED TOTAL				\$41,349.32
FRONT DOOR COMFORT LOGO H/c	SN	1	\$ 105.00	\$105.00
FRONT NO. PLATE H/c	SN	1	\$ 35.00	\$35.00
FRONT NO. PLATE TRIM COVER H/c	SN	1	\$ 42.00	\$42.00
FRONT TYRE (RH) H/c	SN	1	\$ 302.40	\$302.40
SUB TOTAL				\$484.40
Labour Charge				
Panel Beating		1	\$ 2,000.00	\$2,000.00
Spray Painting Charge		1	\$ 1,600.00	\$1,600.00
Wiring Charge		1	\$ 100.00	\$100.00
Tuff Kote		1	\$ 100.00	\$100.00
Towing Charge		1	\$ 80.00	\$80.00
Transfer of Door Mechanism FRONT		1	\$ 80.00	\$80.00
Re-set Frt Power Window System		1	\$ 200.00	\$200.00
Four Wheel Alignment		1	\$ 120.00	\$120.00
Remove/Refix Undercarriage (Frt)		1	\$ 400.00	\$400.00
Re-set Frt ABS System		1	\$ 200.00	\$200.00
Remove/Refix Radiator		1	\$ 90.00	\$90.00
Remove/Refix Aircon & Refill Gas		1	\$ 130.00	\$130.00
Remove/Refix Fuse Box		1	\$ 120.00	\$120.00
Remove/Refix Front Windscreen Glass		1	\$ 120.00	\$120.00
Remove/Refix Engine		1	\$ 600.00	\$600.00
Remove/Refix Dashboard		1	\$ 350.00	\$350.00
Diagnostic & Resetting To Erase Fault Code		1	\$ 550.00	\$550.00
TOTAL LABOUR				\$6,840.00
ESTIMATE TOTAL				\$48,673.72
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

15804.23

11853.17

✓ \$100. =

} 45/-

X 145.00 =

1000/-

1000/- 200/-

30/-

40/-

H/c

H/c

H/c

H/c

H/c

H/c

H/c

50/-

80/-

H/c

H/c

H/c

H/c

150/-

2150.00 =

10/08/2021 @ 1700hrs

H/c Actual

H/c 11 days.

Part by Part.

14148.17

Supp 4789.62

P/P 18,937.79

You

LKK Auto

Pmde Bv

Check Photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: