

Our Ref : TP/082021/4933

Invoice No:

Accident date: 7/8/2021

Your Ref : SML9008C

Date:

10/8/2021

Motor Claim Department

Lonpac Insurance Bhd.

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SMX9138Y

Make/Model : Honda Vezel

1	pc	Front bonnet / BT	\$	892.60
1	pc	Front bonnet LH hinge X Repair	\$	42.50
1	pc	Front bonnet RH hinge / BT	\$	42.50
1	pc	Front bonnet rubber - centre X NN	\$	23.80
1	pc	Front RH headlamp / L BR	\$	1,715.10
1	pc	Front LH headlamp / L BR	\$	1,715.10
1	pc	Front RH headlamp lower bracket = L BR	\$	48.50
1	pc	Front LH headlamp lower bracket = L BR	\$	48.50
1	pc	Front grille / CRA	\$	380.20
1	pc	Front grille outer chrome / CRA	\$	312.80
1	pc	Front grille emblem / MC	\$	28.30
1	pc	Front grille RH side support bracket / BR	\$	17.60
1	pc	Front grille LH side support bracket X NN	\$	17.60
1	pc	Front bumper / CRA	\$	801.70
1	pc	Front bumper centre lower grille X NN	\$	115.60
1	pc	Front bumper RH side retainer / BR	\$	20.60
1	pc	Front bumper LH side retainer X NN	\$	20.60
1	pc	Front bumper reinforcement / BT	\$	360.80
1	pc	Front bumper under cover X NN	\$	96.80
10	pcs	Front bumper clips @ \$4.20 / MC	\$	42.00
1	pc	Front RH fender X Repair	\$	421.10
			\$	7,164.30
Less 20%			\$	(1,432.86)
			\$	5,731.44

1	pc	Front no. plate / BT	\$	40.00	N
---	----	----------------------	----	-------	---

Our Ref : TP/082021/4933

Invoice No:

Accident date: 7/8/2021

Your Ref : SML9008C

Date:

10/8/2021

To diagnose electrical components
To repair damages
To spray painting

\$ 250.00

\$ 780.00

\$ 980.00


\$ 7,781.44

30

680

800

VIN'S MOTOR PTE LTD



5 Days
P/P
before paint photos.
Gino Giar
11/8/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: