

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

10-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6894 L

1 pc	Boot lid	\$	1,119.00	bb
1 pc	Boot lid lock	\$	99.00	Rm
1 pc	Bootlid striker	\$	21.00	Bo
1 pc	Bootlid emblem	\$	27.00	ng
1 pc	Bootlid CRDi	\$	29.00	ng
1 pc	Boot lid rubber weatherstrip	\$	96.00	Xun
1 pc	Boot lid lower garnish	\$	290.00	Ry
2 pcs	Bootlid hinges @ \$66.00	\$	132.00	Xun
1 pc	Bootlid inner trim	\$	190.00	Xun
2 pcs	Rear license lamp @ \$30.00	\$	60.00	Xun
1 pc	End panel	\$	250.00	Ry
1 pc	End panel inner garnish	\$	74.00	Xun
2 pcs	n/s & o/s tail lamp @ \$421.00	\$	842.00	ua
2 pcs	n/s & o/s reflector @ \$350.00	\$	700.00	u/s Xun
1 pc	Rear bumper	\$	696.00	de
1 pc	Rear bumper lower cover	\$	206.00	de
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	re
1 pc	Rear bumper inner sponge	\$	114.00	Ry
1 pc	Rear bumper reinforcement	\$	607.00	Xun
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00	bt
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	X
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	X
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00	X
		\$	5,882.00	3549
Less 10%		\$	588.20	394.10
		\$	5,293.80	

S/NETT

1 set	Rear bumper clips	\$	48.00	30
1 set	End panel inner garnish clips	\$	30.00	20 Xun
1 set	Bootlid inner trim clips	\$	52.00	Xun
1 set	Bootlid lower garnish clips	\$	60.00	Xun
1 set	Bootlid stickers	\$	100.00	80
1 set	Reverse sensor	\$	280.00	200
				310

10-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6894 L

Sundry

\$ 50.00 X 47

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ 120.00 30

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ 180.00 60

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the same etc

\$ 950.00 500

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel

\$ 800.00 600

To apply rustproofing on the repaired and replaced panels.

\$ 200.00 30

\$ 8,163.80 1220

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

3194.10

310

1220

4724.10

153750

04 days.

Tafim 97495749
'WP' 11/8/21 4pm
1/3 Resurvey after repair
Tafim 11/8/21 4pm
3-4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: