

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

10-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6894 L

1 pc	Boot lid	\$	1,119.00 <i>bb</i>
1 pc	Boot lid lock	\$	99.00 <i>?</i>
1 pc	Bootlid striker	\$	21.00 <i>Re</i>
1 pc	Bootlid emblem	\$	27.00 <i>ng</i>
1 pc	Bootlid CRDi	\$	29.00 <i>ng</i>
1 pc	Boot lid rubber weatherstrip	\$	96.00 <i>?</i>
1 pc	Boot lid lower garnish	\$	290.00 <i>Ry</i>
2 pcs	Bootlid hinges @ \$66.00	\$	132.00 <i>?</i>
1 pc	Bootlid inner trim	\$	190.00 <i>X</i>
2 pcs	Rear license lamp @ \$30.00	\$	60.00 <i>X</i>
1 pc	End panel	\$	250.00 <i>Ry</i>
1 pc	End panel inner garnish	\$	74.00 <i>?</i>
2 pcs	n/s & o/s tail lamp @ \$421.00	<i>n/s cut</i> \$	842.00 <i>o/s?</i>
2 pcs	n/s & o/s reflector @ \$350.00	\$	700.00 <i>ng</i>
1 pc	Rear bumper	\$	696.00 <i>de</i>
1 pc	Rear bumper lower cover	\$	206.00 <i>de</i>
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00 <i>ne</i>
1 pc	Rear bumper inner sponge	\$	114.00 <i>?</i>
1 pc	Rear bumper reinforcement	\$	607.00 <i>?</i>
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00 <i>?</i>
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00 <i>?</i>
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00 <i>?</i>
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00 <i>X</i>
		\$	5,882.00
		Less 10%	\$ 588.20
		\$	5,293.80

S/NETT

1 set	Rear bumper clips	\$	48.00 <i>30</i>
1 set	End panel inner garnish clips	\$	30.00 <i>20?</i>
1 set	Bootlid inner trim clips	\$	52.00 <i>X</i>
1 set	Bootlid lower garnish clips	\$	60.00 <i>X</i>
1 set	Bootlid stickers	\$	100.00 <i>80m</i>
1 set	Reverse sensor	\$	280.00 <i>200m</i>

10-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6894 L

Sundry	\$ 50.00	X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00	30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00	60
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the same etc	\$ 950.00	500
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel	\$ 800.00	600
To apply rustproofing on the repaired and replaced panels.	\$ 200.00	30
	<u>\$ 8,163.80</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tafhin 97495744
WP' 11/8/21 4pm
1/5 Resurvey after repair
Tafhin (Hampden)
3-4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: