

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0647/2021/ZK
DATE : 11-Aug-21
WIP : 39293

Jasper.

\$6282.48.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 13/8/2021

YOUR INSURED VEH NO : SMV 8037 Y

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR KOK PENG SENG
ADDRESS : BLK 341 CHO A CHU KANG LOOP
#10-19
SINGAPORE 680341
TELEPHONE : HP +65 9792 1219
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100470446-05
VEHICLE NO : **SLD 3211 A**
MODEL CODE : AUDI Q5 2.0 TFSI
MODEL YEAR : 13/6/2016
ENGINE NO : CNC 165528
CHASSIS NO : WAUZZZ8R1CA123912
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Aug-21
PLACE OF ACCIDENT : ALONG TEBING LANE (TOWARDS CONEY ISLAND)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLD 3211 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING LTD	S/N \$	480.00 ✓	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$	400.00 X	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00 500 ✓	✓
4	TO RESPRAY FRONT BUMPER AND FRONT BUMPER LOWER SPOILER 550 300	\$	2,000.00 850 ✓	✓
5	TO RE-APPLY PAINT COATING ON AFFECTED AREA. (BY OWNER)		TBC X	
6	TO CARRY OUT DIAGNOSTIC CHECK	\$	192.00 ✓	✓
SUB-TOTAL LABOUR CHARGES		:	\$ 4,272.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 3211 A

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>dehnd</i>	1	\$ 2,724.00 ✓		2,179.20
2	FRONT BUMPER FIXING PARTS <i>neu</i>	1	\$ 276.00 ✗		
3	FRONT BUMPER SPOILER <i>Reps</i>	1	\$ 624.00 ✗		
4	FRONT BUMPER CLOSING ELEMENT <i>neu</i>	1	\$ 210.00 +		
5	FRONT BUMPER REINFORCEMENT FOAM <i>neu</i>	1	\$ 114.00 +		
6	FRONT BUMPER PULL STRAP <i>neu</i>	4	\$ 206.00 +		
7	FRONT BUMPER SECURING STRIP - LH <i>neu</i>	1	\$ 37.00 +		
8	FRONT BUMPER TOP COVER <i>neu</i>	1	\$ 127.00 +		
9	FRONT BUMPER AIR GUIDE GRILLE - LH <i>lit</i>	1	\$ 351.00 ✓		280.80
10	FRONT BUMPER GUIDE SECTION - LH <i>neu</i>	1	\$ 38.00 +		
11	FRONT REINFORCEMENT <i>3 neu</i>	1	\$ 708.00 +		
12	FRONT REINFORCEMENT COVER <i>neu</i>	1	\$ 65.00 +		
13	FRONT BUMPER SUPPORT - LH / RH <i>neu</i>	2	\$ 60.00 +		
14	CAUTION STICKER <i>3 neu</i>	1	\$ 14.00 +		
15	AIR CONDITIONER STICKER <i>neu</i>	1	\$ 8.00 +		
16	FRONT RADIATOR GRILLE <i>lit</i>	1	\$ 1,918.00 ✓		1,534.40
17	QUATTRO EMBLEM <i>neu</i>	1	\$ 106.00 ✓		84.80
18	FRONT RADIATOR GRILLE STRIKER PLATE <i>neu</i>	1	\$ 131.00 ✗		
19	HORN - LH <i>neu</i>	1	\$ 201.00 +		
20	HORN BRACKET <i>neu</i>	1	\$ 25.00 +		
SUB TOTAL SPARE PARTS		:	\$ 7,943.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 3211 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR <i>3 new</i>	2	TBC	+
22	FRONT PARKING AID SENSOR SEAL	4	\$ 6.00	+
23	FRONT HEADLIGHT MOUNTING - LH / RH <i>1 H cracked</i>	2	236.00	118. 94.40
24	FRONT HEADLIGHT RETAINING PLATE	1	\$ 78.00	+
25	FRONT HEADLIGHT - LH	1	\$ 2,721.00	+
26	FRONT HEADLIGHT LIFT CYLINDER - LH	1	\$ 204.00	+
27	FRONT HEADLIGHT LIFT CYLINDER HOSE	1	\$ 182.00	+
28	FRONT FOG LAMP - LH	1	\$ 286.00	+
29	RADIATOR AIR GUIDE- LH	1	\$ 25.00	+
30	RADIATOR UPPER COVER	1	\$ 31.00	+
31	FRONT NO PLATE <i>Nec</i>	S/N	\$ 60.00	✓
32	SUNDRIES <i>new</i>	\$	350.00 26.88	✓
TOTAL SPARE PARTS		:	\$ 12,122.00	
TOTAL LABOUR CHARGES		:	\$ 4,272.00	
GRAND TOTAL		:	\$ 16,394.00	

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *03/08/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days* *[Signature]*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT