

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 6-Aug-21

INSURANCE: CHINA

MODEL: Hyundai Ioniq

MVA: LIM T S

VEHICLE NO.: SHB2993R

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Boot Lid	1		\$2,480.40	✓ cut ✓
	Boot Lid Emblem-Hybrid	1		\$24.30	✓ nec ✓
	Boot Lid Emblem-Ioniq	1		\$31.30	✓ nec ✓
	Boot Lid Lamp RH / LH rh-nn	2	\$794.40	\$1,588.80	794.40 (LH) Scr
	Boot Lid Upper Glass Moulding	1		\$186.30	X SUC
	Boot Lid Lower Glass Moulding	1		\$145.20	X SUC
	TailLamp RH / LH	2	\$870.40	\$1,740.80	X SUC
	Third Brake Lamp	1		\$385.60	✓ cra ✓
	Rear Smart Key Antenna	1		\$40.50	✓ cut
	Rear Bumper	1		\$459.40	✓ cut ✓
	Rear Bumper Reinforcement	1		\$394.80	✓ cut
	Rear Bumper Reinforcement Bracket (LH/RH)	2	\$138.10	\$276.20	✓ dt
	Rear Bumper Centre Moulding Assy	1		\$451.25	✓ cut ✓
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00	✓ cut ✓
	Rear Bumper Cover Clips	10	\$2.20	\$22.00	✓ nec ✓
	Rear Bumper Reflector Lamp(LH/RH)	2	\$41.45	\$82.90	X SUC
	Rear Bumper Fog Lamp	1		\$201.50	X SUC ✓ cra
	Rear Bumper Towing Cover	1		\$98.80	X SUC
	SUB TOTAL			\$8,765.05	
	LESS 20%			\$1,753.01	
	DISCOUNTED TOTAL			\$7,012.04	
	Boot Lid ComfortDelGro	1		\$35.00	✓ nec
	Boot Lid 65521111	1		\$35.00	✓ nec
	Boot Lid APPS	1		\$40.00	X NA nn
	Rear Bumper Reverse Sensor	1		\$180.00	✓ cut
	Rear No.Plake W/Trim Cover	1		\$55.00	✓ cra
	Rear Windscreen Sealants	2	\$46.00	\$92.00	✓ nec
	S/NETT TOTAL			\$437.00	
	SPARE PARTS TOTAL			\$7,449.04	
	Labour Charge				
	Panel Beating			\$800.00	525 ✓
	Spray Painting Charge			\$600.00	500 ✓
	R/L Both Rear Upper & Lower Glasses			\$240.00	180 ✓
	Tuff Kote			\$60.00	30 ✓
	Check Lightings / Wirings			\$60.00	30 ✓
	Remove/Refix Reverse Sensor			\$120.00	60 ✓
	TOTAL LABOUR			\$1,880.00	
	ESTIMATE TOTAL			\$9,329.04	
	Acknowledged by Repairer				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.