

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 6-Aug-21INSURANCE: CHINAMODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHB2993R

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Boot Lid	1		\$2,480.40 ✓ Cut
	Boot Lid Emblem-Hybrid	1		\$24.30 ✓ nec
	Boot Lid Emblem-Ioniq	1		\$31.30 ✓ nec
	Boot Lid Lamp RH / LH	2	\$794.40	\$1,588.80 794.40 (LH) Scr
	Boot Lid Upper Glass Moulding	1		\$186.30 X SUC
	Boot Lid Lower Glass Moulding	1		\$145.20 ✓ CIA
	TailLamp RH / LH	2	\$870.40	\$1,740.80 X SUC
	Third Brake Lamp	1		\$385.60 ✓ CIA
	Rear Smart Key Antenna	1		\$40.50 ?
	Rear Bumper	1		\$459.40 ✓ Cut
	Rear Bumper Reinforcement	1		\$394.80 ?
	Rear Bumper Reinforcement Bracket (LH/RH)	2	\$138.10	\$276.20 ?
	Rear Bumper Centre Moulding Assy	1		\$451.25 ✓ Cut
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00 ✓ Cut
	Rear Bumper Cover Clips	10	\$2.20	\$22.00 ✓ nec
	Rear Bumper Reflector Lamp(LH/RH)	2	\$41.45	\$82.90 X SUC
	Rear Bumper Fog Lamp	1		\$201.50 X SUC
	Rear Bumper Towing Cover	1		\$98.80 X SUC
	SUB TOTAL			\$8,765.05
	LESS 20%			\$1,753.01
	DISCOUNTED TOTAL			\$7,012.04
	Boot Lid ComfortDelGro	1		\$35.00 ✓
	Boot Lid 65521111	1		\$35.00 ✓
	Boot Lid APPS	1		\$40.00 X NA
	Rear Bumper Reverse Sensor	1		\$180.00 ✓
	Rear No.Plate W/Trim Cover	1		\$55.00 ✓
	Rear Windscreen Sealants	2	\$46.00	\$92.00 ✓
	S/NETT TOTAL			\$437.00
	SPARE PARTS TOTAL			\$7,449.04
	Labour Charge			
	Panel Beating			\$800.00 525
	Spray Painting Charge			\$600.00 500
	R/R Both Rear Upper & Lower Glasses			\$240.00 180
	Tuff Kote			\$60.00 30
	Check Lightings / Wirings			\$60.00 30
	Remove/Refix Reverse Sensor			\$120.00 60
	TOTAL LABOUR			\$1,880.00
	ESTIMATE TOTAL			\$9,329.04

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan Ltk
up 3 days
6/8/21 16:36
82235769
thuan@China46

Date/Time: 06.08.2021 09:36

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD

Sales Order:

JC NO.: 305481529

OWNER

IS CITYCAB PTE LTD
OWNER NO. 7010070
LESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65551188 (O)


QUANTITY CARD NO.

REGN NO.: SHB2993R	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 04.08.2021 22:25
YR OF MANU. 06.08.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU165087	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 04.08.2021
NATURE: 3P 04.08.2021

S/NO LABOR CODE DESCRIPTION



RECEIVED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Identification Slip

Exit Pass

to: SHB2993R LIMITS

Vehicle No.: SHB2993R

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard