

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 4327C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID	NOT NECESSARY	955.00	-
1	REAR BOOT LID MAZDA LOGO	NOT NECESSARY	50.00	-
1	REAR BOOT LID 3 LOGO	NOT NECESSARY	45.00	-
2	REAR TAIL LAMP	NOT NECESSARY	361.70	-
2	REAR TAIL LAMP PANEL	NOT NECESSARY	361.70	-
4	REAR TAIL LAMP CLIPS @\$8.50	NOT NECESSARY	34.00	-
1	REAR BUMPER	DEFORMED	917.00	917.00
2	REAR BUMPER SIDE BRACKET @\$112.10	NECESSARY	224.20	116.00
2	REAR BUMPER SIDE REFLECTOR @\$97.30	NOT NECESSARY	194.60	-
8	REAR BUMPER CLIPS @\$5.00	NECESSARY	40.00	30.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	574.50	-
1	REAR BUMPER LOWER COVER	NOT NECESSARY	380.00	-
1	REAR END PANEL	NOT NECESSARY	557.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	279.80	-
	LESS 20% DISCOUNT		-	-212.60
			4,974.50	850.40
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	300.00	200.00
			300.00	200.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX CUSHION.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIX REVERSE SENSOR.		100.00	50.00
	TUFF KOTE.	NOT NECESSARY	120.00	-
	TO CHECK WIRING SYSTEM.	NOT NECESSARY	60.00	-
	PANEL BEATING.		600.00	200.00
	SPRAY PAINTING.		600.00	200.00
			1,600.00	450.00
	GRAND TOTAL		6,874.50	1,500.40

Report Ref No. CS/SMO21008372/Aqf3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,150.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO21008372/Aqf3n2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.