

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

10th AUGUST 2021

TP Sompoo
Xiao Chen.

Accident date: 06th AUGUST 2021

Estimated repair cost for vehicle no: SLG4327C Mazda 3 2016

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid		\$955.00 X
2	1	Rear boot lid Mazda logo		\$50.00 X
3	1	Rear boot lid 3 logo		\$45.00 X
4	2	Rear tail lamp	\$420.00	\$361.70 +
5	2	Rear tail lamp panel	\$156.00	\$361.70 +
6	4	Rear tail lamp clips	\$8.50	\$34.00 +
7	1	Rear Bumper <i>Debond</i>		\$917.00 ✓
8	2	Rear Bumper Side Bracket <i>new</i>	\$112.10	\$224.20 /16
9	2	Rear Bumper side reflector <i>new</i>	\$97.30	\$194.60 X
10	1	Rear Bumper reverse sensor <i>Debond</i>		\$300.00 200(SN)
11	8	Rear bumper clips <i>new</i>	\$5.00	\$40.00 30
12	1	Rear Bumper reinforcement <i>3x new</i>		\$574.50 +
13	1	Rear Bumper lower cover		\$380.00 +
14	1	Rear end panel <i>3 new</i>		\$557.00 X
15	1	Rear End Panel Top Garnish <i>new</i>		\$279.80 X

Subtotal :- \$5,274.50

1033
826.40 S-N: 2W

Labour charges

To Remove & refix cushion

\$120.00 X

To Remove & refix reverse Sensor

\$100.00 50

Tuff kote

\$120.00 X

To Check Wiring System

\$60.00 X

Panel beating

\$600.00 2W

Spray painting

\$600.00 2W

Subtotal :- \$1,600.00

Total :- \$6,874.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

450

total: 1476.40
h/s: 1150
02 Days