



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV00443/SONIYA HITEN KAMDAR
	Reg No/Reg Date	SMY825B / 15/02/202
	Date In/Mileage	/ 0
	Chassis No	KNARHB1BVM5047714
	Engine No	D4HELH251848
	Make/Model	KIA/SORENTO 2.2 A D SX SR G703
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
LAX00000	Credit	11/08/2021/ 09:35	BLC	442 / CocoLu	37660				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, FRT FENDER RH& LH REPAIR FRT DOOR RH & LH								2400.00
E PNT88000	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								100.00
M SUNDRY	TOP UP AIRCON GAS								80.00
M SUNDRY	FRT NUMBER PLATE WITH FRAME								50.00
M SUNDRY	APPLY SEALANT FOR ACCIDENT PORTION								40.00
E PNT98000	SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH, FRT SUPPORT FRT DOOR RH & LH								3040.00
A 90000001	CHECK WIRING & ELECTRICAL SYSTEM								30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								120.00
A 90000001	RENEW FRT DASHBOARD								400.00
A 90000001	RENEW FRT AIRBAG AND SEAT BELTS								400.00
A 90000001	REMOVE & INSTALL FRT RIGHT & LEFT SEATS AND SEAT AIRBAG								400.00
A 90000001	REMOVE & INSTALL ROOFLINING								400.00
E PNT88000	RENEW FRT WINDSCREEN								240.00
M SUNDRY	APPLY SEALANT FOR FRT WINDSCREEN								80.00
M SUNDRY	TRANSFER FRT RIGHT RIM								30.00
M SUNDRY									220.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV00443/SONIYA HITEN KAMDAR
	Reg No/Reg Date	SMY825B / 15/02/202
	Date In/Mileage	/ 0
	Chassis No	KNARH81BVM5047714
	Engine No	D4HELH251848
	Make/Model	KIA/SORENTO 2.2 A D SX SR G703
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/08/2021/ 09:35	BLC	442 / CocoLu	37660

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
APPLY SOLAR FILM FOR FRT WINDSCREEN				50.00
M SUNDRY				
Sundry				
M BRACKET, IU ADHESIVE	1.00	26.00	00.00	26.00
M COVER-FR BUMPER UPR	1.00	561.00	20.00	448.80
M SKID PLATE-FR BUMPER	1.00	166.00	20.00	132.80
M LIP-FR BUMPER	1.00	34.00	20.00	27.20
M REINF ASSY-FR BUMPER,LH	1.00	11.00	20.00	8.80
M REINF ASSY-FR BUMPER,RH	1.00	11.00	20.00	8.80
M GRILLE-FRONT BUMPER	1.00	246.00	20.00	196.80
M PIECE-BUMPER GRILLE	1.00	105.00	20.00	84.00
M AIR DUCT-FR BUMPER,LH	1.00	28.00	20.00	22.40
M AIR DUCT-FR BUMPER,RH	1.00	28.00	20.00	22.40
M LAMP ASSY-FR FOG,RH	1.00	646.00	20.00	516.80
M LAMP ASSY-FR FOG,LH	1.00	646.00	20.00	516.80
M WIRING HARNESS-FR BUMPER	1.00	213.00	20.00	170.40
M ABSORBER-FRONT BUMPER ENERGY	1.00	117.00	20.00	93.60
M STIFFENER ASSY-FR BUMPER LWR	1.00	102.00	20.00	81.60
M BRACKET-FR BUMPER SIDE,LH	1.00	15.00	20.00	12.00
M BRACKET-FR BUMPER SIDE,RH	1.00	15.00	20.00	12.00
M GARNISH ASSY-RAD GRILLE,UPR	1.00	209.00	20.00	167.20
M COVER-RADIATOR GRILLE UPR	1.00	107.00	20.00	85.60
M GRILLE ASSY-RADIATOR	1.00	692.00	20.00	553.60
M MOULDING-FRT BPR LICENSE PLATE	1.00	27.00	20.00	21.60
M ULTRASONIC SENSOR ASSY-P.A.S	2.00	189.00	20.00	302.40
M ULTRASONIC SENSOR ASSY-P.A.S	2.00	171.00	20.00	273.60
M GUARD ASSY-FRONT WHEEL,LH	1.00	76.00	20.00	60.80
M GUARD ASSY-FRONT WHEEL,RH	1.00	76.00	20.00	60.80
M PANEL ASSY-HOOD	1.00	1438.00	20.00	1150.40
M HINGE ASSY-HOOD,RH	1.00	62.00	20.00	49.60
M HINGE ASSY-HOOD,LH	1.00	62.00	20.00	49.60
M INSULATOR-FENDER RH	1.00	31.00	20.00	24.80
M INSULATOR-FENDER LH	1.00	31.00	20.00	24.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV00443/SONIYA HITEN KAMDAR
	Reg No/Reg Date	SMY825B / 15/02/202
	Date In/Mileage	/ 0
	Chassis No	KNARH81BVM5047714
	Engine No	D4HELH251848
	Make/Model	KIA/SORENTO 2.2 A D SX SR G703
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/08/2021/ 09:35	BLC	442 / CocoLu	37660
Description of Goods / Services					
		Qty	Unit Price	Disc%	Amount
M	INSULATOR-FENDER UPPER,RH	1.00	17.00	20.00	13.60
M	INSULATOR-FENDER UPPER,LH	1.00	17.00	20.00	13.60
M	PANEL ASSY-FENDER,RH	1.00	702.00	20.00	561.60
M	PANEL ASSY-FENDER,LH	1.00	702.00	20.00	561.60
M	BEAM COMPLETE-FR BUMPER	1.00	674.00	20.00	539.20
M	CARRIER ASSY-FRONT END MODULE	1.00	661.00	20.00	528.80
M	LIFTER-HOOD	1.00	60.00	20.00	48.00
M	PAD-HOOD INSULATING	1.00	172.00	20.00	137.60
M	LATCH ASSY-HOOD	1.00	105.00	20.00	84.00
M	TCU	1.00	1303.00	20.00	1042.40
M	LAMP ASSY-HEAD,RH	1.00	2279.00	20.00	1823.20
M	LAMP ASSY-HEAD,LH	1.00	2279.00	20.00	1823.20
M	PROTECTOR-WIRING	1.00	17.00	20.00	13.60
M	PROTECTOR-WIRING	1.00	20.00	20.00	16.00
M	BRACKET-WIRING MTG	1.00	9.00	20.00	7.20
M	COVER ASSY-COWL TOP	1.00	316.00	20.00	252.80
M	GLASS-WINDSHIELD	1.00	1536.00	20.00	1228.80
M	MOULDING-WINDSHIELD,UPR	1.00	21.00	20.00	16.80
M	BRACKET-W/S MLDG MTG,LH	1.00	35.00	20.00	28.00
M	BRACKET-W/S MLDG MTG,RH	1.00	35.00	20.00	28.00
M	GARNISH ASSY- RH	1.00	116.00	20.00	92.80
M	GARNISH ASSY- LH	1.00	116.00	20.00	92.80
M	CONDENSER ASSY-COOLER	1.00	934.00	20.00	747.20
M	DAM-AIR	1.00	23.00	20.00	18.40
M	GUARD-AIR,RH	1.00	12.00	20.00	9.60
M	PIPE & TUBE ASSY	1.00	785.00	20.00	628.00
M	RADIATOR ASSY	1.00	814.00	20.00	651.20
M	INSULATOR-RADIATOR MTG,LWR	1.00	10.00	20.00	8.00
M	BRACKET ASSY-RADIATOR MTG,UPR	1.00	24.00	20.00	19.20
M	HOSE ASSY-RADIATOR,UPR	1.00	48.00	20.00	38.40
M	HOSE ASSY-RADAATOR,LWR	1.00	52.00	20.00	41.60
M	HOSE	1.00	27.00	20.00	21.60
M	RESERVOIR & HOSE ASSY-RAD	1.00	165.00	20.00	132.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV00443/SONIYA HITEN KAMDAR
	Reg No/Reg Date	SMY825B / 15/02/202
	Date In/Mileage	/ 0
	Chassis No	KNARH81BVM5047714
	Engine No	D4HELH251848
	Make/Model	KIA/SORENTO 2.2 A D SX SR G703
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/08/2021/ 09:35	BLC	442 / CocoLu	37660
Description of Goods / Services					
		Qty	Unit Price	Disc%	Amount
M	HOSE ASSY-WATER	1.00	27.00	20.00	21.60
M	BLOWER ASSY	1.00	698.00	20.00	558.40
M	GUARD-AIR	1.00	64.00	20.00	51.20
M	SHIELD-AIR INTAKE	1.00	27.00	20.00	21.60
M	DUCT ASSY-AIR	1.00	45.00	20.00	36.00
M	DUCT ASSY-AIR	1.00	69.00	20.00	55.20
M	CLEANER ASSY-AIR	1.00	175.00	20.00	140.00
M	SENSOR ASSY-AIR FLOW	1.00	276.00	20.00	220.80
M	HOSE ASSY-AIR INTAKE	1.00	158.00	20.00	126.40
M	GUARD ASSY-AIR,LH	1.00	49.00	20.00	39.20
M	INTERCOOLER	1.00	943.00	20.00	754.40
M	HOSE-BYPASS	1.00	68.00	20.00	54.40
M	VALVE-BYPASS	1.00	797.00	20.00	637.60
M	HOSE-INTERCOOLER INLET	1.00	184.00	20.00	147.20
M	BRKT-I/C, UPR	1.00	29.00	20.00	23.20
M	RESONATOR	1.00	396.00	20.00	316.80
M	STARTER ASSY	1.00	645.00	20.00	516.00
M	MANIFOLD ASSY-INTAKE	1.00	760.00	20.00	608.00
M	ELECTRONIC CONTROL UNIT	1.00	1906.00	20.00	1524.80
M	PANEL ASSY-UNDER COVER	1.00	339.00	20.00	271.20
M	WHEEL ASSY-ALUMINIUM	1.00	799.00	20.00	639.20
M	CRASH PAD ASSY-MAIN	1.00	865.00	20.00	692.00
M	HEADLINING ASSY	1.00	1536.00	20.00	1228.80
M	MAP BOARD ASSY-FRT SEAT BACK,R	1.00	216.00	20.00	172.80
M	ADJUSTER ASSY-HEIGHT	2.00	43.00	20.00	68.80
M	S/BELT ASSY-FR RH	1.00	471.00	20.00	376.80
M	S/BELT ASSY-FR LH	1.00	471.00	20.00	376.80
M	BUCKLE ASSY-FR S/BELT,RH	1.00	97.00	20.00	77.60
M	BUCKLE ASSY-FR S/BELT,LH	1.00	97.00	20.00	77.60
M	BUZZER ASSY-PIEZO	1.00	68.00	20.00	54.40
M	SENSOR ASSY-A TYPE CRASH	1.00	44.00	20.00	35.20
M	HORN ASSY-BURGLAR ALARM	1.00	107.00	20.00	85.60
M	SENSOR ASSY-PRESS TYPE CRASH	1.00	88.00	20.00	70.40

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for a KIA SORENTO.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: LAX00000, Credit, 11/08/2021/ 09:35, BLC, 442 / CocoLu, 37660

Table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists items like SENSOR ASSY-A TYPE CRASH, MODULE ASSY-STRG WHEEL AIR BAG, etc.

Estimate

Table for confirmation and totals. Includes 'Confirm & accepted by' and a summary table with Nett (39,549.20), 7% GST on (2768.44), and Total Payable (42,317.64).

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.