

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 11 Aug 2021

Preliminary Advice

Vehicle No	: SMY825B	Accident Date	: 08/08/2021
Make	: KIA SORENTO	Policy No.	: 7210013338
Assignment Date	: 11/08/2021	Excess	: S\$0.00
Date of Inspection	: 11/08/2021	Est. Duration of Repair	: 14
Inspection At	: CYCLE & CARRIAGE KIA PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,549.20
Revised Amount	:S\$	30,406.80
Check Items (Estimated)	:S\$	6,548.00
Total	:S\$	36,954.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	189,000.00
COE / PARF Rebate	:S\$	72,902.00
Salvage Value	:S\$	
Margin for Repair	:S\$	116,098.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check items) stated are subject to part prices and labour cost.