

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 10 Aug 2021)**Parts:** 143      HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA3792C/10/08/2021 09:48**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

| No. | Qty | Part No. | Particulars              | %Disc | %Depr | Amount                   |
|-----|-----|----------|--------------------------|-------|-------|--------------------------|
| 1   | 1   |          | *BOOTLID                 | 20.00 | 0.00  | *2,609.80 FLX <i>old</i> |
| 2   | 1   |          | *BOOTLID H EMBLEM        | 20.00 | 0.00  | *63.10 FLX <i>damage</i> |
| 3   | 1   |          | *BOOTLID CRDI EMBLEM     | 20.00 | 0.00  | *52.40 FLX               |
| 4   | 1   |          | *BOOTLID I40 EMBLEM      | 20.00 | 0.00  | *67.90 FLX               |
| 5   | 1   |          | *REAR BUMPER             | 20.00 | 0.00  | *1,106.00 FL <i>Ry</i>   |
| 6   | 1   |          | *REAR BUMPER UNDER COVER | 20.00 | 0.00  | *228.00 FL <i>Ry</i>     |
| 7   | 10  |          | *REAR BUMPER CLIPS       | 20.00 | 0.00  | *22.00 FL <i>Ry</i>      |
| 8   | 1   |          | *BOOTLID COMFORTDELGRO   | 0.00  | 0.00  | *15.00 F <i>Xun</i>      |
| 9   | 1   |          | *BOOTLID 65521111        | 0.00  | 0.00  | *15.00 F <i>X</i>        |
| 10  | 1   |          | *REAR BUMPER MAT         | 0.00  | 0.00  | *50.00 F <i>X</i>        |
| 11  | 1   |          | *REVERSE SENSORS         | 0.00  | 0.00  | *135.70 F <i>X</i>       |
| 12  | 1   |          | *BOOTLID MOULDING        | 20.00 | 0.00  | *85.00 FL <i>X</i>       |
| 13  | 1   |          | *BOOTLID LOWER GARNISH   | 20.00 | 0.00  | *227.90 FL <i>X</i>      |

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) **4,677.80**  
 - List Item Discount on L Items (S\$) **892.42**

Total Parts (S\$) **3,785.38**

ComfortDelGro Engineering Pte Ltd/SHA3792C/10/08/2021 09:48. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

| No                         | Qty | Particulars          | Amount |
|----------------------------|-----|----------------------|--------|
| <u>Miscellaneous Items</u> |     |                      |        |
| 1                          | 1   | OD/TP Case (Insurer) | 11.00  |
| Sub Total (S\$)            |     |                      | 11.00  |

11

## Estimates on Labour

| No                      | Particulars             | Lab.Type | Amount       |
|-------------------------|-------------------------|----------|--------------|
| <u>Labour Items</u>     |                         |          |              |
| 1                       | PANEL BEATING           | New      | 280 600.00   |
| 2                       | SPRAY PAINTING          | New      | 250 600.00   |
| 3                       | TUFF KOTE               | New      | 11 X 50.00   |
| 4                       | CHECK LIGHTINGS ETC     | New      | 11 X 40.00   |
| 5                       | R/I REVERSE SENSORS     | New      | 30 120.00    |
| 6                       | TOWING FEE - KING DOLLY | New      | 100 150.00   |
| Gross Labour Cost (S\$) |                         |          | 660 1,560.00 |

ComfortDelGro Engineering Pte Ltd/SHA3792C/10/08/2021 09:48. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 1749 5749  
 'WP' w/e/21 e 330, w

02 days

4/5 Resurvey after repair

Tanpin e/11k auto.com.

\$671 #  
 2 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval