



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20210724/0737		LOCATION OF FIRE: Along Tampines Avenue 11, Near Lamp Post No. 3 Singapore	
FIRE REPORTED ON : 24 July 2021			
TIME OF CALL : 20:11:49 hrs			
STATION COVERAGE : Tampines Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine compartment of a BMW M3 car (SMV91S).			
METHOD OF EXTINGUISHMENT: By a member of public using a dry powder fire extinguisher before the arrival of SCDF crew.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating / electrical origin at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, a section of the engine compartment comprising electrical cables, intake system with charge air cooler, coolant expansion tank and other nearby parts were damaged. Other parts of the engine compartment, as well as the bonnet and the windscreen, sustained varying degrees of heat and smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
 CINDY HAN for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.