

Vehicle Recall Details

ONLY INFORMATION ON VEHICLE RECALLS SUBMITTED FROM 9 APRIL 2007 IS AVAILABLE

| | |
|-------------------------------|---|
| Owner ID Type | Owner ID |
| Foreign Identification Number | 455K |
| Vehicle No. | Make/Model |
| SMV91S | B.M.W./ M3 SEDAN AT ABS D/AIRBAG 2WD LED NAV HUD |
| Engine No.: | Chassis No.: |
| 08178859S55B30A | WBS3C92060J274182 |

Recall Details

| Recall No.: R2021071012 | |
|---|--------------------------------------|
| Manufacturer Recall Date: | Estimated Completion Year of Recall: |
| 29 Jun 2021 | 2023 |
| Brief Description (As Provided by Motor Dealer): | Date Rectified: |
| The (Takata) gas generator of the driver's airbag can malfunction if it has been exposed to high absolute air humidity and high temperature fluctuations for years. | - |
| Hotline Information: | |
| PERFORMANCE MOTORS LIMITED at 1-800-2255-269 BIS AUTOMOBILES PTE. LTD. at 68-963-933 | |
| For more details, contact BMW ASIA PTE LTD | |