



Date	10/8/2021
Vehicle	SKJ 6880D
Make/Model	VOLKSWAGEN JETTA
Chassis No.	WVWZZZ16ZDM079418

	S/Nett Items			
1	FRONT BUMPER CLIP SET	1	120	\$ 80 net 120.00
2	FRONT FENDER COWLING CLIP SET	1	120	\$ 10 net 120 120.00
3	FRONT DOOR INNER TRIM CLIP SET	1	120	\$ net x 120.00
4	FRONT TYRE RH	1	800	\$ net x 800.00
			Total	\$ 1,160.00

	LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	1200	\$ 600	1,200.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1200	\$ 800	1,200.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	1	120	\$ 30	120.00
4	TO CHECK WHEEL ALIGNMENT AND ADJUST	1	120	\$ 80	120.00
5	TO RNR UNDERCARRIAGE	1	250	\$ 160? plus	250.00
6	TO CHECK WHEEL BALANCING	1	120	\$ 30	120.00
7	TO RNR REAR FRONT DOOR MECHANISM	1	250	\$ x nn	250.00
Total Labour				\$	3,260.00
Parts Replacement Amount				\$	1,160.00
				15,516.29	
Total Amount				\$	4,420.00

Tauphin 97415749
 'up' 12/18/21 @ 1650
 L/S Resurvey after repair
 tauphin@khanh.com
 # 5 days

2124
 30
 1540
 3694
 16542950
 05 days
 #

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: