

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com /teamautopl@gmail.com

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SMJ 6209 U**
 Model : Honda Freed
 Year : 2019
 Chassis No : GB71079797

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

| Nos. | PARTS | Qty | Unit S\$ | TOTAL S\$ |
|----------------------|--|-----|-------------|------------------------|
| 1 | Bonnet | 1 | \$ 1,534.70 | \$ 1,534.70 |
| 2 | Bonnet lock assy | 1 | \$ 234.60 | \$ 234.60 |
| 3 | Front bumper | 1 | \$ 1,450.00 | \$ 1,450.00 |
| 4 | Front bumper side retainer | 2 | \$ 89.40 | \$ 178.80 |
| 5 | Front bumper lower grille | 1 | \$ 326.00 | \$ 326.00 |
| 6 | Front bumper lower grille side garnish | 2 | \$ 131.00 | \$ 262.00 |
| 7 | Front bumper reinforcement | 1 | \$ 486.00 | \$ 486.00 |
| 8 | Headlamp assy | 2 | \$ 1,954.80 | \$ 3,909.60 |
| 9 | Headlamp bracket | 2 | \$ 176.00 | \$ 352.00 |
| 10 | Front grille | 1 | \$ 830.00 | \$ 830.00 |
| 11 | Front grille logo | 1 | \$ 78.00 | \$ 78.00 |
| 12 | Front grille inner panel | 1 | \$ 299.80 | \$ 299.80 |
| 13 | Front grille chrome | 1 | \$ 168.00 | \$ 168.00 |
| 14 | Front grille chrome lower | 1 | \$ 175.00 | \$ 175.00 |
| 15 | Front grille upper bracket (centre) | 1 | \$ 91.00 | \$ 91.00 |
| 16 | Front fender LH | 1 | \$ 895.30 | \$ 895.30 |
| 17 | Front fender inner cowling LH | 1 | \$ 164.80 | \$ 164.80 |
| 18 | Front fender emblem 'HYBRID' | 1 | \$ 85.00 | \$ 85.00 |
| 19 | Front support top panel | 1 | \$ 898.00 | \$ 898.00 |
| 20 | Front support top panel garnish | 1 | \$ 185.00 | \$ 185.00 |
| 21 | Radiator | 1 | \$ 987.90 | \$ 987.90 |
| 22 | Aircon condenser | 1 | \$ 985.00 | \$ 985.00 |
| Parts Sub Total : | | | | \$ 14,576.50 |
| 20% Discount : | | | | \$ 2,915.30 |
| PARTS TOTAL : | | | | \$ 11,661.20 |

CAT, XR
 NDX
 CRAV
 NECV
 BR ✓
 NSX
 BT ✓
 BR ✓
 BR ✓
 BR ✓
 BR ✓
 NSX
 NSX
 BR ✓
 NSX
 NSX
 BT ✓
 NSX
 NECV
 NDX
 NDX

| Nos. | SPECIAL NETT | Qty | Unit S\$ | TOTAL S\$ |
|-----------------------------|---------------------------------------|-----|-----------|---------------------------|
| 1 | Sundries | 1 | \$ 80.00 | \$ 80.00 |
| 2 | Bonnet sealant | 1 | \$ 100.00 | \$ 100.00 |
| 3 | Front bumper clips | 1 | \$ 50.00 | \$ 50.00 30.00 |
| 4 | Front bumper lower grille clips | 1 | \$ 50.00 | \$ 50.00 20.00 |
| 5 | Front grille clips | 1 | \$ 50.00 | \$ 50.00 30.00 |
| 6 | Front fender sealant | 1 | \$ 100.00 | \$ 100.00 |
| 7 | Front fender inner cowling clips | 1 | \$ 50.00 | \$ 50.00 |
| 8 | Front support top panel sealant | 1 | \$ 100.00 | \$ 100.00 |
| 9 | Front support top panel garnish clips | 1 | \$ 50.00 | \$ 50.00 |
| 10 | Radiator coolant | 1 | \$ 80.00 | \$ 80.00 |
| 11 | Aircon fluid | 1 | \$ 80.00 | \$ 80.00 |
| SPECIAL NETT TOTAL : | | | | \$ 790.00 |

NNX
 NNX
 NEC ✓
 NNX
 NNX
 NNX

| Nos. | LABOUR | | S\$ |
|-----------------------|-----------------------------|-----------|-------------------|
| 1 | R&R radiator | \$ | 150.00 |
| 2 | R&R aircon condenser | \$ | 150.00 |
| 3 | Diagnostic reset fault code | \$ 120.00 | 300.00 |
| 4 | Upholstery | \$ | 300.00 |
| 5 | Check wiring | \$ 28.00 | 100.00 |
| 6 | Panel beating | \$ 800.00 | 1,400.00 |
| 7 | Rust proofing | \$ | 200.00 |
| 8 | Spray painting | \$ 800.00 | 1,400.00 |
| LABOUR TOTAL : | | \$ | 4,000.00 |

} NNA
NEC
NNX
/

Survey Resurvey
11/8/2021 12/8/2021
1745 hrs 1330hrs
T Colin T Colin
Mr Mr

| | | |
|----------------------|-----------|------------------|
| PARTS TOTAL : | \$ | 11,661.20 |
| SPECIAL NETT TOTAL : | \$ | 790.00 |
| LABOUR TOTAL : | \$ | 4,000.00 |
| GRAND TOTAL : | \$ | 16,451.20 |

Part by Part repair
Repair days 7

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: