SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies,

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

14/07/2021 15:20 (SGT) Date of Accident 13/07/2021 17:25 (SGT) Exact Location of Accident Singapore

Additional Location Information JUNCTION OF PIONEER ROAD NORTH AND NANYANG **FLYOVER**

Singapore

Country/State of Loss

DETAILS OF OWN VEHICLE

Vehicle Registration Number YP4083D

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No Email Address

Mobile Phone No

Alternative Phone No

NEWCON BUILDERS PTE. LTD. 200713695G

(Phone (Office)

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Mitsubishi Canter

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category

Transmission

CC

Employment

No - Claiming third party Commercial vehicle

Manual 2998

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy

Policy Number

Cover Note Number

NTUC Income Insurance Co-operative Ltd

Comprehensive No

5118530550

09/09/2020 - 08/09/2021

DRIVER

Name of Driver

LAKSHMANAN KRISHNAN

Passport No/FIN	
Date Of Birth	14/02/1984
Occupation	Outdoor
Date Of Driving Pass	26/03/2013
Driving experience	8 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone)
Alt, Phone Number	•
Email Address	
Address	
Address complement	<u>. </u>
Postcode	
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employ ee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Incompany Community of Other Vehicle Oversed by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Collision - Cross Junction
Weather Conditions	Drizzling
Road Surface	Wet
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s)	·
soliciting/offering accident claims assistance?	No
DÉTAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	NO
n you against month	•
OUDQUINOTANOED OF ACCIDENT	
CIRCUMSTANCES OF ACCIDENT	
Refer to sketch plan	
ATTACHMENT(S)	
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	VIDEO SIZE HUGE TO UPLOAD
Was there any audio recorded?	No
•	
DETAILS OF OTHER	VEHICLE PROPERTY 1
DETAILS OF OTHER	
Vahiolo Docistration Number	01.04000
Vehicle Registration Number	SI D4383S

Vehicle Registration Number	
Vehicle Manufacturer	Mazda
Vehicle Model	3
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	TAN BEE TECH
NRIC No	



8 N.C	40331	NON	0012	\$1700.5	10.00	1995	13210

Normal Date in Stand I made	(4.67 202) (Sint
Visional Salas Barrer	Our server Trans

Repost No. 201 D. C. A. (2462/2021)

Gene: 17/22 lips:

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the datails of the accident to speed up the claims process.
- 2. This Force must be completed by the Policyholder and/or the Authorised Driver.
- Information provided most be as trutiful and accurate as possible. Any wilful misropresentation or withholding of material facts may allow insurance componies to repudiate policy liability.
- Fire issue and acceptance of this form by insurance compenies is not an admission of poscy sublity on the part of the insurance corapanies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the 6th Records Monagement Centre established by the General Insurance Association of Singapore (6th) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the enclaving of this report of the centre and to copies of the report being made available aforesold.
- 8. Consent under the Personal Data Protection Act (PDPA)

I underständ, odknowledge, egree and consum that:

- (a) My institut, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Inserter' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/suthority (such as the police), for the purpose(s) of :
 - processing, pandling and/or dealing with my claims locating the settlement of the dains and any necessary investigations relating to the claims;
 - (ii) lavesugating the arcident and/or my daines;
 - (iii) Carrying out and/or dealing with my instructions or responding to any enqueries by me;
 - (iv) administering my claims fincluding the moling of correspondence, statements, involves, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the name as well as on the exturnal cover of annelogies/moli packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or desiring with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' towyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the phase Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their their party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

Driver's Signification of driver is not the principalities? Date is Time

- (e) the information so coffeeted under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating investigating, controlling or managing froud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

440721 15:00


J. Varner

14-07-21 (35-69)

Graech (\$993563) Costoner Care Execusive Mator Service Conne

Waterspeed by Reporting Dentre Personnel

Policyheizer's Signiture / Ordu & Tota



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was going straight along Pioneer Rood North under Nanyang Plyover on lane 3 and the traffic was green in tny favour. Suddenny s chuic B coming from apposite direction surving right to PH; and I didn't naturage to stop to stood collision resulted collision with vehicle B. After which both drivers allefined to assess the damage, took some photos and exchange particulars. No me was injured in chis accident.

Declaration

- Platified Selective to regular particulors are tree in every respect.


14 07 31 15,60

Directs Equation of the is next open, helder. Dat. & True


Ganash (8593861). Castomic Cafe Even the Control Service Control

With as was a village and they Control Ferragon of


Page 5 of 13





















NEW PIONEER AUTO PTE. LTD.

1 Soon Lee Street #01-50, Pioneer Centre Singapore 627605

Co. / GST Registration No.: 201319665W

PROFORMA INVOICE

DATE: 06 August 2021 VEHICLE NO.: YP 4083 D

MAKE/MODEL: MITSUBISHI CANTER FEB21ER4SDEB

Newcon Builders Pte. Ltd. C/O 1 Soon Lee Street #01-50 Pioneer Centre Singapore 627605

REPAIR BILL FOR VEHICLE NO. YP 4083 D

Total Repair cost (Lump Sum Repair) 5300.00

Add 7% GST 371.00

Total: <u>5671.00</u>

PRECISION APPRAISAL SERVICES



Insurance Loss Assessors/Adjusters Cargo Surveyors & Licensed Appraisers 227 Simei St 4 #06-42 Singapore 520227 Fax: 6444 4886 Company Registration No. 53139926E

To:

Newcon Builders Pte. Ltd. C/O 1 Soon Lee Street #01-50 Pioneer Centre Singapore 627605 Invoice No.: 210848

DATE: 06 August 2021

	DESCRIPTION	AMOUNT
Vehicle Registration No.	: YP 4083 D	
Type of Claims	: Third Party Claims	
Our Reference No.	: PAS/NP/210848/TP	
Your Reference No.	: -	
Inspection Report Fees	: (including transportation charges & photographs)	\$701.00
Reinspection Report Fees	: -	
Transportation Charges	: -	
Additional Photographs	: -	
Others (Specify)	: -	
DOLLARS SE	VEN HUNDRED AND ONE ONLY TOTAL:	\$701.00



PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/Adjusters Cargo Surveyors & Licensed Appraisers 227 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To:

Newcon Builders Pte. Ltd. C/O 1 Soon Lee Street #01-50 **Pioneer Centre Singapore** 627605

INSURANCE DETAILS

Insured

Policy No. / Claim No. : -

Sum Insured

Excess Clause

Windscreen Coverage:

Type of Claims : Third Party Claims

Third Party Insurer Third Party Policy No.: -

Inspection Report Date: 06 August 2021

Workshop Name:

New Pioneer Auto Pte. Ltd.

Inspection Address:

1 Soon Lee Street #01-50 Pioneer Centre

Singapore 627605

REFERENCE

Assigned By

: As above

Accident Date

: 13 July 2021 : 19 July 2021

Inspection Date

: 19 July 2021

Our Reference No. : PAS/NP/210848/TP

Assignment Date

PARTICULARS OF VEHICLE

Registration No.

: YP 4083 D

Make/Model

: MITSUBISHI CANTER FEB21ER4SDEB

Yr of Manuf/Regn

: 09 Sep 2016

Carrying Capacity : X

Chassis No.

: FEB21EA20975

Engine No.

: 4P10C35273

Colour

: Metallic White

Class

: Goods (Lorry w Canopy)

Mileage

. 416076

Km/h

Radio/Casette CD Disc Player

: Fitted

: Fitted

Air Conditioner

: Fitted

Clock

: Fitted

Seat Belt

: Fitted

Wing Mirror

: Fitted

Other Accessories: Fitted

PRE-ACCIDENT CONDITION (Static Check Only) VEHICLE VALUE

Body Work

: Good

Paint Work

: Good

Handbrake

: Serviceable

Footbrake

: Serviceable

Steering

: Serviceable

Any Apparent

: None Eng Modifications

Market Value

Wreck Value (Parf) : -

TYRE SIZE & CONDITION

Front N/s Size : 195/85R15LT

80 %

Front O/s Size

195/85R15LT

80 %

Make Rear N/s size : 195/85R15LT

: BRIDGESTONE

80 %

Rear O/sSize

Make

Make

BRIDGESTONE 195/85R15LT BRIDGESTONE

80 %

Make

: BRIDGESTONE

80 %

Spare Size Make

: 195/85R15LT BRIDGESTONE

Type of Wheel Rims: Standard

Jack & Tools

: Intact/ Missing

Note: The above percentage % represent the estimated remaining tyre threads.


PRECISION APPRAISAL SERVICES

Insurance Loss Assessors / Adjusters Cargo Surveyors & Licensed Appraisers

VEHICLE REGISTRATION NO.: YP 4083 D







GENERAL DESCRIPTION OF DAMAGES

Parts damaged were: The front n/s door and pillar, front n/s corner panel and bumper were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 19/07/2021 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s New Pioneer Auto Pte. Ltd. as per attached Appraisement Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Lump Sum Repair Basis of \$5,300.00 after deducting the Policy Excess Clause of \$NA.

As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's			Our			
	Esti	imate	Amount	R	evised	Amount	
Spares Parts	:	7408	89		3939	94	
Towing Charges	:	Χ	X		X	Х	
PB Labour Charges	:	1400	00		980	00	
Others Misc Charges	:	380	00		290	00	
Paintwork	:	1800	00		1400	00	
Total	: \$	10988	89	\$	6609	94	

Under normal circumstances, the duration of repairs should not exceed Nine (09) days including

Pre-Repair Inspection (PRI) / Pre-Repair Survey (PRS) waiting time frame & Public Holidays.

Attached photographs taken during inspection Seventy - Six (76) Photographs

SPECIAL REMARKS

- 1. The inspection was conducted on a 'without prejudice' basis
- 2. On 21/07/2021, we examined the extent of damages.
- 3. On 27/07/2021, we examined the repaired vehicle.

Yours FaithFully

TFNG PHILIPFOO ACII CAE, AMIMI

A I A M E, A M S A E-A Licensed Appraiser/Adjuster

Inspection Report Date: 06 August 2021

VEHICLE REGN NO :

YP 4083 D

OUR REFERENCE

PAS/NPA/210848/TP

INSPECTION REPORT DATE:

6-Aug-21

APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO:

1

S/No Qty Parts / Labour Descripti		Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation / Revised Amount	
		PARTS SUPPLY - LIST ITEMS		\$ cts	\$ cts	
1	1pc	N/s Headlamp	Broken	501.42	501.42	
2	3pcs	N/s Headlamp clips@\$5.5	Necessary	16.50	16.50	
3	1pc	N/s Headlamp top reflector o/s	Broken	230.34	230.34	
4	1pc	Front n/s side lamp	Broken	245.00	245.00	
5	2pcs	Front n/s side lamp clips@\$4	Necessary	8.00	8.00	
6	1pc	Front bumper	Badly Dented	1010.34	1010.34	
7	1pc	Front bumper side rubber n/s	Dented/Bent	353.71	353.71	
8	1pc	Front bumper bracket n/s	Bent	203.13	203.13	
9	1pc	Front n/s corner panel	Badly Dented	524.54	524.54	
10	1pc	Front n/s door	Badly Dented/Deformed	1534.85	1534.85	
11	1pc	Front n/s door pillar	Dented	1533.24	Repair	
12	1pc	Front n/s door check	Bent	86.45	86.45	
13	1pc	Front n/s door lower hinges	Bent	168.26	168.26	
14	1pc	Front n/s door upper hinges	Bent	168.26	168.26	
15	1pc	Front n/s door air vent	Warped	202.45	202.45	
16	1pc	Front n/s step panel garnish	Dented/Defaced	622.40	Repair	
		//		7408.89	5253.25	
		Less: 25% discount		- 1	1313.31	
				7408.89	3939.94	
		LABOUR & MISC. CHARGES				
1		Remove the necessary affected	parts,			
		straighten front n/s door pillar,	front	1400.00	980.00	
		n/s step panel and wheel arch				
		and replace parts				
2		Putty and Spraypaint on all affe	cted parts	1800.00	1400.00	
3		Check electrical		100.00	80.00	
4		Remove and refit front n/s door	parts	150.00	120.00	
5		Tuff Kote		50.00	30.00	
6		Rewire front portion and n/s		50.00	30.00	
		headlamp beam				
7		Rewrite door lettering		30.00	30.00	
	-	Note: Recommended lump sum				
		repair at \$5,300.00nett	SUB / GRAND TOTAL	10988.89	6609.94	

PRECISION APPRAISAL SERVICES

Ce Vola













































