

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No : EST0027659
Thia Cherk Ngoh

Page 1 of 1
Your ref. TP-SGL 59K ECICS
Job No. 72181
Our ref. 21.08.13
Payment
Date 11/8/2021

Attn :
Vehicle No : SMU 3815G
Vehicle Model : Mazda 6
Accident on : 9/8/2021

Not Authorized
Penney B & pain
\$2529.20 *6 days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front door RH	982.00	20.00	785.60 ✓
1.00	Set	Front door frame tapes RH	42.00	20.00	33.60 ✓
Labour & Misc:					
1.00		To check/clear fault codes after repair	80.00		80.00 60d
1.00		Tuff coat	40.00		40.00 30d
1.00		To knock dents on rocker panel RH + renew of parts	350.00		350.00 32d
1.00		To spray paint (including rear door RH + rear fender RH + blend front fender RH + roof side panel RH / Pearl Red)	1,500.00		1,500.00 1300d

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S\$

2,789.20
195.24
2,984.44