MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Tel: 6748 4422/ 6745 4422 Fax: 6747- 6720 REG NO 200501102H

Springleaf Tower Singapore 079909 Tel: 6389 - 6111	Quota OATE : 13.08 YEH NO : SMT4 MODEL : Toyot O A : 07.08 YER REF : YM93	3.2021 1444S ta Wish 3.2021
Attn: Motor Claim Dept (Pls arrange vehicle survey & check liability)		
RE: ESTIMATE FOR ACCIDENT REPAIR SMT4444S (TOY	OTA WISH)	
<u>Item</u> <u>Description</u>	_Qty	Amt
1 Front Bumper Defined 2 Bear Bumper Side Holder - RH 3 Front Bumper Reinforcement 4 Front Bumper Fog Lamp Cover - RH 5 Head lamp - RH 6 Front Fender - RH 7 Front Fender Inmer Shield - RH Less 25% S/NET ITEMS	\$67.60 \$0.70 1 1 1 1 \$	645.10 68.90 299.30 45.20 953.60 698.00 218.40 2,928.50 (732.13) 2,196.38
1 Front Bumper Clips New 2 Front Fender Inner Shield Clips - RH New	1 set 1 set	30.00 / 30.00 / 60.00
Total parts	\$	2,256.38
LABOUR CHARGE		
1 To knocking out front portion & renew above parts	\$	600.00 300
2 To putty & spray up paint works),\	600.00 300 400.00 L
3 To check wiring	\$ \$	59.00 30

RE: ESTIMATE FOR ACCIDENT REPAIR SMT4444S (TOYOTA WISH)

Total Labour

\$ 1,050.00

Grand Total

\$ 3,306.38

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 2010.70 2/5: 1.6k. 07Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: