

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / RES / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **FRK18982**
 at Workshop No: **BNN**
 of _____
 Insured: **Any 30424**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **4200**
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % d Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: **1451761** Vehicle IN / OUT

Date / Time Action / Instruction
Net 42439

Veh No: **FRK18982** Yr Regn: **13/4/15**
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Yamaha YBR125** cc **124**
 Colour: **Red** A/C: Insured / Std / NI / NA
 Sp Reading: **40452** T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C/No: **LBPKC 1789E 0028774**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modr: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **2.75-18**
 R: **3.00-18**
 BB / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **TAMSA**
 Front: **7** mm Rear: **7** mm
 R/Bal: _____ mm L/Bal: _____ mm
 L/Bal: _____ mm D.O.A: **6/8/21** D.O.I: **11/8/21**
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear 1 O/S body
 The U/C / Chassis frame / Body Structure affected due to collision

Date/Time, File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

) 8 + RS 31

) Phone

) Other

)

1, 1, 1

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐
☐
☐
☐

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 38917

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO. : FBK1698Z
MAKE/MODEL : YAM / YBR125

DATE : 10/08/2021
CLAIM NO. : 11773
POLICY NO. : MC/00914057
FROM : RAYMOND

not Authorised
1/58
3 days
11/8/21
Take photo after repair

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 25363 - (REPORTED BY MECHANIC)	1/1 REPLACE	1.00	\$23.00	500 23.00 X
2	BRACKET FOOTREST LH P/N: 25346 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	Self 38.00
3	BRACKET FOOTREST RH P/N: 25345 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	Self 38.00
4	BRACKET UNDER FORK P/N: 27458 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$180.00	100 180.00 X
5	COVER TAIL LH (RED) P/N: 45418 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$90.00	100 90.00 X
6	CROWN HANDLE P/N: 28100 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$75.00	100 75.00 X
7	FOOTREST FRONT P/N: 50005 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	100 55.00
8	FOOTREST REAR ASSY LH P/N: 25348 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$15.00	100 15.00
9	FOOTREST REAR ASSY RH P/N: 25347 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$15.00	100 15.00

*38917 *

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

bitsafe



S/N	Description	Action	Qty	Unit Price	Amount
10	FORK FRONT ASSY LH P/N: 45155 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$252.00	17 252.00 X
11	FORK FRONT ASSY RH P/N: 45154 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$252.00	17 252.00 X
12	GASKET EXHAUST PIPE P/N: 21453 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	24 5.00
13	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1	\$63.00	280 504.00
14	LAMP SIGNAL REAR LH P/N: 26504 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	17 28.00 X
15	MUDGUARD FRONT (RED) P/N: 45374 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$98.00	17 98.00 X
16	PEDAL BRAKE P/N: 44906 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$88.00	2 88.00 X
17	PEDAL GEAR (SHORT) P/N: 45076 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	17 19.00 X
18	PIPE EXHAUST ASSY P/N: 68440 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$399.00	20/34 399.00
19	REPAIR REAR BODY ALIGNMENT - (REPORTED BY MECHANIC)	Repair	1	\$280.00	200 280.00
20	RUBBER FOOTREST FRONT P/N: 26136 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$14.00	28 28.00
21	STAND SIDE P/N: 52334 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	17 38.00 X
22	STEERING CONE SET P/N: 41793 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$66.00	17 66.00 X
23	STOPPER 3 P/N: 44997 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	17 16.00 X
24	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1	\$45.00	35 45.00

SUB TOTAL
GST @ 7 %

\$2,647.00
\$185.29

*38917 *

bizSAFE₃



Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-14383
ISO 9001:2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
GRAND TOTAL (SGD)					\$2,832.29

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*38917 *

*bizSAFE*₃



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	288K
Vehicle Details	
Vehicle No.:	FBK1698Z
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Aug 2021
Vehicle Make:	YAMAHA
Vehicle Model:	YBR125
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	E3J2E016944
Chassis No.:	LBPKE1789E0028774
Maximum Power Output:	-
Open Market Value:	\$1,457.00
Original Registration Date:	13 Apr 2015
First Registration Date:	13 Apr 2015
Transfer Count:	1
Actual ARF Paid:	\$219.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Apr 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,800.00
COE Rebate Amount:	\$1,761.00
Total Rebate Amount:	\$1,761.00

The information contained herein is correct as at 11 Aug 2021

OK