



**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K  
MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

NO. : 38917

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO. : FBK1698Z  
MAKE/MODEL : YAM / YBR125

DATE : 10/08/2021  
CLAIM NO. : 11773  
POLICY NO. : MC/00914057  
FROM : RAYMOND

*not Authored  
den  
1/58 800  
3 days.  
11/8/21  
Take photo after repair*

(Page 1 of 3)

| S/N | Description                                                     | Action  | Qty  | Unit Price | Amount   |
|-----|-----------------------------------------------------------------|---------|------|------------|----------|
| 1   | AXLE WHEEL FRONT<br>P/N: 25363<br>- (REPORTED BY MECHANIC)      | REPLACE | 1.00 | \$23.00    | 23.00 X  |
| 2   | BRACKET FOOTREST LH<br>P/N: 25346<br>- (REPORTED BY MECHANIC)   | REPLACE | 1.00 | \$38.00    | 38.00    |
| 3   | BRACKET FOOTREST RH<br>P/N: 25345<br>- (REPORTED BY MECHANIC)   | REPLACE | 1.00 | \$38.00    | 38.00    |
| 4   | BRACKET UNDER FORK<br>P/N: 27458<br>- (REPORTED BY MECHANIC)    | REPLACE | 1.00 | \$180.00   | 180.00 X |
| 5   | COVER TAIL LH (RED)<br>P/N: 45418<br>- (REPORTED BY MECHANIC)   | REPLACE | 1.00 | \$90.00    | 90.00 X  |
| 6   | CROWN HANDLE<br>P/N: 28100<br>- (REPORTED BY MECHANIC)          | REPLACE | 1.00 | \$75.00    | 75.00 X  |
| 7   | FOOTREST FRONT<br>P/N: 50005<br>- (REPORTED BY MECHANIC)        | REPLACE | 1.00 | \$55.00    | 55.00    |
| 8   | FOOTREST REAR ASSY LH<br>P/N: 25348<br>- (REPORTED BY MECHANIC) | REPLACE | 1.00 | \$15.00    | 15.00    |
| 9   | FOOTREST REAR ASSY RH<br>P/N: 25347<br>- (REPORTED BY MECHANIC) | REPLACE | 1.00 | \$15.00    | 15.00    |

\*38917 \*

*L102*  
LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*bizSAFE<sub>3</sub>*



| S/N | Description                                                                           | Action         | Qty  | Unit Price | Amount |          |
|-----|---------------------------------------------------------------------------------------|----------------|------|------------|--------|----------|
| 10  | FORK FRONT ASSY LH<br>P/N: 45155<br>- (REPORTED BY MECHANIC)                          | REPLACE        | 1.00 | \$252.00   | 17     | 252.00 X |
| 11  | FORK FRONT ASSY RH<br>P/N: 45154<br>- (REPORTED BY MECHANIC)                          | REPLACE        | 1.00 | \$252.00   | 17     | 252.00 X |
| 12  | GASKET EXHAUST PIPE<br>P/N: 21453<br>- (REPORTED BY MECHANIC)                         | REPLACE        | 1.00 | \$5.00     | 721    | 5.00     |
| 13  | LABOUR<br>P/N: 06766<br>- LABOUR QUOTED FOR DISMANTLING AND<br>INSTALLATION OF PARTS. | Supply/Install | 8.00 | \$63.00    | 280    | 504.00   |
| 14  | LAMP SIGNAL REAR LH<br>P/N: 26504<br>- (REPORTED BY MECHANIC)                         | REPLACE        | 1.00 | \$28.00    | 17     | 28.00 X  |
| 15  | MUDGUARD FRONT (RED)<br>P/N: 45374<br>- (REPORTED BY MECHANIC)                        | REPLACE        | 1.00 | \$98.00    | 17     | 98.00 X  |
| 16  | PEDAL BRAKE<br>P/N: 44906<br>- (REPORTED BY MECHANIC)                                 | REPLACE        | 1.00 | \$88.00    | 2      | 88.00 X  |
| 17  | PEDAL GEAR (SHORT)<br>P/N: 45076<br>- (REPORTED BY MECHANIC)                          | REPLACE        | 1.00 | \$19.00    | 17     | 19.00 X  |
| 18  | PIPE EXHAUST ASSY<br>P/N: 68440<br>- (REPORTED BY MECHANIC)                           | REPLACE        | 1.00 | \$399.00   | 20/34  | 399.00   |
| 19  | REPAIR REAR BODY ALIGNMENT<br>- (REPORTED BY MECHANIC)                                | Repair         | 1.00 | \$280.00   | 200    | 280.00   |
| 20  | RUBBER FOOTREST FRONT<br>P/N: 26136<br>- (REPORTED BY MECHANIC)                       | REPLACE        | 2.00 | \$14.00    | 7011   | 28.00    |
| 21  | STAND SIDE<br>P/N: 52334<br>- (REPORTED BY MECHANIC)                                  | REPLACE        | 1.00 | \$38.00    | 17     | 38.00 X  |
| 22  | STEERING CONE SET<br>P/N: 41793<br>- (REPORTED BY MECHANIC)                           | REPLACE        | 1.00 | \$66.00    | 17     | 66.00 X  |
| 23  | STOPPER 3<br>P/N: 44997<br>- (REPORTED BY MECHANIC)                                   | REPLACE        | 1.00 | \$16.00    | 17     | 16.00 X  |
| 24  | TRANSPORT CHARGES<br>P/N: 07169<br>- BIKE TOWED BACK TO BHH                           |                | 1.00 | \$45.00    | 35     | 45.00    |

SUB TOTAL  
GST @ 7 %

\$2,647.00  
\$185.29

\*38917 \*

P-593  
102  
5337  
515

bizSAFE<sub>3</sub>



| <u>S/N</u>        | <u>Description</u> | <u>Action</u> | <u>Qty</u> | <u>Unit Price</u> | <u>Amount</u> |
|-------------------|--------------------|---------------|------------|-------------------|---------------|
| GRAND TOTAL (SGD) |                    |               |            |                   | \$2,832.29    |

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

\*38917 \*

bizSAFE<sub>3</sub>





**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## QUOTATION

Customer :

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

NO. : 38917

- Rev. 1

DATE : 10/08/2021  
CLAIM NO. : 11773  
POLICY NO. : MC/00914057

FROM : RAYMOND

VEHICLE NO. : FBK1698Z  
MAKE/MODEL : YAM / YBR125

(Page 1 of 2)

| S/N | Description                                                                           | Action         | Qty  | Unit Price                | Amount |
|-----|---------------------------------------------------------------------------------------|----------------|------|---------------------------|--------|
| 1   | BRACKET FOOTREST LH<br>P/N: 25346<br>- (REPORTED BY MECHANIC)                         | REPLACE        | 1.00 | \$38.00<br>Disc %: 10.00  | 34.20  |
| 2   | BRACKET FOOTREST RH<br>P/N: 25345<br>- (REPORTED BY MECHANIC)                         | REPLACE        | 1.00 | \$38.00<br>Disc %: 10.00  | 34.20  |
| 3   | FOOTREST FRONT<br>P/N: 50005<br>- (REPORTED BY MECHANIC)                              | REPLACE        | 1.00 | \$55.00<br>Disc %: 10.00  | 49.50  |
| 4   | FOOTREST REAR ASSY LH<br>P/N: 25348<br>- (REPORTED BY MECHANIC)                       | REPLACE        | 1.00 | \$15.00<br>Disc %: 10.00  | 13.50  |
| 5   | FOOTREST REAR ASSY RH<br>P/N: 25347<br>- (REPORTED BY MECHANIC)                       | REPLACE        | 1.00 | \$15.00<br>Disc %: 10.00  | 13.50  |
| 6   | GASKET EXHAUST PIPE<br>P/N: 21453<br>- (REPORTED BY MECHANIC)                         | REPLACE        | 1.00 | \$5.00<br>Disc %: 10.00   | 4.50   |
| 7   | LABOUR<br>P/N: 06766<br>- LABOUR QUOTED FOR DISMANTLING AND<br>INSTALLATION OF PARTS. | Supply/Install | 1.00 | \$280.00                  | 280.00 |
| 8   | PIPE EXHAUST ASSY<br>P/N: 68440<br>- (REPORTED BY MECHANIC)                           | REPLACE        | 1.00 | \$399.00<br>Disc %: 10.00 | 359.10 |
| 9   | REPAIR REAR BODY ALIGNMENT<br>- (REPORTED BY MECHANIC)                                | Repair         | 1.00 | \$200.00                  | 200.00 |

\*38917 \*

*bizSAFE<sub>3</sub>*



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg  
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0363  
ISO 9001:2015

| <u>S/N</u> | <u>Description</u>                                              | <u>Action</u> | <u>Qty</u> | <u>Unit Price</u>        | <u>Amount</u> |
|------------|-----------------------------------------------------------------|---------------|------------|--------------------------|---------------|
| 10         | RUBBER FOOTREST FRONT<br>P/N: 26136<br>- (REPORTED BY MECHANIC) | REPLACE       | 2.00       | \$14.00<br>Disc %: 10.00 | 25.20         |
| 11         | TRANSPORT CHARGES<br>P/N: 07169<br>- BIKE TOWED BACK TO BHH     |               | 1.00       | \$35.00                  | 35.00         |

|                          |                   |
|--------------------------|-------------------|
| SUB TOTAL                | \$1,048.70        |
| GST @ 7 %                | \$73.41           |
| <b>GRAND TOTAL (SGD)</b> | <b>\$1,122.11</b> |

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

**BAN HOCK HIN CO PTE LTD**



**RAYMOND**

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

\*38917 \*

*bizSAFE<sub>3</sub>*

