

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 13-Aug-21

INSURANCE: AXA

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA 9539D

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET <i>Dented</i>	1	\$ 1,330.70	\$1,330.70
INSULATOR, HOOD <i>crumpled / dt</i> <b>393.90</b>	1	\$ 557.34	\$557.34
INSULATOR CLIPS <i>Hex</i>	1	\$ 5.04	\$5.04
BONNET RUBBER <i>one</i>	1	\$ 49.70	\$49.70
BONNET CABLE <i>dt</i>	1	\$ 74.48	\$74.48
BONNET HINGE (RH) <i>dt</i>	1	\$ 80.78	\$80.78
BONNET HINGE (LH) <i>dt</i>	1	\$ 80.78	\$80.78
BONNET LOCK <i>dt / Dented</i>	1	\$ 185.64	\$185.64
CATCH, HOOD AUXILIARY HOOK <i>HW</i>	1	\$ 12.04	\$12.04
RADIATOR GRILLE <i>deformed</i> <b>438.00</b>	1	\$ 813.20	\$813.20
RADIATOR GRILLE EMBLEM <i>distorted / mainly cracked</i>	1	\$ 123.20	\$123.20
RADIATOR GRILLE EMBLEM LOWER GARNISH <i>distorted cut</i>	1	\$ 268.30	\$268.30
FRONT BUMPER COVER G5 <i>turn</i> <b>661.24</b>	1	\$ 1,322.48	\$1,322.48
LAMP ASSY, FOG, RH <i>crack</i> <b>696.40</b>	1	\$ 1,288.00	\$1,288.00
LAMP ASSY, FOG WIRE (RH) <i>HW</i>	1	\$ 133.20	\$133.20
FRONT BUMPER CLIPS <i>Hex</i>	1	\$ 30.80	\$30.80
FRONT BUMPER SIDE RETAINER RH <i>distorted</i>	1	\$ 107.80	\$107.80
FRONT LOWER CROSSMEMBER <i>dt</i> <b>320.60</b>	1	\$ 500.78	\$500.78
FRONT LOWER CROSSMEMBER GARNISH <i>crack / broken</i>	1	\$ 481.30	\$481.30
FRONT UNDER COVER <i>turn</i>	1	\$ 253.12	\$253.12
ENGINE UNDER COVER (RR) <i>distorted</i>	1	\$ 640.36	\$640.36
FRONT BUMPER TOP GARNISH <i>crack</i>	1	\$ 315.56	\$315.56
FRONT BUMPER SIDE GARNISH RH <i>broken</i>	1	\$ 216.90	\$216.90
COVER, FRONT BUMPER HOLE, RH <i>distorted</i>	1	\$ 39.73	\$39.73
REINFORCEMENT, FRONT BUMPER LOWER <i>crack</i>	1	\$ 330.54	\$330.54
BRACKET, FRONT BUMPER EXTENSION MOUNTING <i>HW</i>	1	\$ 154.56	\$154.56
SUPPORT FR BUMPER, RH <i>HW</i>	1	\$ 114.38	\$114.38
FRONT BUMPER CENTRE FRAME <i>HW</i>	1	\$ 331.66	\$331.66
BRACKET, FRONT BUMPER SIDE, RH <i>HW</i>	1	\$ 115.22	\$115.22
FRONT CHASSIS MEMBER SIDE COVER (RH) <i>turn / deformed</i>	1	\$ 196.50	\$196.50
UNIT ASSY, HEADLAMP, RH (LED) <i>broken</i> <b>2735.68</b>	1	\$ 4,837.00	\$4,837.00
HEADLAMP ECU <i>mainly broken</i> <b>682.60</b>	1	\$ 2,176.20	\$2,176.20
HEAD LAMP PANEL (RH) <i>replaced</i>	1	\$ 336.14	\$336.14
TOP PANEL CENTRE <i>dt / Dented</i> <b>364.98</b>	1	\$ 510.97	\$510.97
TOP PANEL SIDE RH <i>replaced</i>	1	\$ 204.26	\$204.26
BRACKET, HEADLAMP MOUNTING, RH <i>HW</i>	1	\$ 35.70	\$35.70
AIR CLEANER HOUSING ASSY <i>broken</i>	1	\$ 836.70	\$836.70
AIR CLEANER HOSE <i>dt / deformed</i>	1	\$ 86.97	\$86.97
AIR DUCT <i>broken</i>	1	\$ 181.16	\$181.16
INLET ASSY, AIR CLEANER <i>mainly broken</i>	1	\$ 278.88	\$278.88
AIR DUCT CENTRE <i>dt / mainly broken</i>	1	\$ 131.64	\$131.64
FENDER SUB-ASSY, FRONT RH <i>one</i> <b>945.30</b>	1	\$ 1,323.42	\$1,323.42
FRONT HOUSING ASSY RH <i>one</i>	1	\$ 1,323.36	\$1,323.36

Handwritten checkmarks and notes on the right side of the table, including a total of **245.00** next to the front lower crossmember garnish row.



FRONT WINDSCREEN ERP BRACKET <i>Huc</i>	SN	1	\$ 30.00	\$30.00	✓
FRONT TYRE (RH) <i>SN</i>	SN	1	\$ 302.40	\$302.40	X
<b>SUB TOTAL</b>				<b>\$332.40</b>	30.00
<b>Labour Charge</b>					
Panel Beating		1	\$ 2,200.00	\$2,200.00	1400/-
Spray Painting Charge		1	\$ 1,800.00	\$1,800.00	1000/-
Wiring Charge		1	\$ 100.00	\$100.00	30/-
Tuff Kote		1	\$ 100.00	\$100.00	40/-
Towing Charge		1	\$ 80.00	\$80.00	44
Four Wheel Alignment		1	\$ 120.00	\$120.00	60/-
Remove/Refix Undercarriage (Frt)		1	\$ 400.00	\$400.00	150/-
Re-set Frt ABS System		1	\$ 200.00	\$200.00	44
Remove/Refix Radiator		1	\$ 90.00	\$90.00	50/-
Remove/Refix Aircon & Refill Gas		1	\$ 130.00	\$130.00	80/-
Remove/Refix Fuse Box		1	\$ 120.00	\$120.00	50/-
Remove/Refix Front Windscreen Glass		1	\$ 120.00	\$120.00	80/-
Remove/Refix Engine		1	\$ 600.00	\$600.00	150/-
Remove/Refix Dashboard		1	\$ 350.00	\$350.00	44
Front Chassis Alignment Charge		1	\$ 220.00	\$220.00	150/-
Remove/Refix Steering Rack/Wheel/Dr Shaft		1	\$ 150.00	\$150.00	44
Remove/Refix Air Bag/Steering Wheel/Dashboard/Seat		1	\$ 550.00	\$550.00	180/-
Re-programme Air Bag & Safety Belt System		1	\$ 550.00	\$550.00	} 150/-
Diagnostic & Resetting To Erase Fault Code		1	\$ 550.00	\$550.00	
<b>TOTAL LABOUR</b>				<b>\$8,430.00</b>	3570.00
<b>ESTIMATE TOTAL</b>				<b>\$76,094.54</b>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

13/08/2011 @ 1000am  
 Not Actual 23  
 P/PA 20 days  
 Photo after repair  
 with damaged parts.

42524.76  
 Supp 7603.02  
 50,127.78  
 P/S 42,800/-

*Ryan*

2 KK Ando

*8*

Check part prices  
 Provide BV before  
 final quote

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 27-Aug-21

INSURANCE: AXA


MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA 9539D

DESCRIPTION	QTY	LIST PRICE	AMOUNT
COVER, FRONT BUMPER HOLE, LH <i>Srv</i>	1	\$ 39.73	\$39.73
FRONT CHASSIS MEMBER SIDE COVER (LH/RH) <i>replaced</i>	1	\$ 196.50	\$196.50
UNIT ASSY, HEADLAMP, LH(LED) <i>mainly broken</i>	1	\$ 4,837.00	\$4,837.00
HEAD LAMP PANEL (LH/RH) <i>1st (Dental)</i>	<del>2</del> 4	\$ 336.14	\$336.14
TOP PANEL SIDE LH/RH <i>1st (Dental)</i>	<del>2</del> 4	\$ 204.26	\$204.26
BRACE PANEL <i>1st</i>	<del>2</del> 1	\$ 105.28	\$105.28
COMPRESSOR ASSY, W/MOTOR <i>housing broken</i>	1	\$ 4,093.88	\$4,093.88
FRONT SAFETY BELT (LH/RH) <i>airbag</i>	<del>2</del> 2	\$ 1,173.20	\$1,173.20
REAR SAFETY BELT (LH/RH) <i>airbag</i>	<del>2</del> 2	\$ 1,173.20	\$1,173.20
WIPER TOP GARNISH <i>panel Dental</i>	1	\$ 935.65	\$935.65
CRANK SHAFT PULLY <i>broken</i>	1	\$853.49	\$853.49
<b>SUB TOTAL</b>			<b>\$13,948.33</b>
LESS 20% <i>25%</i>			<b>\$2,789.67</b>
<b>DISCOUNTED TOTAL</b>			<b>\$11,158.66</b>
<b>ESTIMATE TOTAL</b>			<b>\$11,158.66</b>

X  
 X 2735.68  
 ✓  
 ✓  
 ✓  
 ✓  
 ✓ 2887.80  
 ✓  
 ✓  
 ✓ 668.32  
 ✓

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Tyler*  
*2th Auto*  


10137.37  
 25% 7603.02