

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Vehicle No:
Make and model:

GBH 3610P

Toyota Hiace

2009

Qty Spare parts

List price

1	Tailgate	\$	1739.00	2,205.30	DD✓
1	Tailgate centre logo	\$	68.00	80.40	NECV
1	Tailgate lock	\$		288.40	} NDX
1	Tailgate lock catch	\$		40.10	
1	Tailgate lock actuator assy	\$		485.00	NSX
1	Tailgate weatherstrip	\$		395.46	✓ TN✓
1	Tailgate inner trim board	\$		281.90	NDX
1	Tailgate RH rubber stopper	\$		68.10	NNX
1	Rear bumper	\$	522.30	706.00	DD✓
1	Rear bumper RH side retainer	\$	55.00	78.91	} NECV
1	Rear bumper LH side retainer	\$	55.00	78.91	
4	Rear bumper lower brackets	\$		180.40	NDX
1	Rear bumper step bracket	\$		299.00	NDX
1	RH taillamp assy	\$		354.80	BA✓
1set	RH taillamp lock clips	\$		28.00	NECV
1	RH taillamp lower cover	\$		78.95	DD✓
1	RH taillamp lower cover retainer	\$		55.60	NECV
1	RH taillamp panel	\$	366.10	545.00	DD✓
1	End panel (outer)	\$		581.80	DD✓
1	End panel (inner)	\$		925.60	NDX
1	End RH side panel	\$	198.00	238.00	DD✓
1	End panel top moulding	\$		198.10	DD✓
1	Rear spare tyre carriage	\$		243.10	} NDX
1	Exhaust pipe	\$		980.20	
1	Exhaust pipe gasket	\$		61.10	NNX
1	RH side panel	\$	1389.00	1,718.45	DD✓
1	RH side panel inner lower air vent	\$		98.70	NDX
1	RH side panel inner trim board	\$		193.55	NDX

\$ 6006.16 11,490.43
-25% \$ 1501.54 2,872.61
\$ 4504.62 8,617.82

Special Nett price

Qty Spare parts

1 Tailgate "70km/h" sticker

\$

✓ 25.00 NECV✓

1	Tailgate "10pax" sticker	\$	25.00	NEC ✓
1	Tailgate windscreen glass sealant	\$	30.00	70.00 NEC ✓
1	Tailgate windscreen glass inner seal	\$	30.00	50.00 NEC ✓
1set	Tailgate inner trim board clips	\$	60.00	NNX
1set	Rear bumper clips	\$	30.00	70.00 NEC ✓
1set	Rear bumper reverse sensor	\$	200.00	280.00 SC ✓
1	RH side panel glass sealant (front)	\$	70.00	} NNX
1	RH side panel glass inner seal (front)	\$	50.00	
1	RH side panel glass sealant (rear)	\$	30.00	} NEC ✓
1	RH side panel glass inner seal (rear)	\$	30.00	
1set	RH side panel inner trim board clips	\$	60.00	NNX
1	End panel (outer) joint sealant	\$	30.00	60.00 NEC ✓
1	End panel (inner) joint sealant	\$		60.00 NNX
1	RH side panel joint sealant	\$		80.00 NNX
			430.00	

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels	\$	1000.00	1,800.00 ✓
Spray painting on affected panels	\$	600.00	1,200.00 ✓
Check wiring and lighting system	\$		80.00 NNX
Apply rust coating chemical on affected panels	\$		120.00 NNX
Remove, replace and reinstall tailgate windscreen glass and sealants to assist to repair	\$	120.00	200.00 ✓
Remove, reinstall and replace tailgate inner mechanism to new tailgate	\$	80.00	120.00 ✓
Remove, reinstall and replace rear trims, mat and garnish to assist repair	\$		150.00 NNX
Remove, reinstall and replace RH side panel glass (front) and sealants to assist repair	\$		200.00 NNX
Remove, reinstall and replace RH side panel glass (rear) and sealants to assist repair	\$	80.00	200.00
Remove, replace and adjust rear bumper reverse sensors to assist repair	\$	60.00	70.00 ✓

Survey & Resurvey on 17/8/2021

1430 hrs

TGrim Lin

Lump sum repair

Repair days 6

LS 5500/2

TGrim
Lin

20/9/2021

Total: \$ 13,837.82

1940.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Parts 4504.62

SN 430.00

Labour 1940.00

6874.62

@20% 1374.92

5499.70

LS 5500/2