



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI21008405/Bvf3n2 Date: 23/09/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKZ 4693G	Veh. Inspected	GBH 3610D
Policy No.		Coverage (\$)	0.00
Claim No.	C10011176/HA	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	11/08/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE 3.0DX	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KDH2010030952	Colour	SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	GST	5 mm
L/H Front Tyre	195 R15	GST	5 mm
R/H Rear Tyre	195 R15	GST	5 mm
L/H Rear Tyre	195 R15	GST	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/08/2021	Inspection Date	17/08/2021
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	