

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction Dep 6hcc ucl 11-8-2028 1A 5 2444616/8/21 2/3 @ 1300 confirmed with Joel

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

Page 1 / 2
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES708039

Date : 06/08/2021
Vehicle Num. : SJH 4965D
Make/Model : TOYOTA CAMRY
Chassis/Eng# :
Accident Date : 06/08/2021
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	REAR BUMPER		645.00 ✓
2.	2PCS	REAR BUMPER SIDE RETAINER - LONG	78.00	156.00 pc
3.	2PCS	REAR BUMPER SIDE RETAINER - SHORT	60.00	120.00 x
4.	1PC	N/S REAR FENDER INNER SHIELD		185.00 ✓
5.	1PC	N/S REAR WHEEL BEARING		223.00 ✓
6.	1PC	N/S REAR SHOCK ABSORBER		356.00 ✓
7.	1PC	N/S REAR KNUCKLE ARM		379.00 x
8.	1PC	N/S REAR LOWER ARM		325.00 x
9.	1PC	N/S REAR UPPER ARM		285.00 x
List Total S\$:				2,674.00
25.00% Discount S\$:				668.50
				2,005.50
SPECIAL NETT ITEMS :				
1.	1SET	REAR BUMPER CLIP		50.00 ✓
2.	1SET	N/S REAR FENDER INNER SHIELD CLIPS		50.00 ✓
3.	1PC	N/S REAR RIM		600.00 x
Special Nett Total S\$:				700.00
LABOUR :				
TO CHECK LIGHT SYSTEM AND WIRING			20	50.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

Page 2 / 2
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES708039

Date : 06/08/2021
Vehicle Num. : SJH 4965D
Make/Model : TOYOTA CAMRY
Chassis/Eng# :
Accident Date : 06/08/2021
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REMOVE/REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS	80	150.00
		COMPUTERIZED WHEEL ALIGNMENT	60	120.00
		TRANSFER TYRE AND BALANCING	12 x	50.00
		TRANSFER REVERSE SENSOR TO NEW BUMPER	40	60.00
		REPLACE REAR UNDERCARRIAGE	11 X	250.00
		LABOUR/PANEL BEATING	300	500.00
		SPRAY PAINTING	400	500.00
		Labour Total S\$:		1,680.00

E. & O.E. Total S\$: 4,385.50

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

With Amount
all
2/6 \$1300
3 days.
16/8/21
Zhanghua Allen Ng

2-828.1
25.2
P-621.82
S.V-200
L-880
1701.82
282
1361.