



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

Page 1 / 2
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES708039

Date : 06/08/2021
Vehicle Num. : SJH 4965D
Make/Model : TOYOTA CAMRY
Chassis/Eng#:
Accident Date : 06/08/2021
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1PC	REAR BUMPER		645.00
2.	2PCS	REAR BUMPER SIDE RETAINER - LONG	78.00	156.00
3.	2PCS	REAR BUMPER SIDE RETAINER - SHORT	60.00	120.00
4.	1PC	N/S REAR FENDER INNER SHIELD		185.00
5.	1PC	N/S REAR WHEEL BEARING		223.00
6.	1PC	N/S REAR SHOCK ABSORBER		356.00
7.	1PC	N/S REAR KNUCKLE ARM		379.00
8.	1PC	N/S REAR LOWER ARM		325.00
9.	1PC	N/S REAR UPPER ARM		285.00
List TotalS\$:				2,674.00
25.00% Discount S\$:				668.50
				2,005.50
SPECIAL NETT ITEMS :				
1.	1SET	REAR BUMPER CLIP		50.00
2.	1SET	N/S REAR FENDER INNER SHIELD CLIPS		50.00
3.	1PC	N/S REAR RIM		600.00
Special Nett Total S\$:				700.00
LABOUR :				
TO CHECK LIGHT SYSTEM AND WIRING			20	50.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Page 2 / 2

Estimate : ES708039

Date : 06/08/2021
Vehicle Num. : SJH 4965D
Make/Model : TOYOTA CAMRY
Chassis/Eng# :
Accident Date : 06/08/2021
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REMOVE/REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS	80	150.00
		COMPUTERIZED WHEEL ALIGNMENT	60	120.00
		TRANSFER TYRE AND BALANCING	12 x	50.00
		TRANSFER REVERSE SENSOR TO NEW BUMPER	40	60.00
		REPLACE REAR UNDERCARRIAGE	17 X	250.00
		LABOUR/PANEL BEATING	300	500.00
		SPRAY PAINTING	400	500.00
		Labour Total S\$:		1,680.00

E. & O.E. Total S\$: 4,385.50

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1 / Blk K) S(126226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

With Amount
N/A
2/5 #1300
3 days
16/8/21
Zohreh Althamir

2829.1
26.2
P-621.82
S.V-200
L-880
1701.82
282
1861.