



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM21008409/Ars3q2 Date: 28/10/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJB 6946C	Veh. Inspected	SJK 5037K
	Policy No.	GA562897	Coverage (\$)	0.00
	Claim No.	S1M03FCN	Excess (\$)	0.00
	Assign From		Assign Date	11/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA AXIO	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	NZE1416098584	Colour	GREY
	Odometer	214888 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/08/2021	Inspection Date	11/08/2021
	Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	