



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 10/08/2021

Estimated repair cost for vehicle no: SJK5037K TOYOTA AXIO 1.5X A

CHASSIS: NZE1416098584 (2008)

10/07/2021

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Distorted</i>	\$920.10	\$920.10 <i>545</i>
2	2	REAR BUMPER UPPER BRACKET <i>New</i>	\$79.20	\$158.40 <i>X</i>
3	2	REAR BUMPER SIDE RETAINER <i>New</i>	\$67.50	\$135.00 <i>✓</i>
4	2	REAR BUMPER BRACKET <i>Dented</i>	\$167.10	\$334.20 <i>112.80</i>
5	1	REAR BOOTLID <i>Dented</i>	\$1,131.50	\$1,131.50 <i>849.30</i>
6	2	REAR BOOTLID HINGE <i>Bent</i>	\$106.20	\$212.40 <i>✓</i>
7	1	REAR BOOTLID INNER TRIM <i>Deformed</i>	\$203.20	\$203.20 <i>✓</i>
8	1	REAR BOOTLID LOCK <i>Damaged</i>	\$390.80	\$390.80 <i>185.20</i>
9	1	REAR BOOTLID OUTER MOULDING <i>Cracked</i>	\$342.10	\$342.10 <i>✓</i>
10	2	REAR BOOTLID STOPPER <i>New</i>	\$18.50	\$37.00 <i>X</i>
11	2	REAR BOOTLID OUTER MOULDING LOGO <i>New</i>	\$88.60	\$88.60 <i>48</i>
12	2	REAR BOOTLID EMBELM AXIO <i>New</i>	\$74.30	\$784.30 <i>52</i>
13	1	REAR BOOTLID EMBELM X <i>New</i>	\$54.60	\$54.60 <i>45</i>
14	2	REAR TAILLAMP <i>Cracked</i>	\$702.60	\$1,405.20 <i>735</i>
15	2	REAR TAILLAMP INNER PANEL <i>Repair</i>	\$174.50	\$349.00 <i>X</i>
16	1	REAR END PANEL <i>Dented</i>	\$568.20	\$568.20 <i>✓</i>
17	1	REAR END PANEL TOP GARNISH <i>Dented</i>	\$275.30	\$275.30 <i>195</i>
18	1	REAR WEATHER STRIPE <i>cut</i>	\$288.80	\$288.80 <i>✓</i>
19	1	REAR SPARE TYRE COMPARTMENT PANEL <i>Repair</i>	\$904.50	\$904.50 <i>X</i>
20	1	REAR SPARE TYRE SPONGE <i>New</i>	\$218.60	\$218.60 <i>X</i>
21	1	REAR SPARE TYRE LOCK BOLT <i>New</i>	\$29.10	\$29.10 <i>X</i>
22	1	REAR SPARE TYRE TOP BOARD <i>Dented</i>	\$585.50	\$585.50 <i>265.90</i>
23	1	REAR EXHUAUST MUFFLER <i>Repair</i>	\$785.60	\$785.60 <i>X</i>
24	2	REAR EXHUAUST MUFFLER RUBBER MOUNTING <i>New</i>	\$32.40	\$64.80 <i>X</i>
25	2	REAR FENDER <i>Repair</i>	\$1,048.70	\$2,097.40 <i>X</i>
26	2	REAR FENDER INNER TRIM <i>form</i>	\$203.20	\$406.40 <i>✓</i>
27	2	REAR FENDER AIR VENT <i>New</i>	\$184.30	\$368.60 <i>✓</i>

5269.60

486.10

3952.20

3735.57

TOTAL :

\$13,139.20

LESS 25 %

\$3,284.80

SUB-TOTAL : \$9,854.40

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>New</i>	\$80.00	\$80.00 30
2	1	REAR END PANEL SEALANT <i>New</i>	\$80.00	\$80.00 60.
3	1	REAR END PANEL TOP GARNISH CLIPS <i>New</i>	\$60.00	\$60.00 10
4	2	REAR TAILLAMP CLIPS <i>New</i>	\$20.00	\$40.00 20
5	1	REAR NUMBER PLATE WITH CASING <i>cracked</i>	\$60.00	\$60.00 50.
6	1	REAR REVERSE CAMERA <i>Damaged</i>	\$80.00	\$80.00 380.

550

TOTAL: \$600.00

TOTAL PARTS: \$10,454.40

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & TRANSFER ALL REAR BOOTLID FITTING
- 6 LABOUR FOR REMOVE & RENEW REAR EXHUAUST MUFFLER , TO REPAIR STRAIGHTEN REAR EXHUAUST PIPE

~~\$2,400.00~~ 1200
~~\$1,800.00~~ 1200
~~\$60.00~~ 30
~~\$400.00~~ 80
~~\$300.00~~ 80
~~\$300.00~~ 80.

2800

7. To remove and refix rear camera.
- 8 To remove and refix upholstery

100 50
150 80.

Subtotal :- \$5,260.00

Total:- \$15,714.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

58K.

Adrian Lij

1/5 07 Days

total: 7302.20

2/5: 5.8K.