

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008413/T1BS3Q2
Date: 05/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLB4920R	Insured Vehicle No :	SLJ3683P
Date of Loss:	07/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003401

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB4920R		
Make & Model:	TOYOTA MARK X, 3.0 (A)	Engine No:	4GR0446827
Reg. Date:	23/10/2008 (Man. Year: 2008)	Chassis No:	GRX1203057652
Colour:	Silver	Odometer:	196066 km
Engine Capacity:	2499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,086.00	1,566.50	3,519.50	69.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,090.00	1,630.00	59.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,806.00	2,656.50	5,149.50	65.97
Approved Total (Overridden) (S\$)		2,100.00		

Nett Amount (S\$)	7,806.00	2,100.00	5,706.00	73.10
+ Car Rental (4.0 x S\$150.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,707.45		
Global Sum Settlement (S\$)		2,600.00		

INSPECTION

Date of Assignment: 11/08/2021

Date Inspected: 11/08/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Max Motors (HQ)
 1 Kaki Bukit Ave 6, #01-98 Autobay @ Kaki Bukit
 Singapore 417883

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Sep 2021)
Parts:	143	TOYOTA MARK X 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB4920R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,090.00 F	*- FL
2	1		*BOOTLID EMBLEM LOGO	Necessary	76.00 F	*76.00 FL
3	1		*BOOTLID EMBLEM -MARK X	Necessary	75.00 F	*75.00 FL
4	1		*BOOTLID EMBLEM -250S	Necessary	55.00 F	*55.00 FL
5	1		*REAR BUMPER	Deformed	920.00 F	*920.00 FL
6	2		*REAR BUMPER RETAINER	Necessary (1 PCS ONLY)	120.00 F	*60.00 FL
7	2		*REAR BUMPER TOW COVER	Cut (1 PCS ONLY)	118.00 F	*64.00 FL
8	1		*REAR TAILLAMP RH	Not Necessary	532.00 F	*- FL
9	1		*REAR TAILLAMP LH	Cut	532.00 F	*532.00 FL
10	1		*REAR BUMPER SPONGE	Not Necessary	139.00 F	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Not Necessary	329.00 F	*- FL
12	1		*END PANEL	Not Necessary	550.00 F	*- FL
13	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
14	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS
15	1		*SET REAR REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,086.00	2,012.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	445.50
Total Parts (S\$)	5,086.00	1,566.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	80.00	30.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	30.00
3	REMOVE AND STRAIGHTEN REAR EXHAUST	New	150.00	0.00
4	REMOVE ,REFIT REAR LINING ,TRIM AND GARNISH	New	150.00	0.00
5	TRANSFER PARTS FROM OLD BOOTLID TO NEW	New	200.00	0.00
6	PANEL BEATING ON AFFECTED AREAS AND RENEW PARTS	New	1,000.00	500.00
7	SPRAY PAINTING ON AFFECTED PANEL	New	900.00	500.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	30.00
Gross Labour Cost (S\$)			2,720.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >