



MAX MOTORS

All Kinds Of Motors Work

MAX MOTORS

1 Kaki Bukit Ave 6, #01-98
Autobay@ Kaki Bukit Blk E,
Singapore 417883
Reg. No : 53196198B

Vehicle No : ^{Singapore} SLB 4920R

Vehicle Model : MARK X

Accident Date : 08 July 2021

Reg Date : Nil

COE EXP Date : Nil

Date : 10 August 2021

Chassis : Nil

TP INS. INDIA INS

ESTIMATE

S/N	PARTS	QTY	UNIT PRICE	LIST PRICE
1	BOOTLID	1	\$ 1,090.00	\$ Rp 1,090.00
2	BOOTLID EMBLEM LOGO	1	\$ 76.00	\$ acc 76.00
3	BOOTLID EMBLEM - MARK X	1	\$ 75.00	\$ he 75.00
4	BOOTLID EMBLEM - 250S	1	\$ 55.00	\$ he 55.00
5	REAR BUMPER	1	\$ 920.00	\$ de 920.00
6	REAR BUMPER RETAINER	1/2	\$ 120.00	\$ re 60 120.00
7	REAR BUMPER TOW COVER	1/2	\$ 118.00	\$ out 64 118.00
8	REAR TAILLAMP LH	1	\$ 532.00	\$ cut 532.00
9	REAR TAILLAMP RH	1	\$ 532.00	\$ X nn 532.00
10	REAR BUMPER SPONG	1	\$ 139.00	\$ X nn 139.00
11	REAR BUMPER REINFORCEMENT	1	\$ 329.00	\$ X nn 329.00
12	END PANEL	1	\$ 550.00	\$ X nn 550.00

C/F \$ 4,536.00

1782
25% - 1336.50

B/F \$ 4,536.00

VEHICLE NO : SLB 4920R
The Repairer of the following:
• To reserve before the repair work
• To display damaged parts during repair
• Parts are supplied to the customer
• The repairer is not responsible for the loss
• The repairer is not responsible for the loss

PREMIUM QUALITY

ESTD



1984

MAX MOTORS

All Kinds Of Motors Work

Singapore

Special Netts

\$ MAX MOTORS

1 Kaki Bukit Ave 6 #01-98

\$ 1,134.00

\$ 3,402.00

Reg. No. 53196198B

Less 25%

S/N	PARTS	QTY	UNIT PRICE	LIST PRICE
13	REAR BUMPER CLIP	1 SET	\$ 30.00	\$ 30.00 30.00
14	JOINT SEALANT	1	\$ 120.00	\$ 120.00 120.00
15	REAR REVERSE SENSOR	1 SET	\$ 400.00	\$ 400.00 400.00

\$ 550.00 230

C/F \$ 3,952.00

VEHICLE NO : SLB 4920R

B/F \$ 3,952.00

Labour Charge

16	CHECK REAR WIRING AND LIGHTNING SYSTEM	\$ 80.00	\$ 30 80.00
17	REMOVE AND RENEW REAR REVERSE SENSOR	\$ 120.00	\$ 30 120.00
18	REMOVE AND STRAIGHTEN REAR EXHAUST	\$ 150.00	\$ 150.00 150.00
19	REMOVE, REFIT REAR LINING, TRIM AND GANRISH	\$ 150.00	\$ 150.00 150.00
20	TRANSFER PARTS FROM OLD BOOTLID TO NEW	\$ 200.00	\$ 200.00 200.00
21	PANEL BEATING ON AFFECTED AREAS AND RENEW PARTS	\$ 1,000.00	\$ 500 1,000.00
22	SPRAY PAINTING ON AFFECTDED PANEL	\$ 900.00	\$ 500 900.00
23	APPLY ANTI RUST ON AFFECTED AREAS	\$ 120.00	\$ 30. 120.00

1090

\$ 2,720.00 2656.50

4/5 \$ 2100

4days

Tau fikh 97495748
 WP 11/8/21 23pm
 C/S Resurvey after repair
 tau.fikh@lkkauto.com
 04days

TOTAL AMOUNT \$

6,672.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: