

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 1688C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	HEADLAMP (LED) R/L @\$1775.00	N/S CRACKED / O/S NOT NECESSARY	3,550.00	1,775.00
8	FRT BUMPER CLIP @\$3.60	NECESSARY	28.80	28.80
2	FRT BUMPER SUPPORT R/L @\$39.30	N/S BROKEN / CRACKED / O/S NOT NECESSARY	78.60	39.30
2	FRT BUMPER RETAINER R/L @\$58.00	CRACKED / NECESSARY	116.00	116.00
1	FRT BUMPER REINFORCEMENT	DENTED	548.20	548.20
1	FRT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	682.00	-
1	FRT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	172.30	-
9	FRT SUPPORT PANEL TOP GARNISH CLIP @\$3.20	NECESSARY	28.80	28.80
1	FRT SUPPORT PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRT FENDER R/L (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-1,040.94	-507.22
			4,163.76	2,028.88
	SPECIAL NETT ITEMS			
1	FRT BUMPER (MUGEN, W/GRILLE) (SN)	DENTED / CRACKED	1,200.00	700.00
			1,200.00	700.00
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL SYSTEM AND CALIBRATE / FOCUS HEADLAMP.		60.00	30.00
	TO REMOVE, REINSTALL RADIATOR, A/C CONDENSER AND PIPINGS FOR NECESSARY REPAIRS. (INCLUDE PRESSURE TEST COOLING SYSTEM AND VACUUM, RECHARGE A/C GAS).	NOT NECESSARY	180.00	-
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRT SUPPORT PANEL ASSY, FRT SUPPORT PANEL AND FRT FENDER R/L.		800.00	400.00

Report Ref No. CS3/INC19015092/Gvce2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		1,000.00	500.00
			2,040.00	930.00
	GRAND TOTAL		7,403.76	3,658.88

RECOMMENDED COST OF LUMP SUM REPAIRS		2,900.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/INC19015092/Gvce2-1

XING GUO QIANG

ANG BRYAN TANI

Automotive Assessor / Investigator

M.MATAI, AMSAE-A
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.