

TETUM

CC4/A1G21008425/Bea3

Doher

From: _____ Date: 12/8/2021

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMN 35882

at Workshop m/s MS cars

of 8 Kaki Bt Ave 4 Premier #01-07

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

N/S	O/S

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMV 3588Z Yr Regn: 2/8/2019
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Mazda Axela 1.5 C.C. 1496
Colour: Red A/C: Insured / Std / NI / NA
Sp/Reading: 121987 T/Radio: Insured / Std / NI / NA
Eng/No: 553036420
C/No: BMLFP107462
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In Order / Jammed / Leaked / Burnt or _____
Brake: In Order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 205/60/16
R: 205/60/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Tourador*

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 09/8/2021

Survey held at MS Cars

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 5 mm

L/Bal. 5 mm

D.O.I. 12/8/2021

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	5,150.00
	Recommended COR IS LS [REDACTED] TGLin Wm 22/9/2021
	MV 83,000/r PV 33,787/v NV 49,213/r
	TGLin Wm 21/9/2021

☐ : Prelim. Report
☐ : Final Report

13

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.B. (%)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

	: Site Insp (\$	
	: Interview (\$	
	: Tech. Invs (\$	
	: Weekend (\$	

Survey Fee:

Transportation:

) Photos

	Others
--	--------

TOTAL

SJE : _____
Date of Survey : _____
Contacts : _____

Vehicle Nos : SMN 35ff 2
Model : _____
Year : _____

2019

ITEM	DESCRIPTION	Qty	
1	Rear boot BT✓	1	\$1,176.00✓
2	Rear boot lock JMV✓	1	\$194.00✓
3	Rear boot w/strip 172.00 TNV✓	1	\$172.00✓
4	Rear boot logo 52.00	1	\$75.80
5	Rear boot (SKYACTIM) 58.30 NEC✓	1	\$64.30
6	Rear boot embk lem AXELA 46.50	1	\$78.60
7	Rear bumper BR✓	1	\$974.80✓
8	Rear bumper retainer L+R NEC✓	2	\$84.20✓
9	Rear bumper reflector L+R BR✓	2	\$176.40✓
10	Rear bumper number plate lamp L+R NDX	2	\$148.20
11	Rear bumper reinforcement 541.70 DDV✓	1	\$782.10
12	Rear bumper clip 30.00 NEC✓	10	\$50.00
13	Rear end panel 623.70 DDV✓	1	\$747.00
14	Rear end panel top garnish 125.00 BR✓	1	\$239.00
15	Rear end panel clip L+R NEC✓	2	\$10.00✓
16	Rear end panel sensor 253.00 SC✓	1	\$275.00✓
17	Towing cover 34.00 1✓ nec BR	2	\$155.60
18	Tail light R/L BR✓	2	\$756.60✓
19	Rear boot light R/L 2✓ BR✓	2	\$682.80
20	Rear end panel top garnish RPT X I	1	\$186.40
21	Rear end panel top garnish clip NEC✓	2	\$15.00✓
Parts Sub Total			\$7,043.80
@ 20% Discount 20%			\$1,408.76
Parts Total			\$5,635.04
Special Nett			
1	Reverse sensor 200.00 Original SC✓	2	\$560.00
2	Rear number plate NDX	1	\$50.00
3	Rear end panel sealant NNX	1	\$80.00
200.00 Special Nett Total:			\$690.00
Labour			
1	To R & R accident damage parts, to cut/weld, knock and realign accident affected area	1	\$1,200.00
2	To putty and respray accident affected area. 800.00✓	1	\$1,000.00

3	To rust proof accident affected area	1	\$60.00
4	To R & R rear boot mechanism	1	\$100.00
5	To R & R upholstery, garnish and attachment parts	1	\$100.00
6	To R & R reverse sensor and check function	1	\$80.00
	1440.00	Labour Total	\$2,540.00
		Parts Total	\$5,635.04
		Special Nett Total:	\$690.00
		Labour Total	\$2,540.00
		Grand Total	\$8,865.04

Survey
12/8/2021

1230 hrs

TGim
hr

Resurvey

13/8/2021

1330 hrs

TGim hr

Lum & Sun repair
Repair days 5

TGim hr

22/9/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: