

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	STRIDES AUTOMOTIVE SERVICES PTE LTD			CS/SMR21008434/Eqf3n2	
	60 WOODLANDS E4SINGAPORE 75	NDUSTRIAL PARK 57705	Date	26/04/2022	
			Code	: SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 4889R	Veh. Inspected	SMK 457D	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	TAX/07/21/2052	Excess (\$)	0.00	
	Assign From	HUA YEN	Assign Date	12/08/2021	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ E200	c.c	1796	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	WDD2120482A161886	Colour	SILVER	
	Odometer	111434 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	245/40 R18	YOKOHAMA	5 mm	
	L/H Front Tyre	245/40 R18	YOKOHAMA	5 mm	
	R/H Rear Tyre	245/40 R18	YOKOHAMA	5 mm	
	L/H Rear Tyre	245/40 R18	YOKOHAMA	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	21/07/2021	Inspection Date	12/08/2021	
	Survey held at	AUTO INSURE PTE LTD			
		6 MARSILING LANE S739145			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			