

Auto Insure Pte. Ltd.

6 Marsiling Lane

Singapore (739145)

E: claims01@autoinsure.com.sg

W: www.autoinsure.com.sg T: 3157 2626 F: 6368 0081

GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: SMK457D (SIEW)

Your Ref: SHC4889R

BY EMAIL ONLY

(claims01@autoinsure.com.sg)

Date:

3-Aug-21

ATTENTION: MOTOR CLAIMS DEPT

Auto & General Southeast Asia (SEA)

190 Clemenceau Ave,

#03-01 Singapore Shopping Centre,

Singapore 239924

Assessed Vehicle No

: SMK457D

Car Make and Model

: MERCEDES BENZ E200 CGI A

Date of Accident

: 21-Jul-21

Date of Assessment

: 3-Aug-21

We have carried out a physical assessment of SMK457D at our workshop Auto Insure Pte Ltd sustained damages to the LH SIDE portion of the vehicle.

4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the LH SIDE portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount

L/S

Adjusted Amount

: \$ 5,600.00

Est. Repair Days

5

Pursuant to your instruction, we have NOT AUTHORIZED repair.

The assessment was conducted on a "WITHOUT PREJUDICE" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the adressee solely in relation to the loss of occurrence in which the assessd vehicle is involved.

No liability or responsibilty whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SMK457D Your Ref: SHC4889R

s/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
1 2 3 4 5	1 1 1 1	PARTS REPLACEMENT - LIST ITEMS FRONT DOOR LH / DD FRONT DOOR LOCK LH FRONT DOOR INNER WEATHERSTRIP LH / D' FRONT DOOR LOWER WEATHERSTRIP LH ROCKER PANEL SKIRTING LH X R REAR DOOR LH X D	s BR	\$ (998 - 2,597.95 \$ 528.28 \$ 241 - 372.03 \$ 182 - 235.72 REPAINT REPAIR
		2421	SUB TOTAL	
		1	LESS 10%	\$ 373.40
		-10%	TOTAL AMOUNT	\$ 3,360.58

Our Ref: SMK457D Your Ref: SHC4889R

s/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP		
1	1	FRONT DOOR SEALANT LH / N	†	\$	80.00	
2	1	ROCKER PANEL SKIRTING LH 3M TAPE	NC	\$	<i>JO</i> - 50.00	
			SUB TOTAL	\$	130.00	
		(B	TOTAL PARTS COST	\$	3,490.58	

Our Ref: SMK457D Your Ref: SHC4889R

S/NO	DESCRIPTION	EST. BY WORKSHOP			
	LABOUR & PAINTV	VORK			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS BEAT & RESHAPE THE AFFECTED AREAS AND I AND COMPONE	REPLACED THE DAMAGED PARTS	\$	250	500.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACC	\$	30	80.08	
3	TO REMOVE & REFIT FRONT DO	\$	50	200.00	
4	TO RESPRAY AND SUPPLY EXPANDABLE ITEM	\$	600	800.00	
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS			30	50.00
6	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)			10	40.00
7	TO VACUUM, WAXING & CLEAN			X	60.00
8	TO PERFORM WATER SEEPAGE TEST	\$	X	50.00	
L	070	TOTAL BEFORE GST	\$	5	,270.58
	9/0	GST 7%	\$	\$ 368	
=3208.90 TOTAL (PARTS		TOTAL (PARTS & LABOUR):	\$	5	,639.52

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$5,600.00 for lump sum with the third

party insurance. Yours Faithfully,

Jason Heng Claims Director

-IS-2567.12 Steve (LKK) WIL AL

= 2558

11/8/11, 2-37

LKK Auto Consultants hence notify
the Benzirer of the following:

3 Gy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: