



泛舟修理汽車私人有限公司
PUAN CHEW MOTOR WORK PTE LTD

BLK K, PANDAN LOOP INDUSTRIAL ESTATE #01-12 SINGAPORE 128230

TEL: 6773 0073 FAX: 6773 0928

GST REGN NO: 19-8700614-G

Date: 11.8.2021

First Capital Insurance Ltd
36, Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

Dear Sir / Mdm,

TP CLAIM AGAINST YOUR INSURED SHF 296 L

OUR CLIENT'S : MISS LEE CHER LING
VEH. REG. NO : SCF 954 E
MODEL : TOYOTA COROLLA ALTIS
ACCIDENT DATE : 10.8.2021

Below are the estimate for SCF 954 E

- 1 1 rear n/s door *bt*
2 1 rear n/s fender *refer bt*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1623
1520
3143
20%
2514.40
45-2,500

\$ 1,248.50 1079
\$ 1,149.90 1085
\$ 2,398.40 2164
Less 25%: \$ 599.60 541
Total: \$ 1,798.80 1623

Labour Charges

- 3 To transfer rear n/s door glass window, rear n/s door harness, rear n/s door lock, rear n/s door inner board trim.
4 To remove and replace damaged parts, knock out, cut and weld body panel parts where necessary, straighten and reshape, reposition and realign replacement parts to the original position.
5 Spray painting of accident sections.

\$ 180.00 120
1520
\$ 980.00 700
\$ 880.00 700
Grand Total: \$ 3,838.80

PRICES QUOTED EXCLUDE GST CHARGES

PERSON TO CONTACT MR. LIM AT 97938181 / 96338181

Pascal
Hp 900/10068
6 days
4s
12/08/21
1450
Reg after repair