

BIFROST AUTO PTE LTD
8 KAKI BUKIT AVE 4 #01-49
SINGAPORE 415875
TEL: 64524457 FAX: 64524584
ATT: IKHWAN HP 93290237

Estimate for ^{GB6}GBH2882H (Toyota Hiace)

1 *FRONT BONNET	727.10	\$859.90	DD✓
1 *FRONT LOGO		✓ \$56.40	NEC✓
2 *FRONT BONNET HINGE		\$137.20	NDX✓
1 *FRONT BONNET LOCK	77.00	\$97.00	JMV✓
1 *FRONT GRILLE ASSY	855.20	\$1,400.00	BR✓
1 *FRONT TOP PANEL		✓ \$352.40	DD✓
2 *HEAD LAMP PANEL		✓ \$307.80	DD✓
2 *HEAD LAMP RH BR✓ LH ? BR✓		✓ \$1,596.00	? BR✓
1 *FRONT BUMPER		✓ \$627.70	BR✓
1 *FRONT BUMPER FOG LAMP COVER		✓ \$94.40	MIS✓
1 *FRONT BUMPER TOP BEAM		✓ \$86.30	? DD✓
2 *FRONT BUMPER BRACKET		✓ \$116.40	NEC✓
2 *FRONT BUMPER EXTENSION BRACKET	185.00	\$350.00	? BT✓
1 *FRONT BUMPER REINFORCEMENT		✓ \$261.40	? PD✓
1 *FRONT BUMPER AIR GRILLE		✓ \$98.20	BR✓
2 *FRONT BUMPER SIDE RETAINER	191.30	\$313.60	NEC✓
2 *FRONT CORNER PANEL RH	268.70	\$730.40	BT✓
1 *FRONT WING MIRROR		\$328.20	NDX
1 *FRONT DOOR LH	1248.90	\$1,623.20	DD✓
1 *FRONT DOOR GLASS		\$487.20	NDX
1 *FRONT DOOR GLASS OUTER MLDG		✓ \$126.40	NEC✓
1 *FRONT DOOR CHECKER		✓ \$166.10	BT✓
2 *FRONT DOOR HINGE		✓ \$171.20	BT✓
1 *FRONT DOOR RUBBER	156.00	\$254.30	TN✓
1 *FRONT DOOR BOARD	544.00	\$852.40	? BR✓
1 *FRONT DOOR GLASS RUN CHANNEL		✓ \$281.90	NEC✓
1 *FRONT DOOR GLASS REGULATOR MOTOR		\$496.50	} NDX
1 *FRONT DOOR GLASS REGULATOR		\$332.80	
1 *FRONT STEP GARNISH		✓ \$176.70	BR✓
1 *FRONT STEP PANEL	361.80	\$445.80	BT✓
1 *FRONT DOOR INNER LOCK		\$481.70	JMV✓
1 *FRONT W/S GLASS		\$1,450.00	NDX
1 *FRONT W/S GLASS MOULDING		\$87.50	NNX
1 *FRONT DOOR PILLAR	606.00	\$851.20	BT✓
1 *FRONT DOOR OUTER HANDLE		\$102.30	NDX
1 *ROCKER PANEL RH		\$989.00	NDX
1 *AIR CLEANER ASSY		✓ \$687.50	? BR✓
1 *FRONT TOP ARM LH		✓ \$481.00	BR✓
1 *FRONT WHEEL BEARING LH RH		✓ \$258.60	} JMV✓
1 *FRONT WHEEL BEARING HUB LH RH		✓ \$481.20	
1 *FRONT SHOCK ABSORBER LH RH	169.75	\$315.60	BT✓
1 *FRONT KNUCKLE ARM LH RH	349.00	\$516.80	BT✓

2017

BIFROST AUTO PTE LTD
8 KAKI BUKIT AVE 4 #01-49
SINGAPORE 415875
TEL: 64524457 FAX: 64524584
ATT: IKHWAN HP 93290237

Estimate for ^{GBE}GBH2882H (Toyota Hiace)

1 *FRONT LOWER ARM LH		\$435.50	
1 *STEERING LOCK & PINION		\$2,121.30	? NDX
1 *FRONT STABILIZER BAR LINK		\$152.40	? NDX
1 *FRONT BALL JOINT LH		\$173.00	
1 *AIRCOND CONDENSER		\$247.60	? BT✓
2 *FAN COWLING	550.47	\$2,350.00	? BR✓
1 AIR FILTER		\$186.00	BR✓
1 *FAN BLADE		\$89.40	? NDX
1 *FAN MOTOR		\$457.30	? NDX
1 FRONT DOOR PILLAR		\$392.70	RPTX
1 *FRONT DOOR WING MIRROR		\$427.10	NDX
1 *RADIATOR ASSY		\$1,758.00	? BT✓
1 DASHBOARD ASSY		\$1,890.00	? NDX
1 AIR BOX	300.00	\$680.00	BR✓
1 AIR INTAKE HOSE		\$780.00	RPTX
1 AIR INTAKE		\$1,569.00	? NDX
1 AIRCON PIPE		\$280.00	? BT✓
1 BRAKE MASTER PUMP	546.70	\$984.00	? leaking✓
1 BRAKE BOOSTER PUMP	1664.00	\$1,715.00	DD✓
1 BRAKE BOOSTER PIPE		\$298.00	NDX
1 MAP SENSOR		\$523.00	? NDX
1 DOOR HARNESS		\$894.00	? NDX
1 INTERCOOLER		\$1,988.00	DD✓
1 FRONT SEAT BELT LH / RH	Jm✓ 1745.20	\$1,862.00	JM✓
2 FRONT SEAT BELT BUCKET LH / RH	586.20 pc	\$582.00	NDX
2 FRONT AIRBAG LH / RH		\$3,132.00	NDX
1 FRONT HORN		\$280.00	NDX
1 FRONT HORN AIRBAG		\$1,099.00	NDX
	20,514.22	\$47,276.50	
Less 20%	4,102.84	\$11,819.13	
	16,411.38	\$35,457.38	
*FRONT BUMPER CLIP	30.00	\$50.00	NEC✓
*FRONT DOOR TRIM RH CLIP	30.00	\$50.00	NEC✓
FRONT BUMPER CLIPS	30.00	\$50.00	NEC✓
*REAR TYRE LH		\$150.00	NDX
FRONT BUMPER LIP	800.00	\$1,800.00	BR✓
FRONT DOOR VISOR		\$250.00	NDX
SOUNDPROOF SPONGE	100.00	\$250.00	? NEC✓
FRONT BONNET EMBLEM AFTERMARKET		\$250.00	NDX
FRONT DOOR SPEAKER RH		\$180.00	? NDX
FRONT GRILLE AFTERMARKET	855.20	\$1,500.00	BR✓

BIFROST AUTO PTE LTD
8 KAKI BUKIT AVE 4 #01-49
SINGAPORE 415875
TEL: 64524457 FAX: 64524584
ATT: IKHWAN HP 93290237

Estimate for ^{GBE} GBH2882H (Toyota Hiace)

*REAR RIM LH		\$300.00 NDX
*FRONT TYRE RH		\$150.00 NDX
*FRONT RIM RH	local repair 100.00	\$300.00 CUT ✓
*FRONT W/S GLASS SEALANT		\$80.00 NNX
*TO CUT FRONT DOOR COMPANY NAME & STICKER	30.00	\$50.00 NEC ✓
*FRONT NUMBER PLATE	25.00	\$50.00 MIS ✓
*FRONT WINDSCREEN SEALANT		\$100.00 NNX
ERP BRACKET		\$150.00 NNX
	<u>2000.20</u>	<u>\$5,810.00</u>
TO CHECKING WIRING	50.00	\$200.00 ✓ NEC ✓
APPLY ANTI RUST CHEMICAL	100.00	\$250.00 NEC ✓
REMOVE AND REFIX FRONT WINDSCREEN		\$150.00 NNX
REMOVE AND REFIX AIRCON CONDENSER & REFILL AIRCON GAS	120.00	\$150.00 ? ✓
REMOVE AND REFIX DASHBOARD & CHECK WIRING		\$350.00 NNX
REMOVE AND REFIX FRONT CUSHION SEAT		\$150.00 NNX
REMOVE AND REFIX RADIATOR	50.00	\$80.00 ? ✓
REMOVE AND REFIX FRONT UNDERCARRIAGE, SUSPENSION ETC	200.00	\$450.00 ? ✓
CHECK 4 WHEEL ALIGNMENT	60.00	\$120.00 NEC ✓
LABOUR CHARGE FOR KNOCK DENTS ON DAMAGE PORTION RENEW		\$3,500.00 ✓
THE ABOVE MENTIONED PARTS	1200.00	\$3,500.00 ✓
TO SPRAY PAINTING AND ETC	1000.00	\$3,000.00 ✓
LABOUR FOR INSTALLING SOUND PROOD ON THE DAMAGE PORTION		—
	<u>1880.00</u>	<u>\$8,400.00</u>

Total

\$49,667.38

Survey 11/8/2021 15:35 hrs Tglim M
 Resurvey 12/8/2021 16:30 hrs Tglim M
 Lump Sum repair Repair days 16

Parts 16,411.38
 SN 2,000.20
 Labour 1880.00
20,291.58
4058.32
16,233.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LS 16,250/2

Tglim M
 25/8/2021