



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

W BASA320X0D334570

LKK

TPA19.
Hui Zhen.

DATE: 13/08/2021 OUR REF: UAPL1477
REPAIR ESTIMATE YOUR BMW 520I NO: **SMH3385Z**
1 FRONT BUMPER FACE *Deland*
1 FRONT R/H BUMPER SIDE RETAINER *new*
1 FRONT R/H BUMPER FOG LAMP COVER GARNISH *at*
1 FRONT R/H HEADLAMP ASSY *rule*
1 FRONT R/H HEADLAMP LOWER GARNISH *new*
1 FRONT R/H FENDER ASSY *Peris*
1 FRONT R/H FENDER INNER SHIELD *torn*
10 FRONT R/H FENDER INNER SHIELD CLIPS *new*

LESS 10%.....

\$	1,943.00	1515
\$	89.00 x	95
\$	278.00	
\$	4,856.00	3200.
\$	133.40 x	
\$	1,350.00 x	
\$	242.00	
\$	50.00	30
\$	8,941.40	
\$	894.14	5082
\$	<u>8,047.26</u>	4573.80.

LABOUR CHARGES:-

TO DISM/REWIRE FRONT DAMAGED PORTION

TO RESET ECU AFTER REPAIR

TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS

TO SEND VEHICLE FOR WHEEL ALIGHTMENT

TO PUTTY AND RESPRAY DAMAGED PORTION

TO SPARY UNDERCOATING IN REPAIR

\$	100.00	30
\$	120.00 x	
\$	900.00	400
\$	120.00	x
\$	900.00	400
\$	80.00	30
\$	<u>10,267.26</u>	860

total: 54338

4/5: 4350. ✓

04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: