

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0645/2021/KS
DATE : 11-Aug-21
WIP : 39079

Veron

~~\$46535.76~~

Litort Repair: \$431k

16 days.

sls.

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR KHAW BAN LEONG VICTOR
ADDRESS : 25 HAZEL PARK TERRACE
#19-03
SINGAPORE 678948
TELEPHONE : HP +65 82233928
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700049423-03
VEHICLE NO : SLT 8328 E
MODEL CODE : AUDI A3 1.0 TFSI 8V
MODEL YEAR : A3 SEDAN 1.0 TFSI
ENGINE NO : CHZ 512265
CHASSIS NO : WAUZZZ8V5J1012901
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
DATE OF ACCIDENT : 7-Aug-21
PLACE OF LOCATION : SOUTH BUONA VISTA ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SLT 8328 E.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING, ATD	S/N \$ 480.00	X ☒ <i>H/S.</i>
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	350.00 250. ✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$ 1,400.00	X ☒ <i>H/S.</i>
4	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	350.00 280 ✓
5	TO TOW BACK THE VEHICLE FROM ACCIDENT SCNE	S/N \$ 280.00	X
6	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	S/N \$ 2,400.00	2 ✓
SUBTOTAL LABOUR CHARGES		: \$ 5,260.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SLT 8328 E.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL DASHBOARD ASSY TO FACILITATE RENEW OF LHS A-PILLAR INNER PLATE	S/N \$ 2,400.00	X.
8	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. TO CUT OUT AND WELD LHS A-PILLAR INNER PLATE. TO REPAIR LHS FRONT FENDER TOP SUPPORT. LHS SILL PANEL. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED.	\$ 7,000.00	1500 ✓
9	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS FRONT FENDER TOP SUPPORT, LHS UPPER A-PILLAR, LHS A-PILLAR INNER PLATE, LHS SILL PANEL AND LHS WING MIRROR COVER.	\$ 6,000.00	1850 ✓ 3 x 550 = 1650 Fender top Suppl = 20 1850
10	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	✓ ✓
11	TO CARRY OUT PRE/ POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192 ✓
TOTAL LABOUR CHARGES		\$ 21,564.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8328 E.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,987.00	✓ 1589.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 187.00	+
3	FRONT BUMPER GUIDE SECTION LH <i>Damaged</i>	1	\$ 39.00	✓ 30.48
4	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 160.00	x
5	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE <i>? cut</i>	1	\$ 536.00	✓ x
6	FRONT BUMPER CLOSING ELEMENT LH <i>new</i>	1	\$ 297.00	✓ x
7	FRONT BUMPER TRIM LH <i>cut</i>	1	\$ 163.00	✓ 130
8	FRONT BUMPER ADAPTOP LH <i>Damaged</i>	1	\$ 38.00	✓ 29.84
9	FRONT BUMPER AIR GUIDE GRILLE LH <i>Missing</i>	1	\$ 188.00	✓ 150
10	FOAM FILLER PIECE <i>new</i>	1	\$ 189.00	x
11	FRONT BUMPER REINFORCEMENT BEAM <i>? new</i>	1	\$ 795.00	x
12	FRONT BUMPER REINFORCEMENT BEAM COVER <i>new</i>	1	\$ 122.00	x
13	FRONT SIGNAL HORN LH <i>new</i>	1	\$ 200.00	✓ x
14	FRONT FENDER LH <i>Distorted</i>	1	\$ 851.00	✓ 680.40
15	FRONT FENDER RIVET <i>new</i>	5	\$ 17.00	✓ 13.20
16	FRONT FENDER ATTACHMENT PART LH <i>new</i>	1	\$ 72.00	+
18	FRONT FENDER BRACE LH <i>? new</i>	1	\$ 96.00	✓ 76.48
19	FRONT FENDER BRACKET LH <i>Bent</i>	1	\$ 39.00	✓ 30.72
20	FRONT FENDER BRACKET LH	1	\$ 28.00	✓ 21.84
SUBTOTAL SPARE PARTS		:	\$ 6,004.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55, UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8328 E

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER SEAL LH <i>new</i>	1	\$ 34.00	? X
22	FRONT WHEEL HOUSING INSULATION LH <i>new</i>	1	\$ 43.00	? X
23	FRONT FENDER CLOSING ELEMENT LH <i>new</i>	1	\$ 33.00	? X
24	FRONT WHEEL HOUSING LINER LH <i>torn</i>	1	\$ 169.00	✓ 134.80
25	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 89.00	? X
26	FRONT PLENUM CHAMBER COVER CENTER <i>new</i>	1	\$ 179.00	X
27	FRONT PLENUM CHAMBER COVER LH <i>new</i>	1	\$ 41.00	+
28	LED HEADLIGHT - LH <i>cracked</i>	1	\$ 5,455.00	✓ 4364
29	LED HEAT SINK - LH <i>new</i>	1	\$ 733.00	+
30	LED HEADLIGHT POWER MODULE	1	\$ 758.00	+
31	LED HEADLIGHT CONTROL UNIT - LH <i>new</i>	1	\$ 557.00	+
32	LIFT CYLINDER - LH <i>new</i>	1	\$ 142.00	+
33	LIFT CYLINDER HOSE - LH <i>new</i>	1	\$ 68.00	+
34	HEADLIGHT WASHER PUMP <i>new</i>	1	\$ 155.00	+
35	WINDSCREEN WASHER PUMP <i>new</i>	1	\$ 125.00	+
36	WINDSCREEN WASHER RESERVOIR <i>del</i>	1	\$ 206.00	✓ 164.40
37	LOCK CARRIER <i>new</i>	1	\$ 727.00	+
38	RADIATOR COOLANT <i>new</i> nec	6	\$ 142.00	113.60
39	RADIATOR AIR GUIDE - LH <i>new</i>	1	\$ 25.00	+
40	RADIATOR AIR GUIDE - UPPER CENTRE <i>new</i>	1	\$ 12.00	+
SUBTOTAL SPARE PARTS		:	\$ 9,693.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8328 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT DOOR LH <i>Dented</i>	1	\$ 3,039.00	✓ 2431.20
42	FRONT DOOR OUTER SEAL LH <i>new</i>	1	\$ 161.00	✓ 128.40
43	BONDING AGENT LH <i>new</i>	1	\$ 49.00	? X
44	CLEANING SOLUTION <i>new</i>	1	\$ 68.00	? X
45	APPLICATOR <i>new</i>	1	\$ 8.00	? X
46	FRONT DOOR ATTACHMENT PARTS LH <i>new</i>	1	\$ 241.00	X
47	FRONT DOOR CATCH LH <i>Dmgd.</i>	1	\$ 105.00	? 84
48	WATER DEFLECTOR LH <i>new</i>	1	\$ 93.00	X
49	WINDOW CHROME SLOT SEAL - LH <i>cut</i>	1	\$ 309.00	✓ 246.80
50	WINDOW CHROME TRIM STRIP - LH <i>new</i>	1	\$ 257.00	X
51	FRONT FENDER LOWER MOUNTING BRACKET LH <i>new</i>	1	\$ 65.00	? X
52	FRONT FENDER CLOSING ELEMENT LOWER CENTER <i>new</i>	1	\$ 74.00	? X
53	FRONT FENDER LOWER MOUNTING RIVET <i>new</i>	1	\$ 12.00	? X
54	FRONT SUSPENSION FRAME <i>cut</i>	1	\$ 1,000.00	? ✓ 800
55	FRONT SUSPENSION FRAME BUSHES - SET <i>nec</i>	1	\$ 112.00	? ✓ 89.20
56	FRONT LOWER ARM LH <i>cut</i>	1	\$ 373.00	✓ 298
57	FRONT STABILIZER BAR <i>bent</i>	1	\$ 395.00	? ✓ 316
58	FRONT WHEEL BEARING HOUSING LH <i>damaged</i>	1	\$ 579.00	? ✓ 462.80
59	FRONT WHEEL HUB LH <i>Dmgd</i>	1	\$ 478.00	✓ 382.40
60	FRONT LOWER ARM BALL JOINT LH <i>new Dmgd</i>	1	\$ 124.00	✓ 98.80
SUBTOTAL SPARE PARTS			\$ 7,542.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8328 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT COUPLING ROD ? bent	1	\$ 99.00	? ✓ 77.76
62	FRONT DRIVE SHAFT LH HEM damaged	1	\$ 2,211.00	X ✓ 1768.80
63	FRONT GAS SHOCK ABSORBER LH Best ? bent	1	\$ 259.00	OK ? ✓ 206.80
64	FRONT TIE ROD LH ? bent	1	\$ 92.00	? ✓ 73.04
65	FRONT TIE ROD END LH bent	1	\$ 122.00	? ✓ 97.20
66	STEERING GEAR ? HEM	1	\$ 4,964.00	? X
67	STEERING GEAR KIT ? HEM	1	\$ 43.00	? X
68	ARCYLIX SEALANT HEM	S/N	\$ 180.00	? X
69	CAVITY WAX HEM	S/N	\$ 140.00	? X
70	STONE CHIP HEM	S/N	\$ 180.00	? X
71	METAL FILLER POWDER HEM	S/N	\$ 280.00	? X
72	FRONT LHS RIM HEM	1	TBC	✓ 1166
73	SUNDRIES HEM		\$ 450.00	? 189.76
TOTAL SPARE PARTS		:	\$ 32,259.00	
TOTAL LABOUR CHARGES		:	\$ 21,564.00	
GRAND TOTAL		:	\$ 53,823.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian G
 SURVEYED DATE : 11/08/21
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : Not Authorised, 08 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate - 2

Veron.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0645/2021/TF
9-Sep-21
CHANG
1 of 1
SLT 8328 E
AUDI A3 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	BRAKE HOSE <i>corn</i>	\$ 82.00	✓ 65.60
2	RATIANER FOR BRAKE HOSE <i>nn</i>	\$ 10.00	✓ X
3	SPEED SENSOR <i>from 2nd</i>	\$ 186.00	✓ 148.40
4	WIRING FOR SPEED SENSOR <i>from 2nd</i>	\$ 221.00	✓ 176.80
5	DOUBLE STUD HAXAGON DRIVE	\$ 24.00	✓ 19.04
6	MULTI-POINT SOCKET HEAD BOLTS <i>9</i>	\$ 74.00	✓ 57.60
GRAND TOTAL PARTS		\$ 597.00	

For Premium Automobiles Pte Ltd

Adrian Ling
Resurveyed
10/09/21
SLS



Authorised Signature

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Veron.

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0645/2021/TF
18-Aug-21
Tony
1 of 1
SLT 8328 E
AUDI A3 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REMOVE AND REINSTALL ENGINE ASSY AND GEAR BOX TO FACILITATE RENEWAL OF GEARBOX ASSY. TO CARRY OUT CALIBRATION ADAPTIVE FOR GEARBOX ASSY. (S/N)	\$ 2,800.00	✓✓
2	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER. (S/N)	\$ 800.00	✓✓
3	TO REPAIR LHS CHASSIS MEMBER AND LHS FRONT WHEEL HOUSING TOP MOUNTING. ✓	\$ 1,400.00	750 ✓
4	TO RESPRAY LHS CHASSIS MEMBER AND LHS FRONT WHEEL HOUSING TOP MOUNTING. ✓	\$ 2,000.00	825 ✓
GRAND TOTAL LABOUR		\$ 7,000.00	

For Premium Automobiles Pte Ltd



Authorised Signature

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

CST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0645/2021/TF
18-Aug-21
Tony
1 of 1
SLT 8328 E
AUDI A3 1.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT ABSORBER TOP MOUNTING - LH <i>damaged</i>	\$ 122.00	97.20
2	FRONT ABSORBER TOP MOUNTING BEARING - LH <i>damaged</i>	\$ 46.00	36.16
3	FRONT ABSORBER DUST COVER - LH <i>nn</i>	\$ 54.00	X
4	FRONT ABSORBER COIL SPRING - LH <i>new</i>	\$ 248.00	X
5	FRONT BRAKE DISC COVER - LH <i>Set</i>	\$ 48.00	37.84
6	FRONT BRAKE CALIPER HOUSING - LH <i>nn</i>	\$ 446.00	X
7	FRONT BRAKE CALIPER MOUNTING - LH <i>nn</i>	\$ 288.00	X
8	FRONT BRAKE PAD <i>nn</i>	\$ 211.00	X
9	FRONT BRAKE DISC <i>cut</i>	\$ 165.00	131.60
10	BOLTS - BRAKE HOUSING <i>new</i>	\$ 30.00	X
11	FRONT BRAKE HOSE RETAINER - LH <i>new</i>	\$ 10.00	X
12	FRONT BRAKE HOSE - LH <i>damaged</i>	\$ 82.00	65.04
13	FRONT BRAKE HOSE BRACKET - LH - LH <i>damaged</i>	\$ 5.00	3.52
14	NOISE INSULATION - ENGINE COVER <i>cut</i>	\$ 290.00	232
15	BOTLS - NOISE INSULATION <i>new</i> <i>nec</i>	\$ 26.00	20.40
16	DRIVE SHAFT - LH <i>Replaced</i>	\$ 2,211.00	X
17	DRIVE SHAFT BOLTS <i>nec</i>	\$ 38.00	X
18	GEARBOX <i>cut</i>	\$ 17,519.00	14,015.20
19	FRONT WHEEL HOUSING LINER - RH <i>cut</i>	\$ 169.00	135.20
20	FRONT LOWER ARM - RH <i>best</i>	\$ 373.00	298
GRAND TOTAL PARTS		\$ 22,381.00	

Rim RH. *cut* ✓

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
Resigned
18/08/21
[Signature]