



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0645/2021/KS  
**DATE** : 11-Aug-21  
**WIP** : 39079

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR KHAW BAN LEONG VICTOR  
**ADDRESS** : 25 HAZEL PARK TERRACE  
#19-03  
SINGAPORE 678948  
**TELEPHONE** : HP +65 82233928  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1700049423-03  
**VEHICLE NO** : **SLT 8328 E**  
**MODEL CODE** : AUDI A3 1.0 TFSI 8V  
**MODEL YEAR** : A3 SEDAN 1.0 TFSI  
**ENGINE NO** : CHZ 512265  
**CHASSIS NO** : WAUZZZ8V5J1012901  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**DATE OF ACCIDENT** : 7-Aug-21  
**PLACE OF LOCATION** : SOUTH BUONA VISTA ROAD



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SLT 8328 E.**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS , OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING, ATD	S/N \$	480.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	<del>350.00</del>	250.
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$	1,400.00	X
4	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	<del>350.00</del>	280
5	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	S/N \$	280.00	X
6	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	S/N \$	2,400.00	✓
<b>SUBTOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 5,260.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SLT 8328 E.**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL DASHBOARD ASSY TO FACILITATE RENEW OF LHS A-PILLAR INNER PLATE	S/N \$ 2,400.00	X.
8	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. TO CUT OUT AND WELD LHS A-PILLAR INNER PLATE. TO REPAIR LHS FRONT FENDER TOP SUPPORT. LHS SILL PANEL. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED.	\$ <del>7,000.00</del>	1500.
9	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS FRONT FENDER TOP SUPPORT, LHS UPPER A-PILLAR, LHS A-PILLAR INNER PLATE, LHS SILL PANEL AND LHS WING MIRROR COVER.	\$ <del>6,000.00</del>	1850 3 x 550 = 1650 Fender top Suppl = 200. <u>1850</u>
10	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	✓
11	TO CARRY OUT PRE/ POST DIAGNOSTIC CHECK.	S/N \$ <del>384.00</del>	192
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 21,564.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SLT 8328 E.**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,987.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 187.00	+
3	FRONT BUMPER GUIDE SECTION LH <i>Damaged</i>	1	\$ 39.00	✓
4	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 160.00	x
5	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE ?	1	\$ 536.00	?
6	FRONT BUMPER CLOSING ELEMENT LH ?	1	\$ 297.00	?
7	FRONT BUMPER TRIM LH <i>OK</i>	1	\$ 163.00	✓
8	FRONT BUMPER ADAPTOP LH <i>Damaged</i>	1	\$ 38.00	✓
9	FRONT BUMPER AIR GUIDE GRILLE LH <i>Missing</i>	1	\$ 188.00	✓
10	FOAM FILLER PIECE <i>new</i>	1	\$ 189.00	+
11	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 795.00	x
12	FRONT BUMPER REINFORCEMENT BEAM COVER <i>new</i>	1	\$ 122.00	x
13	FRONT SIGNAL HORN LH ?	1	\$ 200.00	?
14	FRONT FENDER LH <i>Distorted</i>	1	\$ 851.00	✓
15	FRONT FENDER RIVET <i>new</i>	5	\$ 17.00	✓
16	FRONT FENDER ATTACHMENT PART LH <i>new</i>	1	\$ 72.00	+
18	FRONT FENDER BRACE LH ?	1	\$ 96.00	✓
19	FRONT FENDER BRACKET LH <i>Best</i>	1	\$ 39.00	✓
20	FRONT FENDER BRACKET LH	1	\$ 28.00	✓
<b>SUBTOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 6,004.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8328 E**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER SEAL LH ?	1	\$ 34.00 ?	
22	FRONT WHEEL HOUSING INSULATION LH ?	1	\$ 43.00 ?	
23	FRONT FENDER CLOSING ELEMENT LH ?	1	\$ 33.00 ?	
24	FRONT WHEEL HOUSING LINER LH <i>torn</i>	1	\$ 169.00 ✓	
25	FRONT FENDER ATTACHMENT PARTS ?	1	\$ 89.00 ?	
26	FRONT PLENUM CHAMBER COVER CENTER ?	1	\$ 179.00 +	
27	FRONT PLENUM CHAMBER COVER LH <i>Not m</i>	1	\$ 41.00 +	
28	LED HEADLIGHT - LH <i>cracked.</i>	1	\$ 5,455.00 ✓	
29	LED HEAT SINK - LH <i>new</i>	1	\$ 733.00 +	
30	LED HEADLIGHT POWER MODULE <i>new</i>	1	\$ 758.00 +	
31	LED HEADLIGHT CONTROL UNIT - LH <i>new</i>	1	\$ 557.00 +	
32	LIFT CYLINDER - LH <i>new</i>	1	\$ 142.00 +	
33	LIFT CYLINDER HOSE - LH <i>new</i>	1	\$ 68.00 +	
34	HEADLIGHT WASHER PUMP <i>new</i>	1	\$ 155.00 +	
35	WINDSCREEN WASHER PUMP <i>Not m</i>	1	\$ 125.00 +	
36	WINDSCREEN WASHER RESERVOIR <i>del</i>	1	\$ 206.00 ✓	
37	LOCK CARRIER <i>Not m</i>	1	\$ 727.00 +	
38	RADIATOR COOLANT <i>new</i>	6	\$ 142.00 +	
39	RADIATOR AIR GUIDE - LH <i>new</i>	1	\$ 25.00 +	
40	RADIATOR AIR GUIDE - UPPER CENTRE <i>Not m</i>	1	\$ 12.00 +	
<b>SUBTOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 9,693.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8328 E**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT DOOR LH <i>Dented</i>	1	\$ 3,039.00	✓
42	FRONT DOOR OUTER SEAL LH <i>me</i>	1	\$ 161.00	✓
43	BONDING AGENT LH ?	1	\$ 49.00	?
44	CLEANING SOLUTION ?	1	\$ 68.00	?
45	APPLICATOR ?	1	\$ 8.00	?
46	FRONT DOOR ATTACHMENT PARTS LH <i>new</i>	1	\$ 241.00	X
47	FRONT DOOR CATCH LH ?	1	\$ 105.00	?
48	WATER DEFLECTOR LH <i>new</i>	1	\$ 93.00	X
49	WINDOW CHROME SLOT SEAL - LH <i>at</i>	1	\$ 309.00	✓
50	WINDOW CHROME TRIM STRIP - LH <i>new</i>	1	\$ 257.00	X
51	FRONT FENDER LOWER MOUNTING BRACKET LH ?	1	\$ 65.00	?
52	FRONT FENDER CLOSING ELEMENT LOWER CENTER ?	1	\$ 74.00	?
53	FRONT FENDER LOWER MOUNTING RIVET ?	1	\$ 12.00	?
54	FRONT SUSPENSION FRAME - LH ?	1	\$ 1,000.00	?
55	FRONT SUSPENSION FRAME BUSHES - SET ?	1	\$ 112.00	?
56	FRONT LOWER ARM LH <i>Best</i>	1	\$ 373.00	✓
57	FRONT STABILIZER BAR ?	1	\$ 395.00	?
58	FRONT WHEEL BEARING HOUSING LH ?	1	\$ 579.00	?
59	FRONT WHEEL HUB LH <i>Dangd</i>	1	\$ 478.00	✓
60	FRONT LOWER ARM BALL JOINT LH <i>at Dangd</i>	1	\$ 124.00	✓
<b>SUBTOTAL SPARE PARTS</b>			<b>\$ 7,542.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8328 E**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT COUPLING ROD ?	1	\$ 99.00	?
62	FRONT DRIVE SHAFT LH <i>X-rem</i>	1	\$ 2,211.00	X
63	FRONT GAS SHOCK ABSORBER LH <i>Best ?</i>	1	\$ 259.00	<i>ok ?</i>
64	FRONT TIE ROD LH <i>3/2 ?</i>	1	\$ 92.00	?
65	FRONT TIE ROD END LH	1	\$ 122.00	?
66	STEERING GEAR ?	1	\$ 4,964.00	?
67	STEERING GEAR KIT ?	1	\$ 43.00	?
68	ARCYLIX SEALANT ?	S/N	\$ 180.00	?
69	CAVITY WAX ?	S/N	\$ 140.00	?
70	STONE CHIP ?	S/N	\$ 180.00	?
71	METAL FILLER POWDER ?	S/N	\$ 280.00	?
72	FRONT LHS RIM <i>ht</i>	1	TBC	✓
73	SUNDRIES		\$ 450.00	?
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 32,259.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 21,564.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 53,823.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lj  
SURVEYED DATE : 11/08/21  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : Not Authorised, 08 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT