



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SLT 8328 E.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,987.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 187.00	+
3	FRONT BUMPER GUIDE SECTION LH <i>Damaged</i>	1	\$ 39.00	✓
4	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 160.00	+
5	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE <i>cut</i>	1	\$ 536.00	✓
6	FRONT BUMPER CLOSING ELEMENT LH ?	1	\$ 297.00	?
7	FRONT BUMPER TRIM LH <i>cut</i>	1	\$ 163.00	✓
8	FRONT BUMPER ADAPTOP LH <i>Damaged</i>	1	\$ 38.00	✓
9	FRONT BUMPER AIR GUIDE GRILLE LH <i>Missing</i>	1	\$ 188.00	✓
10	FOAM FILLER PIECE <i>new</i>	1	\$ 189.00	+
11	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 795.00	+
12	FRONT BUMPER REINFORCEMENT BEAM COVER <i>new</i>	1	\$ 122.00	+
13	FRONT SIGNAL HORN LH ?	1	\$ 200.00	?
14	FRONT FENDER LH <i>Distorted</i>	1	\$ 851.00	✓
15	FRONT FENDER RIVET <i>new</i>	5	\$ 17.00	✓
16	FRONT FENDER ATTACHMENT PART LH <i>new</i>	1	\$ 72.00	+
18	FRONT FENDER BRACE LH	1	\$ 96.00	✓
19	FRONT FENDER BRACKET LH <i>Bent</i>	1	\$ 39.00	✓
20	FRONT FENDER BRACKET LH	1	\$ 28.00	✓
SUBTOTAL SPARE PARTS		:	\$ 6,004.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8328 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT DOOR LH <i>Dented</i>	1	\$	3,039.00	✓
42	FRONT DOOR OUTER SEAL LH <i>me</i>	1	\$	161.00	✓
43	BONDING AGENT LH ?	1	\$	49.00	?
44	CLEANING SOLUTION ?	1	\$	68.00	?
45	APPLICATOR ?	1	\$	8.00	?
46	FRONT DOOR ATTACHMENT PARTS LH <i>new</i>	1	\$	241.00	X
47	FRONT DOOR CATCH LH ?	1	\$	105.00	?
48	WATER DEFLECTOR LH <i>new</i>	1	\$	93.00	X
49	WINDOW CHROME SLOT SEAL - LH <i>at</i>	1	\$	309.00	✓
50	WINDOW CHROME TRIM STRIP - LH <i>new</i>	1	\$	257.00	X
51	FRONT FENDER LOWER MOUNTING BRACKET LH ?	1	\$	65.00	?
52	FRONT FENDER CLOSING ELEMENT LOWER CENTER ?	1	\$	74.00	?
53	FRONT FENDER LOWER MOUNTING RIVET ?	1	\$	12.00	?
54	FRONT SUSPENSION FRAME - <i>at</i> <i>rit</i>	1	\$	1,000.00	✓
55	FRONT SUSPENSION FRAME BUSHES - SET <i>new</i>	1	\$	112.00	✓
56	FRONT LOWER ARM LH <i>Best</i>	1	\$	373.00	✓
57	FRONT STABILIZER BAR <i>Best</i>	1	\$	395.00	✓
58	FRONT WHEEL BEARING HOUSING LH <i>Dmgd</i>	1	\$	579.00	✓
59	FRONT WHEEL HUB LH <i>Dmgd</i>	1	\$	478.00	✓
60	FRONT LOWER ARM BALL JOINT LH <i>at Dmgd</i>	1	\$	124.00	✓
SUBTOTAL SPARE PARTS		:	\$	7,542.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 8328 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT COUPLING ROD <i>Best</i>	1	\$ 99.00	✓
62	FRONT DRIVE SHAFT LH <i>Ham David</i>	1	\$ 2,211.00	✓
63	FRONT GAS SHOCK ABSORBER LH <i>Best Best</i>	1	\$ 259.00	✓
64	FRONT TIE ROD LH <i>3 & Best</i>	1	\$ 92.00	✓
65	FRONT TIE ROD END LH	1	\$ 122.00	✓
66	STEERING GEAR	1	\$ 4,964.00	?
67	STEERING GEAR KIT	1	\$ 43.00	?
68	ARCYLIX SEALANT	S/N	\$ 180.00	?
69	CAVITY WAX	S/N	\$ 140.00	?
70	STONE CHIP	S/N	\$ 180.00	?
71	METAL FILLER POWDER	S/N	\$ 280.00	?
72	FRONT LHS RIM <i>ht</i>	1	TBC	✓
73	SUNDRIES		\$ 450.00	
TOTAL SPARE PARTS		:	\$ 32,259.00	
TOTAL LABOUR CHARGES		:	\$ 21,564.00	
GRAND TOTAL		:	\$ 53,823.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Resurveyed.
Adrian Lij
18/08/21