

Car-in 17/8/21. cwp: 39079.

PREMIUM AUTOMOBILES

~~cwp: 3~~

Kiam



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Hui Zhen.

AIG - Admin

5 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 5845 E.

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 1,787.00	✓
2	FRONT BUMPER FIXING PARTS <i>Not m</i>	1	\$ 587.00	X
3	FRONT BUMPER SECURING STRIP <i>blee</i>	2	\$ 72.00	✓
4	FRONT BUMPER GRILLE CENTER <i>new behind</i>	1	\$ 196.00	✓
5	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 210.00	X
6	FRONT BUMPER AIR GUIDE LH <i>new</i>	1	\$ 63.00	X
7	RADIATOR GRILLE <i>new cracked</i>	1	\$ 1,332.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE LH <i>new</i>	1	\$ 135.00	X
9	FOAM FILLER PIECE <i>new</i>	1	\$ 124.00	X
10	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 845.00	+
11	FRONT BUMPER GUIDE SECTION LH <i>Diff</i>	1	\$ 36.00	✓
12	FRONT BUMPER TOP COVER	1	\$ 127.00	+
13	"CAUTION" STICKER	1	\$ 14.00	+
14	A/C STICKER	1	\$ 8.00	+
15	LOCK CARRIER BRACKET <i>new</i>	1	\$ 137.00	+
16	LOCK CARRIER SUPPORT LH / RH <i>new</i>	2	\$ 58.00	+
18	FRONT PARKING AID SESNOR <i>Missing 1 piece</i>	2	TBC	
19	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	1	\$ 14.00	+
20	FRONT BUMPER WIRING SET <i>new</i>	1	\$ 510.00	+
SUB TOTAL SPARE PARTS			\$ 6,255.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 5845 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN LH <i>Not in</i>	1	\$ 12.00	X
22	HORN BRACKET LH <i>Not in</i>	1	\$ 29.00	X
23	FRONT FENDER LH <i>Dented</i>	1	\$ 767.00	✓
24	FRONT FENDER ATTACHMENT LH <i>Not in</i>	1	\$ 202.00	X
25	FRONT FENDER CLOSING ELEMENT LH <i>Pyd</i>	1	\$ 72.00	✓
26	FRONT FENDER BRACKET LH ?	1	\$ 35.00	?
27	FRONT FENDER DEFORMATION ELEMENT ?	1	\$ 49.00	?
28	FRONT FENDER BRACKET LH ?	1	\$ 32.00	?
29	FRONT FENDER BRACE LH <i>Bent</i>	1	\$ 118.00	✓
30	FRONT WHEEL HOUSING LINER LH <i>Dented</i>	1	\$ 240.00	✓
31	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not in</i>	1	\$ 233.00	X
32	FRONT WHEEL SPOILER LH <i>Not in</i>	1	\$ 73.00	X
33	FRONT WHEEL SPOILER TRIM LH <i>New</i>	1	\$ 35.00	X
34	FRONT WHEEL STONE CHIP GUARD LH <i>Not in</i>	1	\$ 51.00	X
35	FRONT FENDER FLEDGE COVER - LONG <i>Cover</i>	1	\$ 31.00	✓
36	FRONT FENDER FLEDGE COVER - SHORT	1	\$ 23.00	✓
37	LED HEADLIGHT - LH <i>Not in</i>	1	\$ 7,693.00	X
38	LIFT CYLINDER - LH ?	1	\$ 210.00	X
39	LIFT CYLINDER HOSE - LH <i>Not in</i>	1	\$ 93.00	X
40	LOCK CARRIER <i>Not in</i>	1	\$ 1,016.00	X
TOTAL SPARE PARTS		:	\$ 17,269.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 5845 E

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LOCK CARRIER LOWER SUPPORT LH <i>new</i>	1	\$ 38.00	X
42	RADIATOR COOLANT	6	\$ 266.00	X
43	RADIATOR AIR GUIDE LH <i>new</i>	1	\$ 28.00	X
44	RADIATOR AIR GUIDE LH	1	\$ 12.00	X
45	RADIATOR AIR GUIDE CENTER <i>new</i>	1	\$ 16.00	X
46	RADIATOR AIR GUIDE LOWER <i>new</i>	1	\$ 22.00	X
47	FRONT LOWER ARM LH ?	1	\$ 539.00	?
48	FRONT SUSPENSION GUIDE LH ?	1	\$ 943.00	?
49	FRONT UPPER ARM LH FRONT ?	1	\$ 512.00	?
50	FRONT UPPER ARM LH REAR ?	1	\$ 512.00	?
51	FRONT WHEEL HOUSING BEARING LH ?	1	\$ 968.00	?
52	FRONT LOWER ARM BALL JOINT LH ?	1	\$ 193.00	?
53	FRONT WHEEL HUB LH ?	1	\$ 479.00	?
54	FRONT WHEEL BEARING LH ?	1	\$ 246.00	?
55	FRONT SUSPENSION FORK LH ?	1	\$ 264.00	?
56	FRONT COUPLING ROD LH ?	1	\$ 167.00	?
57	FRONT GAS SHOCK ABSORBER ?	1	\$ 301.00	?
58	FRONT TIE ROD LH ?	1	\$ 99.00	?
59	FRONT TIE ROD END LH ?	1	\$ 197.00	?
60	FRONT NO PLATE <i>new new</i>	1	\$ 60.00	X
61	FRONT LHS TYRE <i>new</i>	1	TBC	X
62	FRONT LHS RIM <i>new</i>	1	TBC	X
63	SUNDRIES ?	1	\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 29,386.00	
TOTAL LABOUR CHARGES		:	\$ 12,092.00	
GRAND TOTAL		:	\$ 41,478.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Adrian Lj
H.S.
Resoucyed