

OOHRAY RENTAL PTE. LTD.

8 Kaki Bukit Avenue 4, Premier@Kaki Bukit #06-31 Singapore 415875
Tel: (65) 6661 9687 Fax: (65) 6241 6697

Estimate Repair List

11 August 2021

HHTPClaims21-49

India International Insurance Pte Ltd
64 Cecil Street, IOB Building
#04-00 / #05-00
Singapore 049711

Hui Zhen.

Attn: Motor Claims Department

ACCIDENT INVOLVING SLT 1021 K & SLS 9308 L ON 10/08/2021 ALONG SERANGOON ROAD AT ABOUT 1438 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No : SLT 1021 K
Vehicle Make : TOYOTA
Vehicle Model : COROLLA AXIO HYBRID 1.5 CVT
Vehicle Chassis No : NKE1657144644
Policy No : 5109921641-02-000057
Date of Accident : 10/08/2021

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper <i>Rehnd</i>		1,255.75 780
2	2	Rear Bumper Side Retainer (LH/RH) <i>new</i>	\$ 301.20	602.40 +
3	10	Rear Bumper Clips <i>new</i>	\$ 5.00	50.00 30 821
4	1	Rear Boot <i>Dented</i>		2,126.75
5	1	Rear Boot Chrome <i>new</i>		985.50 +
6	1	Rear Boot Emblem <i>new</i>	3185	171.60 75
7	1	Rear Boot Logo (Corolla) <i>new</i>		122.70 58
8	1	Rear Boot Logo (Axio) <i>new</i>	2388.75	136.80 55
9	1	Rear Boot Logo (Hybrid) <i>new</i>		136.80 60
10	1	Rear Tail Lamp (LH) <i>Cracked</i>		1,704.00 458
11	1	Rear End Panel <i>Dented</i>		1,740.75 682
12	1	Rear End Panel Top Garnish <i>Rehnd</i>		691.80 166
				\$ 9,725.75
				Less 25% (1,945.15)
				7,780.60
				7294.31
13	1	Number Plate <i>new</i>	200	35.00 +
14	1	Reverse Sensor <i>Damaged</i>		200.00 +
				\$ 800.00 600
				\$ 8,815.60

To cut & weld rear end panel. To change rear bumper, rear boot. knocking all area affected by accident

OOHRAY RENTAL PTE. LTD.

8 Kaki Bukit Avenue 4, Premier@Kaki Bukit #06-31 Singapore 415875
Tel: (65) 6661 9687 Fax: (65) 6241 6697

ACCIDENT INVOLVING SLT 1021 K & SLS 9308 L ON 10/08/2021 ALONG SERANGOON ROAD AT ABOUT 1438 HOURS

Repair Estimate for vehicle SLT 1021 K- Toyota Axio

Balance B/F \$ 8,815.60

To perform wiring check

1230

\$ 50.00 30

To spray rear end panel, rear bumper, rear boot and all affected area

\$ 800.00 602

\$ ~~0,005.60~~ 9179.31

7% GST \$ 676.59

Total \$ 10,342.19

Jul

Authorised by Claims Dept

Adrian Lj
P/P (Lump sum) ??

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary: 218.25

total: 4037.

2/s: 3.2K.

OOHRAY RENTAL PTE. LTD.

8 Kaki Bukit Avenue 4, Premier@Kaki Bukit #06-31 Singapore 415875
Tel: (65) 6661 9687 Fax: (65) 6241 6697

Supplementary List

7 September 2021

HHTPClaims21-49

India International Insurance Pte Ltd
64 Cecil Street, IOB Building
#04-00 / #05-00
Singapore 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING SLT 1021 K & SLS 9308 L ON 10/08/2021 ALONG SERANGOON ROAD AT ABOUT 1438 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No : SLT 1021 K
Vehicle Make : TOYOTA
Vehicle Model : COROLLA AXIO HYBRID 1.5 CVT
Vehicle Chassis No : NKE1657144644
Policy No : 5109921641-02-000057
Date of Accident : 10/08/2021

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Boot Weatherstrip <i>ut</i>	\$	321.70 <i>187</i>
2	1	Rear Boot Lock <i>Dang d</i>	\$	268.50 <i>104</i>
			25%	\$ 590.20
			Less 20%	\$ (118.04)
				\$ 472.16 <i>442.65</i>
			7% GST	\$ 33.05
			Total	\$ 505.21

Authorised by Claims Dept

550 291
Supplementary: 218.25

total \$9621.96