



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CLYDE CLIFFORD GREGORY Reg No/Reg Date SMM5084C / 01/07/201 Date In/Mileage / 30300 Chassis No MMBSTA13AKH001827 Engine No 3A92UHS9513 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	12/08/2021/ 12:46	BLE	261 / Edwin Caina	14144			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 1 50 2 1 1					4.5 X 450 + 80			2250.00
RENEW FR BUMPER & BODY KIT , FR SUPPORT , BONNET & RHF FENDER								2105
REPAIR LHF FENDER								2100.00
E PNT98000 1 1 1 1					5 X 350			1750
RESPRAY FR BUMPER , FR BUMPER BODY KIT , FR SUPPORT , BONNET ,								
LHF FENDER & RHF FENDER								100.00 X
E PNT88000								80.00 X
REMOVE & REFIT AC COND & RADIATOR (photo)								30.00
M SUNDRY								120.00
TOP UP AC GAS								50.00
A 54900099								80.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								60.00
A 10028901								20.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								40
SUPPLY FR NUMBER PLATE WITH CASING BT								80.00
M SUNDRY								40
APPLY ANTI CORROSION ON AFFECTED AREAS								60.00
M SUNDRY								
SUPPLY BODY PNL SEALANT								20.00
M SUNDRY								
Sundries					1.00	706.00	23.00	543.62
M FACE,FR BUMPER / DO					1.00	12.00	23.00	9.24
M COVER,FR BUMPER					1.00	62.00	23.00	47.74
M COVER,HEADLAMP SUPT PANEL					5.00	4.00	23.00	15.40
M CLIP,FR BUMPER					1.00	13.00	23.00	10.01
M BRACKET,FR BUMPER,LH					1.00	13.00	23.00	10.01
M BRACKET,FR BUMPER,RH					1.00	165.00	23.00	127.05
M GRILLE,FR UNDER					1.00	127.00	23.00	97.79
M GARNISH,FR BUMPER,RH					1.00	70.00	23.00	53.90
M MARK,THREE-DIA					1.00	557.00	23.00	428.89
M GRILLE,RADIATOR					1.00	737.00	23.00	567.49
M HOOD								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CLYDE CLIFFORD GREGORY Reg No/Reg Date SMM5084C / 01/07/201 Date In/Mileage / 30300 Chassis No MMBSTA13AKH001827 Engine No 3A92UHS9513 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	12/08/2021/ 12:46	BLE	261 / Edwin Caina	14144
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M CLIP, HOOD INSULATOR	✓ PC	8.00	3.00	23.00	18.48
M HINGE, HOOD, LH	✓ X n n	1.00	56.00	23.00	43.12
M HINGE, HOOD, RH	✓ X n n	1.00	56.00	23.00	43.12
M LATCH, HOOD	✓ X n n	1.00	69.00	23.00	53.13
M FENDER, FR RH	✓ BR	1.00	500.00	23.00	385.00
M SHIELD, FR WHEELHOUSE, RH	✓ X n n	1.00	98.00	23.00	75.46
M CLIP, INNERSHIELD	✓ X n n (photo) X n n	6.00	4.00	23.00	18.48
M PANEL ASSY, FR END	✓ BR	1.00	1055.00	23.00	812.35
M PANEL, HEADLAMP SUPPORT, UPR	✓ X n n	1.00	66.00	23.00	50.82
M HEADLAMP ASSY, LH	✓ X n n	1.00	663.00	23.00	510.51
M HEADLAMP ASSY, RH	✓ BR	1.00	663.00	23.00	510.51
M CONDENSER ASSY, A/C REFRIGE	✓ X n n	1.00	762.00	23.00	586.74
M PANEL, AIR GUIDE, LH	✓ X n n	1.00	11.00	23.00	8.47
M PANEL, AIR GUIDE, RH	✓ X n n	1.00	11.00	23.00	8.47
M PANEL, AIR GUIDE	✓ BR	1.00	112.00	23.00	86.24
M RADIATOR ASSY	✓ X n n	1.00	972.00	23.00	748.44
M FAN, COOLING	✓ X n n	1.00	77.00	23.00	59.29
M SHROUD, COOLING FAN	✓ X n n	1.00	131.00	23.00	100.87
M MOTOR, COOLING FAN	✓ X n n	1.00	484.00	23.00	372.68
M EMBLEM ECO	✓ PC	1.00	17.00	00.00	17.00
M LLC 4L	✓ X n n	1.00	26.00	23.00	20.02
M UNPAINTED BODYKITS	✓ BR	1.00	1643.00	20.00	1314.40

SURVEYOR NAME:

Steve CLKK 12/8/21, 4.00p

SURVEYOR SIGNATURE:

OO-MAL

DATE:

EXPERT-?

REMARKS:

PIP, My Bel Sy

7 days

Confirm & accepted by

Nett 12,644.74
7% GST on 12644.74 885.13

Total Payable

13,529.87

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a payment for this may be made in cash, credit card or