



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CLYDE CLIFFORD GREGORY Reg No/Reg Date SMM5084C / 01/07/201 Date In/Mileage / 30300 Chassis No MMBSTA13AKH001827 Engine No 3A92UHS9513 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	12/08/2021/ 12:46	BLE	261 / Edwin Caina	14144			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000	1	50	2	1	1			2250.00
RENEW FR BUMPER & BODY KIT , FR SUPPORT , BONNET & RHF FENDER					4-5 X 450	+ 80		2195
REPAIR LHF FENDER								
E PNT98000	1		1	1	1			2100.00
RESPRAY FR BUMPER , FR BUMPER BODY KIT , FR SUPPORT , BONNET ,					5 X 350			1750
LHF FENDER & RHF FENDER								
E PNT88000	1							100.00
REMOVE & REFIT AC COND & RADIATOR (photo)								
M SUNDRY								80.00
TOP UP AC GAS								
A 54900099								30.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								50.00
SUPPLY FR NUMBER PLATE WITH CASING BT								
M SUNDRY								40 80.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								40 60.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								20.00
Sundries								
M FACE,FR BUMPER	✓	DD			1.00	706.00	23.00	543.62
M COVER,FR BUMPER	✓				1.00	12.00	23.00	9.24
M COVER,HEADLAMP SUPT PANEL	✓				1.00	62.00	23.00	47.74
M CLIP,FR BUMPER	✓	MC			5.00	4.00	23.00	15.40
M BRACKET,FR BUMPER,LH	✓				1.00	13.00	23.00	10.01
M BRACKET,FR BUMPER,RH	✓				1.00	13.00	23.00	10.01
M GRILLE,FR UNDER	✓	BR			1.00	165.00	23.00	127.05
M GARNISH,FR BUMPER,RH	✓				1.00	127.00	23.00	97.79
M MARK,THREE-DIA	✓	MC			1.00	70.00	23.00	53.90
M GRILLE,RADIATOR	✓	BR			1.00	557.00	23.00	428.89
M HOOD	✓	ON			1.00	737.00	23.00	567.49

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CLYDE CLIFFORD GREGORY Reg No/Reg Date SMM5084C / 01/07/201 Date In/Mileage / 30300 Chassis No MMBSTA13AKH001827 Engine No 3A92UHS9513 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	12/08/2021/ 12:46	BLE	261 / Edwin Caina	14144
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M CLIP, HOOD INSULATOR	REC	8.00	3.00	23.00	18.48
M HINGE, HOOD, LH		1.00	56.00	23.00	43.12
M HINGE, HOOD, RH		1.00	56.00	23.00	43.12
M LATCH, HOOD		1.00	69.00	23.00	53.13
M FENDER, FR RH	BR	1.00	500.00	23.00	385.00
M SHIELD, FR WHEELHOUSE, RH	X	1.00	98.00	23.00	75.46
M CLIP, INNERSHIELD	X	6.00	4.00	23.00	18.48
M PANEL ASSY, FR END	BR (photo)	1.00	1055.00	23.00	812.35
M PANEL, HEADLAMP SUPPORT, UPR		1.00	66.00	23.00	50.82
M HEADLAMP ASSY, LH		1.00	663.00	23.00	510.51
M HEADLAMP ASSY, RH	BR	1.00	663.00	23.00	510.51
M CONDENSER ASSY, A/C REFRIGE		1.00	762.00	23.00	586.74
M PANEL, AIR GUIDE, LH		1.00	11.00	23.00	8.47
M PANEL, AIR GUIDE, RH		1.00	11.00	23.00	8.47
M PANEL, AIR GUIDE		1.00	112.00	23.00	86.24
M RADIATOR ASSY		1.00	972.00	23.00	748.44
M FAN, COOLING		1.00	77.00	23.00	59.29
M SHROUD, COOLING FAN		1.00	131.00	23.00	100.87
M MOTOR, COOLING FAN		1.00	484.00	23.00	372.68
M EMBLEM ECO	REC	1.00	17.00	00.00	17.00
M LLC 4L		1.00	26.00	23.00	20.02
M UNPAINTED BODYKITS	BR	1.00	1643.00	20.00	1314.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SURVEYOR NAME: Steve (LKK) 12/8/21, 4:00pm
 SURVEYOR SIGNATURE: OO-MAL
 DATE: EXPERT-?
 REMARKS: P/P, My Bel'sy
7 days

Confirm & accepted by

7% GST on	Nett	12,644.74
		885.13
	Total Payable	13,529.87

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.