



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

TP Budget Direct Denise.

Page No. 1

Vehicle No. SBE8123B MERCEDES E250

WDD2120362 A895153.

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR BOOTLID LAMP LH <i>at</i>		489.50	✓
1	REAR TAILLAMP LH <i>crushed</i>		710.00	✓
1	REAR BUMPER <i>Distorted.</i>		1915.00	✓ 1791
2	REAR BUMPER FRAME LH <i>delnd</i>		75.90	✓
1	REAR BUMPER CHROME MOULDING LH <i>new at</i>		145.00	✓
1	REAR BUMPER REINFORCEMENT <i>Best.</i>		774.50	✓
1	REAR BUMPER LOWER TRIM <i>at</i>		541.00	✓ 369
2	REAR BUMPER SIDE RETAINER LH & RH @\$108.40 <i>LH New</i>		216.80	✓ 108.40
2	REAR BUMPER SIDE BRACKET LH & RH @\$115.00 <i>New</i>		230.00	✓
1	REAR BUMPER SPONGE <i>New</i>		219.00	✓
1	REAR BUMPER INNER PLASTIC <i>New</i>		277.00	✓
1	REAR END PANEL <i>Regis</i>		1417.30	✓
1	REAR END PANEL TOP GARNISH <i>New</i>		155.40	✓
1	REAR EXHAUST SILENCER CHROME LH <i>New</i>		202.00	✓
			7368.40	
		less	10% 736.84	10%
			6631.56	
SPECIAL ITEMS				
2 PCS	REVERSE SENSOR <i>1 piece damaged</i>		600.00	✓ 250.
2	REVERSE SENSOR SEAL <i>2 New</i>		140.00	✓
2	REVERSE SENSOR O RING		160.00	✓
1 SET	REAR BUMPER CLIPS <i>New</i>		100.00	✓ 30.
	Total Parts		7631.56	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SBE8123B MERCEDES E250

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT (\$\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	800
3	To remove and refix wiring at damaged areas	180.00	30
4	To perform anti rust treatment on affected areas	150.00	60
5	To remove & replace reverse sensor	150.00	50
6	To conduct water seepage test	120.00	+
7	To transfer rear boot mechanism	120.00	+
8	To remove and replace rear taillamp beam	80.00	+
9	To clear fault code with diagnostic computer and reset to Mercedes specification .	250.00	+
	Labour Total :	4050.00	
	TOTAL (PARTS & LABOUR):	11681.56	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Ly
w/s 13/08/21
05 Days.
Total: 5991.50
w/s: A.81C
4.8k