



Final Report

Estimate No. : **b1 59181**
Date Estimated : **11/08/2021**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
LEOW KWOK LEONG JIMMY
BLK 416 CANBERRA ROAD
#12-379

SINGAPORE 750416

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMR6926R	WBA2X920407F371	17/01/2020	216i Active Tourer	19942

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
Replace rear bumper, rear boot lid & remove attachment parts.	1,700.00	0.00	1,700.00
Painting rear boot lid, rear tail panel and rear bumper	1,826.00	0.00	1,826.00
To remove and install rear windscreen glass.	574.00	0.00	574.00
To conduct water leak tests.	75.00	0.00	75.00
To supply and install rear windscreen solar film.			
To remove and install boot compartment carpet and garnish to facilitate repair.	257.00	0.00	257.00
To check electrical wiring system and lighting at the rear section for proper function.	168.00	0.00	168.00
To carry out body cavity preservation. (Per panel).	112.00	0.00	112.00
Sundries.	150.00	0.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6	2.70	3.00	0.00	8.10
TRUNK LID	1,216.40	1.00	0.00	1,216.40
# EXPANDING NUT	1.00	2.00	0.00	2.00
REAR BUMPER TRIM STRIP (BLACK)	88.20	1.00	0.00	88.20
REAR BUMPER PANEL PRIMED (LINES PDC	1,050.65	1.00	0.00	1,050.65
LETTERING 216 I	64.75	1.00	0.00	64.75
GROMMET	0.80	2.00	0.00	1.60
PLAQUE 74MM	71.95	1.00	0.00	71.95
BUMP STOP	3.20	10.00	0.00	32.00
(DG) CLEANER R1 (100ML)	26.15	1.00	0.00	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	0.00	263.10
(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	27.85	1.00	0.00	27.85

SUPPLEMENTARY ITEMS

Total Labour : 4,862.00



Final Report

Total Parts :	2,852.75
Total Labour & Parts :	7,714.75
Deduction for Excess :	
Total Repair Costs less Excess:	7,714.75
GST @7%:	540.03
Grand Total :	<u>8,254.78</u>

LOSS OF USE=\$60 X7 DAYS
GIA SEARCH FEE=\$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W/ GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 59181**
Date Estimated : **11/08/2021**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
LEOW KWOK LEONG JIMMY
BLK 416 CANBERRA ROAD
#12-379

SINGAPORE 750416

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMR6926R	WBA2X920407F371	17/01/2020	216i Active Tourer	19942

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# BLIND RIVET NUT M6	2.70	3.00	0.00	8.10	nec
# EXPANDING NUT	1.00	2.00	0.00	2.00	nec

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	10.10
Total Labour & Parts :	10.10