

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 416180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796661 (After Sales)
64796624 (Motors)



17/8/2021
Sunny day
9am - 3pm

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 59181
Date Estimated : 11/08/2021
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

LEOW KWOK LEONG JIMMY
BLK 416 CANBERRA ROAD
#12-379

SINGAPORE 750416

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SMR6926R

WBA2X920407F37158

17/01/2020

216i Active Tourer

19942

DESCRIPTION

VALUE

Replace rear bumper, rear boot lid include remove attachment etc

1720 2,125.00

Painting rear boot lid, rear tail panel and rear bumper

1826 2,666.00

To replace rear windscreen glass.

574.00

To conduct water leak tests.

75.00

To supply and install rear windscreen solar film.

50412 531.00

To remove and install boot compartment carpet and garnish to facilitate repair.

257 271.00

To check electrical wiring system and lighting at the rear section for proper function.

168 177.00

To carry out body cavity preservation.
(Per panel).

112 118.00

Sundries.

150.00

Total Labour 1:

6,687.00

DESCRIPTION

QTY

PRIC

VALUE

TRUNK LID

1

1,216.40

1,216.40

RR BUMPER RH SIDE GUIDE

1

161.15

161.15

REAR BUMPER CARRIER

1

483.40

483.40

SUPPORT

1

45.75

45.75

RR BUMPER RH INNER SIDE GUIDE

1

161.15

161.15

LH PROTECTION FOIL

1

5.65

5.65

RH PROTECTION FOIL

1

5.65

5.65

REAR BUMPER TRIM STRIP (BLACK)

1

88.20

88.20

REAR BUMPER PANEL PRIMED (LINES PDC

1

1,050.65

1,050.65

SET MOUNTS PDC SENSOR REAR

1

61.00

61.00

LETTERING 216 I

1

64.75

64.75

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64726601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 59181
Date Estimated : 11/08/2021
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMR6926R	WBA2X920407F37158	17/01/2020	2161 Active Tourer	19942

DESCRIPTION	QTY	PRIC	VALUE
GROMMET / <i>PRC</i>	2	0.80	1.60
PLAQUE 74MM / <i>PRC</i>	1	71.95	71.95
STRIKER BOOT LID / <i>X nn</i>	1	60.10	60.10
LOCK TRUNK LID / <i>X nn</i>	1	195.75	195.75
BUMP STOP / <i>PRC</i>	10	3.20	32.00
REAR FLAP TOWING EYE PRIMED / <i>CRU</i>	1	43.25	43.25
REAR WINDOW ESG / <i>X nn</i>	1	657.60	657.60
TRUNK LID SEALING / <i>X nn</i>	1	97.85	97.85
REAR RH LIGHT IN THE SIDE PANEL / <i>X nn</i>	1	376.30	376.30
REAR RH LIGHT IN TRUNK LID / <i>X nn</i>	1	263.40	263.40
RH GUTTER STRIP / <i>X nn</i>	1	53.30	53.30
DECOUPING RING PDC TORQUE CONVERTER / <i>PRC</i>	4	5.15	20.60
ULTRASONIC SENSOR IMPERIALBLAU(WA89) / <i>X nn</i>	4	371.20	1,484.80
SET ADHESIVE PADS FOR ACE 2.0 / <i>PRC</i>	1	43.65	43.65
(DG) CLEANER R1 (100ML) / <i>PRC</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) / <i>PRC</i>	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) / <i>PRC</i>	1	27.85	27.85

Total Parts : 7,063.00

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time _____ Excess S\$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

Working Days Recommend

LKK Auto Consultants Inc. hereby

the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged parts, if any, in survey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurace Company

Acknowledged by Repairer

Signature: _____

Steve (LKK) WIL PL

17/8/21, 2.00pm

P/P

My BL Sy

8 5dys



Labour 1	:	6,687.00
Parts	:	7,063.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	962.50
Grand Total	:	14,712.50

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **